



report date: 2024-03-29

General information

Make	VAUXHALL
Model	ZAFIRA SRI NAV
Colour	White
Year of manufacture	2018
Top speed	124 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	200 Nm at 1.850 rpm
Engine capacity	1.364 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.2 mpg
Consumption extra urban	49.6 mpg
Consumption combined	41.5 mpg
CO2 emission	156 g/km
CO2 label	G








Internet history

Entry 1

Date	2022-01-14
Pictures	24
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2025-02-22
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	19
Total items failed	1

## MOT #5 2024-02-21 14:40

MOT test number 550206203755

Result ✓ Passed

Next expiry date 2025-02-22

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))

## MOT #4 2024-02-08 14:16

MOT test number 455699120582

Result ✗ Failed**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))**Fail** Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #3** 2023-02-20 14:10**MOT test number** 770227905766**Result** ✓ Passed

- Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement wishbone rear bush (5.3.4 (a) (i))
- Advice** Offside Rear Nail in tyre
- Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (ii))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Coolant low
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #2** 2022-02-03 10:25**MOT test number** 421484687639**Result** ✓ Passed**MOT #1** 2021-02-23 12:04**MOT test number** 745093978659**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 October 2024

✓  
**MOT**

**Expires:**  
22 February 2025

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	154
<b>MOT expiry date</b>	22 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	I
<b>First licence fee (12 months)</b>	£ 645,00,-
<b>Standard rate (12 months)</b>	£ 180,00,-
<b>Standard rate (6 months)</b>	£ 99,00,-
<b>Premium rate (12 months)</b>	£ 570,00,-
<b>Premium rate (6 months)</b>	£ 313,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Number of owners	1
Current owner since	2019-06-29
Previous owner since	2019-06-29
Number of owners	1
Current owner since	2019-06-29
Previous owner since	2019-06-29

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 <b>SG18NEN</b>
Plate since	2019-06-29
Current registration	 <b>SG18NEN</b>
Plate since	2019-06-29

More info >





Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2018-03-29
Last registration	2024-02-21
Complete history	<a href="#">See info</a>



Registration #1	2018-03-29	16 mi
Registration #2	2021-02-23	50.691 mi
Registration #3	2022-02-03	66.305 mi
Registration #4		
Registration #5		
Registration #6		
Registration #7		

More info >



Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1884 mm
Height	1685 mm
Length	4666 mm
Wheel base	2760 mm
Kerb weight	1538 kg
Max. allowed weight	2310 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	B14NET -19SU9449LUJ