



**AE08TWB**

report date: 2024-03-29

General information

Make	FIAT
Model	PUNTO ACTIVE
Colour	Blue
Year of manufacture	2008
Top speed	103 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.000 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-05-28
Pictures	3
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-12-11
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	33
Total items failed	12

MOT #17	2023-12-12 13:16
MOT test number	125913227448
Result	✓ Passed
Next expiry date	2024-12-11
Advice	Nearside Front Tyre worn close to legal limit/worn on edge Worn on edges (5.2.3 (e))
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #16	2023-12-12 13:16
MOT test number	992659660235
Result	✗ Failed
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Pass with rectification	Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge Worn on edges (5.2.3 (e))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #15** 2023-01-05 15:55**MOT test number** 415964684827**Result** ✓ Passed**MOT #14** 2023-01-05 11:23**MOT test number** 543979456394**Result** ✗ Failed**Minor** Offside Front Lower Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure Inner wall marked yellow (5.2.3 (d) (ii))**MOT #13** 2022-01-17 14:03**MOT test number** 834290690757**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #12** 2022-01-07 12:16**MOT test number** 791950471753**Result** ✗ Failed**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Indicator switch inoperative Does not operate either side when put on (4.4.2 (a) (ii))**Fail** Front Exhaust has a major leak of exhaust gases Flexi pipe (6.1.2 (a))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Offside Front All direction indicators incorrect colour (4.4.3 (a))

**MOT #11** 2021-01-04 11:14**MOT test number** 516527209915**Result** ✓ Passed

- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing sidewall (5.2.3 (d) (ii))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Front exhaust flex weak
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #10** 2019-07-16 11:07**MOT test number** 731406169454**Result** ✓ Passed

- Minor** Nearside Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing side wall (5.2.3 (d) (ii))

**MOT #9** 2018-06-05 14:01**MOT test number** 723509169440**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge on edges (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge on edges (5.2.3 (e))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #8**

2017-06-20 08:02

**MOT test number**

892660004634

**Result**

✓ Passed

**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside and nearside plastic sill covers fitted**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #7**

2017-06-13 10:50

**MOT test number**

733267457198

**Result**

✗ Failed

**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside and nearside plastic sill covers fitted**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear passenger door cannot be opened from outside the vehicle (6.2.B.1c)**MOT #6**

2016-06-14 09:57

**MOT test number**

690412922191

**Result**

✓ Passed

**Advice** Rear exhaust box corroding on outer skin**MOT #5**

2015-05-12 11:02

**MOT test number**

929822335146

**Result**

✓ Passed



MOT #4	2014-05-13 08:38
MOT test number	845333234168
Result	✓ Passed
MOT #3	2013-05-30 13:29
MOT test number	747950353160
Result	✓ Passed
MOT #2	2013-05-28 12:29
MOT test number	345088743130
Result	✗ Failed
<div><div>Fail</div> Hazard warning switch faulty (1.4.B.1d)</div>	
MOT #1	2012-01-14 10:35
MOT test number	465094812032
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 June 2024

✓  
**MOT**  
  
Expires:  
11 December 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	11 December 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-





Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-06-30
Last registration	2023-12-12
Complete history	<a href="#">See info</a>



Registration #1	2008-06-30	22 mi
Registration #2	2012-01-14	38.650 mi
Registration #3	2013-05-28	39.382 mi
Registration #4	2013-05-30	39.382 mi
Registration #5	2014-05-13	41.554 mi
Registration #6	2015-05-12	44.070 mi
Registration #7	2016-06-14	47.208 mi
Registration #8	2017-06-13	50.071 mi
Registration #9	2017-06-20	50.133 mi
Registration #10	2018-06-05	52.821 mi
Registration #11	2019-06-05	55.000 mi
Registration #12	2020-06-05	55.000 mi
Registration #13	2021-06-05	55.000 mi
Registration #14	2022-06-05	55.000 mi
Registration #15	2023-06-05	55.000 mi
Registration #16	2024-06-05	55.000 mi
Registration #17	2025-06-05	55.000 mi
Registration #18	2026-06-05	55.000 mi
Registration #19	2027-06-05	55.000 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1025 kg
Max. allowed weight	1585 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	4708035