





report date: 2024-03-29

### General information

Make	AUDI
Model	A6 TDI SE TDV
Colour	Grey
Year of manufacture	2008
Top speed	140 mph
0 - 60 mph	8.3 seconds
Gearbox	1 speed CVT

### Engine & fuel consumption

Power	180 BHP
Max. torque	379 Nm at 1.400 rpm
Engine capacity	2.698 cc
Cylinders	6
Fuel type	Diesel
Consumption city	27.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	37.7 mpg
CO2 emission	192 g/km
CO2 label	J



CarCheck.co.uk page 1/11



**EX08FNG** report date: 2024-03-29

MOT history

MOT expiry date	2022-01-04
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	6
Total items failed	7

MOT #13	2020-12-28 14:14
MOT test number	441866357752
Result	✓ Passed
Next expiry date	2022-01-04
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	)

MOT #12	2019-12-30 13:34
MOT test number	372850026043
Result	✓ Passed

MOT #11	2019-01-04 13:46
MOT test number	321460219499
Result	✓ Passed
	. 43333

CarCheck.co.uk page 2/11



report date: 2024-03-29

**MOT #10** 2019-01-04 10:33

**MOT test number** 794013172152

**Result** X Failed

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**Fail** Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure inner wall (5.2.3 (d) (ii))

**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords inner wall (5.2.3 (d) (i))

Fail Offside Front Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))

**Fail** Offside Front Tyre has a bulge, caused by separation or partial failure of its structure inner wall (5.2.3 (d) (ii))

**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords inner wall (5.2.3 (d) (i))

MOT #9 2018-01-04 08:50

**MOT test number** 135365941568

Result 

Passed

MOT #8 2017-01-04 10:11

**MOT test number** 238969268843

**Result** 
✓ Passed

MOT #7 2017-01-03 15:32

**MOT test number** 672332530209

**Result** X Failed

**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)

MOT #6 2016-01-04 14:50

**MOT test number** 426214660814

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #5	2015-01-05 09:54
MOT test number	196345205418
Result	✓ Passed
MOT #4	2014-09-02 15:31
MOT test number	665425444231
Result	✓ Passed
MOT #3	2013-09-09 12:09
MOT test number	465062653221
Result	✓ Passed
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #2		2012-09-24 08:55
MOT test	number	689028162284
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #1	2011-03-10 14:01
MOT test number	608349061030
Result	✓ Passed

CarCheck.co.uk page 4/11



report date: 2024-03-29

### Tax & MOT check

Tax expired: 31 March 2021



X MOT

Expired: 4 January 2022

Tax status	Expired at 31 March 2021
Days left	1126 days too late
MOT expiry date	4 January 2022
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

### Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

### Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

O١			- La 2	 
- ( ) (	Λ/n	ıer	n	

For how long did the current and previous owner(s) have this AUDI? How many owners d Check it in the premium report and see all owner registrations. Download the full report	
**************************************	
***************************************	
	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	
Current registration	NK SIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

### Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

# Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2008-03-01
Last registration	2020-12-28
Complete history	See info



Registration #1	2008-03-01	23 mi
Registration #2	2011-03-10	69.858 mi
Registration #3	2012-09-24	90.970 mi
Registration #4	2013-09-09	103.480 mi
Registration #5	2014-09-02	119.241 mi
Registration #6	2015-01-05	129.987 mi
Registration #7	2016-01-04	156.296 mi
Registration #8		11.777 es
Registration #9		9.70 es
Registration #10		11.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es

mn.n.n

More info >

77.777 au

CarCheck.co.uk page 10/11



report date: 2024-03-29

# Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1855 mm
Height	1459 mm
Length	4916 mm
Wheel base	2843 mm
Kerb weight	1655 kg
Max. allowed weight	2235 kg

# Additional information

Fuel tank capacity	70 I	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5	page 11/11

Number of axles 2

Engine number BPP 123801