





report date: 2024-03-28

General information

Make	MERCEDES
Model	S-Class S320 CDI
Colour	Silver
Year of manufacture	2007
Top speed	149 mph
0 - 60 mph	7.5 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	231 BHP
Max. torque	540 Nm at 1.600 rpm
Engine capacity	2.987 cc
Cylinders	6
Fuel type	Diesel
Consumption city	24.4 mpg
Consumption extra urban	44.1 mpg
Consumption combined	34.0 mpg
CO2 emission	220 g/km
CO2 label	K



CarCheck.co.uk page 1/14



report date: 2024-03-28

Internet history

Entry 1

Date	2021-02-02	
Pictures	1	
Listing price	View report	



source: autoonline.co.uk

CarCheck.co.uk page 2/14



PK07XKP report date: 2024-03-28

MOT history

MOT expiry date	2025-04-02
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	21
Total items failed	11

MOT #19		2024-03-14 11:45
MOT test	number	568644198788
Result		✓ Passed
Next expi	ry date	2025-04-02
Advice	Rear Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))	
Advice	Offside Front Play in steering rack inner joint(s)	
Advice	Oil leak, but not excessive on undertray (8.4.1 (a) (i))	
Advice	Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))	
Advice	Offside Front Upper Suspension arm ball joint has slight play (5.3.4 (a) (i))	
Advice	Exhaust emits black smoke during acceleration (8.2.1.2 (g))	

MOT #18	2023-04-03 14:45
MOT test number	310715998304
Result	✓ Passed
Advice Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))	

MOT #17	2022-03-26 14:24
MOT test number	982900145592
Result	√ Passed

CarCheck.co.uk page 3/14



Result

PK07XKP

report date: 2024-03-28

× Failed

MOT #16 2022-03-26 11:25

MOT test number 979979287018

Result X Failed

Fail Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

MOT #15 2021-08-17 13:25

MOT test number 224287558580

Fail Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Fail Offside Windscreen washer not working (3.5 (a))

Fail Offside Windscreen wiper not working (3.4 (a))

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Fail Nearside Windscreen washer not working (3.5 (a))

Fail Nearside Windscreen wiper not working (3.4 (a))

Advice Offside Front Tyre worn close to legal limit/worn on edge on edges (5.2.3 (e))

MOT #14 2018-09-20 15:13

MOT test number 917582448912

Result

Passed

MOT #13 2018-09-10 14:34

MOT test number 268017173982

Result ★ Failed

Fail Hazard warning switch inoperative (4.4.2 (a) (ii))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

CarCheck.co.uk page 4/14



report date: 2024-03-28

MOT #12 2018-01-09 10:10

MOT test number 702908045702

Result ✓ Passed

Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #11 2018-01-09 10:10

MOT test number 551123766703

Result X Failed

Pass with rectification Windscreen washer provides insufficient washer liquid (8.2.3)

Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Pass with rectification Offside Headlamp not working on dipped beam (1.7.5a)

Advice Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #10 2017-04-27 15:31

MOT test number 984226879175

Result ✓ Passed

MOT #9 2016-05-03 08:14

MOT test number 894791752363

Result ✓ Passed

MOT #8 2016-05-03 08:14

MOT test number 671639735946

Result X Failed

Pass with rectification Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

CarCheck.co.uk page 5/14



report date: 2024-03-28

MOT #7 2015-05-27 12:43

MOT test number 886957945137

MOT #6 2014-05-06 11:29

MOT test number 385026024138

Result ✓ Passed

Notice Slight play o/s front lower ball joint

MOT #5 2013-04-23 16:53

MOT test number 576743613130

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #4 2012-10-04 14:18

MOT test number 969888872298

Notice Front brake discs worn and rusty.

Notice Rear brake discs rusty.

MOT #3 2012-10-03 16:08

MOT test number 376037172457

Result X Failed

Notice Front brake discs worn and rusty.

Notice Rear brake discs rusty.

Fail Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)

CarCheck.co.uk page 6/14



report date: 2024-03-28

 MOT #2
 2011-04-05 16:45

 MOT test number
 567235391078

 Result
 ✓ Passed

MOT #1 2010-03-29 18:02
MOT test number 142938580479
Result ✓ Passed

CarCheck.co.uk page 7/14



PK07XKP report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 January
Days left	246
MOT expiry date	2 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 8/14



report date: 2024-03-28

Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Tyne	

Damage 2	
Date	
Category	
Туре	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



PK07XKP report date: 2024-03-28

Owner history	
For how long did the current and previous owner(s) have this MERCEDES? How many own MERCEDES have? Check it in the premium report and see all owner registrations. Downlo	

	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	NK NAME OF THE PROPERTY OF THE
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 11/14



report date: 2024-03-28

Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-03-29
Last registration	2024-03-14
Complete history	See info



Registration #1	2007-03-29	26 mi
Registration #2	2010-03-29	55.018 mi
Registration #3	2011-04-05	63.429 mi
Registration #4	2012-10-03	77.098 mi
Registration #5	2012-10-04	77.098 mi
Registration #6	2013-04-23	81.802 mi
Registration #7	2014-05-06	90.623 mi
Registration #8	2015-05-27	100.276 mi
Registration #9	2016-05-03	104.184 mi
Registration #10	2016-05-03	104.184 mi
Registration #11	2017-04-27	106.655 mi
Registration #12		11.117 es
Registration #13		11.177 es
Registration #14		11.117 es
Registration #15		11.177 es
Registration #16		11.117 es
Registration #17		11.177 es
Registration #18		11.117 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		

More info >

CarCheck.co.uk page 13/14



PK07XKP report date: 2024-03-28

Safety ratings

NCAP rating	***

Video <u>see crash video</u>



Dimensions & weight

Width	1872 mm
Height	1473 mm
Length	5076 mm
Wheel base	3035 mm
Kerb weight	1965 kg
Max. allowed weight	2550 kg

Additional information

Fuel tank capacity	90 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	64293040339215

CarCheck.co.uk page 14/14