





report date: 2024-03-28

General information

Make	FORD
Model	S-MAX TITANIUM TDCI
Colour	Silver
Year of manufacture	2009
Top speed	120 mph
0 - 60 mph	11.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	140 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	28.5 mpg
Consumption extra urban	48.7 mpg
Consumption combined	38.7 mpg
CO2 emission	189 g/km
CO2 label	J



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date 2021-09-29

Pictures 37

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2025-03-14
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	17
Total items failed	3

MOT #16	2024-03-12 13:06
MOT test number	772849241835
Result	✓ Passed
Next expiry date	2025-03-14

MOT #15	2023-03-13 16:55
MOT test number	870280737868
Result	✓ Passed

MOT #14	2022-03-15 12:16
MOT test number	149514444189
Result	✓ Passed

MOT #13	2022-03-15 10:53
MOT test number	609161775734
Result	× Failed
Fail Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))	

CarCheck.co.uk page 3/13



MOT #12 2021-10-07 10:35

MOT test number 158998575744

Result ✓ Passed

Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing

Arm (5.3.4 (a) (i))

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing

Arm (5.3.4 (a) (i))

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #11 2020-12-04 10:22

MOT test number 999979290557

Result \rightarrow Passed

Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10 2019-12-10 09:47

MOT test number 737314279072

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Rear Child Seat fitted not allowing full inspection of adult belt

MOT #9 2018-12-07 11:11

MOT test number 644897818083

Result ✓ Passed

MOT #8 2017-11-30 11:59

MOT test number 177386659938

CarCheck.co.uk page 4/13



EJ59XBN

report date: 2024-03-28

MOT #7

MOT test number

727925515809

Result

Advice Engine cover and under-tray fitted

MOT #6 2016-11-30 15:21 **MOT** test number 381779673131 Result × Failed Fail Offside Front Tyre has ply or cords exposed (4.1.D.1b) Offside Rear Direction indicator slightly discoloured (1.4.A.2f) **Advice** Nearside Rear Tyre worn on outer edge Advice Nearside Rear Direction indicator slightly discoloured (1.4.A.2f) Advice **Advice** Engine cover and under-tray fitted

 MOT #5
 2015-12-09 14:05

 MOT test number
 822209001947

 Result
 ✓ Passed

MOT #4

MOT test number

696926024327

Result

Notice

N/S/F Tyre worn on inner edge and cracking

Notice

Child seat fitted not allowing full inspection of adult belt

Notice

Nail in nearside front tyre

 MOT #3
 2013-11-22 08:50

 MOT test number
 925966723384

 Result
 ✓ Passed

CarCheck.co.uk page 5/13



EJ59XBN

report date: 2024-03-28

MOT #2 2012-12-12 08:13 **MOT test number** 878567242317 ✓ Passed Result MOT #1 2012-12-10 09:33 965245642317 **MOT test number** × Failed Result Fail Offside Front Valve stem seriously damaged (4.1.D.1e) Notice Child seat fitted not allowing full inspection of adult belt

CarCheck.co.uk page 6/13





Tax & MOT check



Tax status	Valid until 1 March
Days left	307
MOT expiry date	14 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



O	history
IWADAL	
	IIISLUIV

e when makeny	
For how long did the current and previous owner(s) have this FORD? How many owners defect it in the premium report and see all owner registrations. Download the full report $\underline{\mathbf{k}}$	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	OR STATE
Flate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-12-10
Last registration	2024-03-12
Complete history	See info



Registration #1	2009-12-10	20 mi
Registration #2	2012-12-10	10.789 mi
Registration #3	2012-12-12	10.790 mi
Registration #4	2013-11-22	15.333 mi
Registration #5	2014-11-22	19.139 mi
Registration #6	2015-12-09	24.409 mi
Registration #7	2016-11-30	28.413 mi
Registration #8	2016-12-01	28.413 mi
Registration #9	2017-11-30	32.845 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		D.777 es
Registration #17		11.777 es
Registration #18		11.777 es

More info >

page 12/13 CarCheck.co.uk



Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2154 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1943 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 13/1

Number of axles 2

Engine number 9G39426