






report date: 2024-03-28

General information

Make	FORD
Model	FOCUS ZETEC
Colour	Black
Year of manufacture	2010
Top speed	107 mph
0 - 60 mph	13.6 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	100 BHP
Max. torque	149 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	48.7 mpg
Consumption combined	37.7 mpg
CO2 emission	184 g/km
CO2 label	I



CarCheck.co.uk page 1/11



MOT history

all lamps (4.7.1 (b) (ii))

MOT expiry date	2024-09-01
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	8
Total items failed	8

MOT #13		2023-08-29 10:22
MOT test	number	996128915442
Result		✓ Passed
Next expiry date 2024-09-03		
Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		

MOT #12	2022-08-22 15:22
MOT test number	798383174163
Result	✓ Passed
MOT #11	2022-08-22 15:22
MOT test number	637937949791
Result	★ Failed
Pass with rectification	Offside Front Position lamp not working (4.2.1 (a) (ii))
Pass with rectification	Nearside Rear Registration plate lamp inoperative in the case of a single lamp or

MOT #10	2021-09-02 14:57
MOT test number	723667875658
Result	✓ Passed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 2/11



MOT #9 2020-07-25 09:57

MOT test number 616780736206

MOT #8 2019-08-14 11:57

MOT test number 128518930650

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #7 2019-08-07 11:34

MOT test number 944518679674

Result × Failed

Fail Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Fail Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Nearside Side repeater not working (4.4.1 (a) (ii))

MOT #6 2018-12-21 09:08

MOT test number 902528059743

Result
✓ Passed

MOT #5 2017-12-18 08:38

MOT test number 313712473285

CarCheck.co.uk page 3/11



MOT #4	2016-12-19 13:07
MOT test number	342441314435
Result	✓ Passed
Advice Front Brake pad(s) wearing thin (3.5.1g)	

Advice Front Brake pad(s) wearing thin (3.5.1g)	
MOT #2	2015 12 24 12 50
MOT #3	2015-12-24 12:50
MOT test number	140807067962
Result	✓ Passed
MOT #2	2014-10-23 14:00
MOT test number	569836394238
Result	✓ Passed
MOT #1	2013-09-20 12:20
MOT test number	805193163239
Result	✓ Passed
Notice Offside front tyre worn low inside edge	

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 July
Days left	64
MOT expiry date	1 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

e when miscery	
For how long did the current and previous owner(s) have this FORD? How many owners check it in the premium report and see all owner registrations. Download the full report	
manus .	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	NK NK
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >


CarCheck.co.uk page 9/11



Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2010-09-29
Last registration	2023-08-29
Complete history	See info



Registration #1	2010-09-29	25 mi
Registration #2	2013-09-20	31.002 mi
Registration #3	2014-10-23	40.934 mi
Registration #4	2015-12-24	56.208 mi
Registration #5	2016-12-19	67.261 mi
Registration #6	2017-12-18	72.011 mi
Registration #7	2018-12-21	76.727 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2019 mm
Height	1500 mm
Length	4337 mm
Wheel base	2640 mm
Kerb weight	1314 kg
Max. allowed weight	1835 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11,

Number of axles 2

Engine number AY19587