



Mercedes-Benz




report date: 2024-03-28

General information

Make	MERCEDES
Model	B-CLASS B170 SE
Colour	Silver
Year of manufacture	2006
Top speed	114 mph
0 - 60 mph	11.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	155 Nm at 4.000 rpm
Engine capacity	1.699 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	48.7 mpg
Consumption combined	41.5 mpg
CO2 emission	163 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-09-04
Pictures	24
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-03-27
MOT pass rate	64 %
MOT passed	16
Failed MOT tests	9
Total advice items	31
Total items failed	15

MOT #25	2024-03-28 12:18
MOT test number	346501295490
Result	✓ Passed
Next expiry date	2025-03-27
Minor	Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #24	2024-03-28 12:18
MOT test number	630033615447
Result	✗ Failed
Minor	Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Pass with rectification	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #23	2023-01-26 14:26
MOT test number	307375174111
Result	✓ Passed

MOT #22	2023-01-26 14:26
MOT test number	275711112533
Result	✗ Failed
Pass with rectification	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

**MOT #21** 2022-01-26 12:01**MOT test number** 716773135653**Result** ✓ Passed**MOT #20** 2021-01-27 15:42**MOT test number** 568459818619**Result** ✓ Passed

- Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #19 2020-01-18 09:39**MOT test number** 639961015499**Result** ✓ Passed

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Tyre slightly damaged/cracking or perishing both sides (5.2.3 (d) (ii))

**MOT #18**

2020-01-18 09:39

MOT test number

661167096479

Result**✗ Failed****Advice** Rear Tyre slightly damaged/cracking or perishing both sides (5.2.3 (d) (ii))**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**MOT #17**

2019-01-19 11:02

MOT test number

875112937777

Result**✓ Passed****MOT #16**

2018-01-22 10:36

MOT test number

609731136970

Result**✓ Passed****Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Offside Front Tyre worn close to the legal limit outer edge (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit outer edge (4.1.E.1)

**MOT #15** 2018-01-22 10:36**MOT test number** 559998659463**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit outer edge (4.1.E.1)**Pass with rectification** Offside Stop lamp not working (1.2.1b)**Advice** Offside Front Tyre worn close to the legal limit outer edge (4.1.E.1)**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #14** 2017-02-24 16:05**MOT test number** 593068855551**Result** ✓ Passed**Advice** Oil leak**MOT #13** 2017-02-24 11:41**MOT test number** 366020466395**Result** ✗ Failed**Advice** Oil leak**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Driver's door cannot be opened from inside the vehicle (6.2.B.1b)**Fail** Rear parking brake recording little or no effort 11% (3.7.B.6a)**MOT #12** 2016-02-26 10:18**MOT test number** 705811391489**Result** ✓ Passed**MOT #11** 2015-02-18 10:48**MOT test number** 707319345007**Result** ✓ Passed

**MOT #10** 2014-02-13 14:38**MOT test number** 297424044086**Result** ✓ Passed**MOT #9** 2014-02-13 10:34**MOT test number** 359674044053**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Stop lamp not working (1.2.1b)**MOT #8** 2013-02-15 11:17**MOT test number** 255826743077**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #7** 2013-02-15 11:17**MOT test number** 468876643088**Result** ✗ Failed**Pass with rectification** Nearside Rear Stop lamp not working (1.2.1b)**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #6** 2012-02-14 14:52**MOT test number** 608475642000**Result** ✓ Passed

**MOT #5** 2012-02-14 09:29**MOT test number** 207505242025**Result** ✗ Failed**Advice** Parking brake lever has little reserve travel (3.1.6b)**Fail** Rear An item not tested (Manual)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Stop lamp not working (1.2.1b)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #4** 2011-02-16 13:43**MOT test number** 199037241420**Result** ✓ Passed**Notice** Covers over offside and nearside front and rear inner wings, & offside and nearside floors. not allowing full inspection**MOT #3** 2010-02-15 15:02**MOT test number** 622006640013**Result** ✓ Passed**MOT #2** 2010-02-15 09:12**MOT test number** 723836740068**Result** ✗ Failed**Fail** Offside Front coil spring fractured (2.4.C.1a)**MOT #1** 2009-02-24 09:37**MOT test number** 201605459088**Result** ✓ Passed**Notice** Front tyres worn to 3mm**Notice** Washers Poor



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
27 March 2025

Tax status	Valid until 1 November
Days left	186
MOT expiry date	27 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2019-01-01
Current registration	XXXXXX
Plate since	2019-01-01

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2006-03-16
Last registration	2024-03-28
Complete history	See info



Registration #1	2006-03-16	25 mi
Registration #2	2009-02-24	30.482 mi
Registration #3	2010-02-15	42.513 mi
Registration #4	2010-02-15	42.513 mi
Registration #5	2011-02-16	50.692 mi
Registration #6	2012-02-14	55.260 mi
Registration #7	2012-02-14	55.260 mi
Registration #8	2013-02-15	59.678 mi
Registration #9	2014-02-13	63.472 mi
Registration #10	2014-02-13	63.472 mi
Registration #11	2015-02-18	68.443 mi
Registration #12	2016-02-26	72.377 mi
Registration #13	2017-02-24	76.674 mi
Registration #14	2018-02-24	81.000 mi
Registration #15	2019-02-24	85.326 mi
Registration #16	2020-02-24	89.652 mi
Registration #17	2021-02-24	93.978 mi
Registration #18	2022-02-24	98.304 mi
Registration #19	2023-02-24	102.630 mi
Registration #20	2024-02-24	106.956 mi
Registration #21	2025-02-24	111.282 mi
Registration #22	2026-02-24	115.608 mi
Registration #23	2027-02-24	119.934 mi
Registration #24	2028-02-24	124.260 mi
Registration #25	2029-02-24	128.586 mi
Registration #26	2030-02-24	132.912 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1777 mm
Height	1603 mm
Length	4270 mm
Wheel base	2778 mm
Kerb weight	1310 kg
Max. allowed weight	1830 kg

Additional information

Fuel tank capacity	54 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	26694030124500