



**XEZ79I2**

report date: 2024-03-28

General information

Make	FORD
Model	FOCUS ZETEC
Colour	Blue
Year of manufacture	2009
Top speed	115 mph
0 - 60 mph	11.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	143 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.7 mpg
Consumption extra urban	51.4 mpg
Consumption combined	40.9 mpg
CO2 emission	159 g/km
CO2 label	G





MOT history

MOT expiry date	2024-09-21
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	18
Total items failed	0

MOT #9	2023-09-19 15:39
MOT test number	551722811196
Result	✓ Passed
Next expiry date	2024-09-21

MOT #8	2022-09-22 14:08
MOT test number	144989050228
Result	✓ Passed

Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
--------	---

**MOT #7**

2022-09-16 13:30

**MOT test number**

261710796629

**Result****✗ Failed**

**MAJOR** Nearside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MAJOR** Offside Rear Anti-roll bar linkage insecurely attached (5.3.3 (a) (i))

**Advice** Heat shield loose

**MAJOR** Front Lower Suspension arm pin or bush excessively worn both (5.3.4 (a) (i))

**Minor** Nearside Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MAJOR** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**MOT #6**

2021-09-16 11:16

**MOT test number**

524197993524

**Result****✓ Passed****MOT #5**

2020-09-15 12:36

**MOT test number**

223348581040

**Result****✓ Passed**

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge very close (5.2.3 (e))

**Advice** Offside Front Anti-roll bar linkage ball joint has slight play drop link bar (5.3.4 (a) (i))

**Advice** Rear Exhaust shield loose

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #4**

2019-09-13 08:13

**MOT test number**

868010792997

**Result****✓ Passed**

**MOT #3** 2018-09-14 14:26**MOT test number** 375480998946**Result** ✓ Passed**MOT #2** 2018-09-14 10:07**MOT test number** 770178773744**Result** ✗ Failed

**MAJOR** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MAJOR** Offside Front Position lamp not working sidelight (4.2.1 (a))

**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #1** 2017-09-15 09:23**MOT test number** 955444931716**Result** ✓ Passed

**Advice** Front Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
21 September 2024

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	64
<b>MOT expiry date</b>	21 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXX	XXXXXX
XXXXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXX	XXXXXX
XXXXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	 XXXXX
Plate since	2023-03-28
Current registration	 XXXXX
Plate since	2023-03-28

More info >





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2009-07-06
Last registration	2023-09-19
Complete history	<a href="#">See info</a>



Registration #1	2009-07-06	22 mi
Registration #2	2017-09-15	68.118 mi
Registration #3	2018-09-14	75.411 mi
Registration #4	2018-09-14	75.435 mi
Registration #5	2019-09-13	79.129 mi
Registration #6	2020-09-20	85.277 mi
Registration #7	2021-09-20	91.425 mi
Registration #8	2022-09-20	97.573 mi
Registration #9	2023-09-19	103.721 mi
Registration #10	2024-03-28	109.869 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1998 mm
Height	1430 mm
Length	4152 mm
Wheel base	2640 mm
Kerb weight	1277 kg
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	9U51607