



report date: 2024-03-29

General information

Make	FORD
Model	GALAXY TITANIUM TDCI
Colour	Grey
Year of manufacture	2009
Top speed	120 mph
0 - 60 mph	11.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	140 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	28.5 mpg
Consumption extra urban	48.7 mpg
Consumption combined	38.7 mpg
CO2 emission	189 g/km
CO2 label	J






Internet history

Entry 1

Date	2021-10-28
Pictures	27
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-21
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	33
Total items failed	23

MOT #18 2024-01-22 12:02

MOT test number 925356891046

Result ✓ Passed

Next expiry date 2025-01-21

- Advice** Nearside Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

MOT #17 2022-11-24 12:29

MOT test number 233856440557

Result ✓ Passed

- Advice** Nearside Front Inner Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge tyre on the limit (5.2.3 (e))
- Advice** Rear Suspension component corroded but not seriously weakened all the rear (5.3.3 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge tyre on the limit (5.2.3 (e))
- Advice** Offside Front Inner Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #16**

2022-11-10 12:03

MOT test number

593247531081

Result

✗ Failed

Advice Offside Front Tyre worn close to legal limit/worn on edge tyre on the limit (5.2.3 (e))**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Front Inner Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge tyre on the limit (5.2.3 (e))**Advice** Rear Suspension component corroded but not seriously weakened all the rear (5.3.3 (b) (i))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**Fail** Nearside Front Outer Side repeater not working (4.4.1 (a) (ii))**Fail** Nearside Rear Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Offside Front Inner Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #15**

2021-11-10 15:54

MOT test number

551757883782

Result

✓ Passed

Minor Nearside Side repeater insecure (4.4.1 (c) (i))**Advice** Offside Front Tyre slightly damaged (5.2.3 (d) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both sides surface corroded (1.1.14 (a) (ii))**Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both sides surface corroded (1.1.14 (a) (ii))**MOT #14**

2020-10-30 13:41

MOT test number

308512546585

Result

✓ Passed

**MOT #13** 2020-10-29 16:27**MOT test number** 406503349448**Result** ✗ Failed**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #12** 2019-04-29 16:26**MOT test number** 452257079704**Result** ✓ Passed**MOT #11** 2018-04-17 13:48**MOT test number** 253084432812**Result** ✓ Passed**MOT #10** 2017-04-24 10:43**MOT test number** 446671777030**Result** ✓ Passed**MOT #9** 2016-04-04 11:29**MOT test number** 221091754768**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #8** 2015-04-16 10:20**MOT test number** 118486605197**Result** ✓ Passed**Notice** Nail in offside rear tyre**Notice** Items removed from driver's view prior to test**Notice** Front bumper insecure

**MOT #7**

2015-04-14 12:33

MOT test number

629794305126

Result**✗ Failed****Notice**

Front bumper insecure

Fail

Offside Side repeater excessively damaged so that it is not visible from a reasonable distance (1.4.A.2e)

Fail

Offside Headlamp insecure (1.7.3)

Fail

Offside Headlamp aim too high (1.8)

Notice

Nail in offside rear tyre

Fail

Nearside Side repeater excessively damaged so that it is not visible from a reasonable distance (1.4.A.2e)

Notice

Items removed from driver's view prior to test

Fail

Nearside Headlamp insecure (1.7.3)

Fail

Nearside Headlamp aim too low (1.8)

Fail

Body has a sharp edge caused by damage (6.1.C.1)

MOT #6

2014-04-24 09:56

MOT test number

539084214154

Result**✓ Passed****Notice**

Front bumper insecure

Advice

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2014-04-23 16:16**MOT test number** 587863514115**Result** ✗ Failed**Fail** Centre Stop lamp not working (1.2.1b)**Notice** Front bumper insecure**Fail** Nearside Headlamp aim too low and too far to the right. (1.8)**Fail** Offside Obligatory mirror seriously damaged, affecting the rear view (8.1.2a)**Fail** Offside Side repeater missing (1.4.A.2b)**Fail** Offside Headlamp aim too high (1.8)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)**MOT #4** 2013-04-11 14:15**MOT test number** 867401303185**Result** ✓ Passed**MOT #3** 2013-04-08 17:18**MOT test number** 945888393096**Result** ✗ Failed**Fail** Nearside Headlamp insecure (1.7.3)**MOT #2** 2012-03-23 15:09**MOT test number** 297993182088**Result** ✓ Passed**Notice** THIS VEHICLE WAS TESTED AS PRESENTED WITH 4 PASSENGER SEATS AVAILABLE FOR TEST**Notice** HIGH LEVEL STOP LIGHT NOT WORKING



MOT #12012-03-23 15:09

MOT test number686393882063

Result✖ Failed

- Pass with rectification

Offside Headlamp aim too low (1.8)
- Notice

THIS VEHICLE WAS TESTED AS PRESENTED WITH 4 PASSENGER SEATS AVAILABLE FOR TEST
- Pass with rectification

Nearside Headlamp aim too low (1.8)
- Notice

HIGH LEVEL STOP LIGHT NOT WORKING
- Pass with rectification

Offside Side repeater not working (1.4.A.2c)



Tax & MOT check

X

Untaxed

Tax expired:
12 April 2024

✓

MOT

Expires:
21 January 2025

Tax status	Expired at 12 April 2024
Days left	18 days too late
MOT expiry date	21 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-03-17
Last registration	2024-01-22
Complete history	See info



Registration #1	2009-03-17	12 mi
Registration #2	2012-03-23	26.418 mi
Registration #3	2013-04-08	30.954 mi
Registration #4	2013-04-11	30.376 mi
Registration #5	2014-04-23	37.239 mi
Registration #6	2014-04-24	37.239 mi
Registration #7	2015-04-14	44.290 mi
Registration #8	2015-04-16	44.326 mi
Registration #9	2016-04-04	50.184 mi
Registration #10	2017-04-24	57.048 mi
Registration #11	2018-04-24	57.048 mi
Registration #12	2019-04-24	57.048 mi
Registration #13	2020-04-24	57.048 mi
Registration #14	2021-04-24	57.048 mi
Registration #15	2022-04-24	57.048 mi
Registration #16	2023-04-24	57.048 mi
Registration #17	2024-01-22	57.048 mi
Registration #18	2024-01-22	57.048 mi
Registration #19	2024-01-22	57.048 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2154 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1943 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	9G39426