



report date: 2024-03-29

General information

Make	VAUXHALL
Model	MERIVA TECH LINE
Colour	Grey
Year of manufacture	2014
Top speed	110 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	130 Nm at 4.000 rpm
Engine capacity	1.398 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg
CO2 emission	140 g/km
CO2 label	E





MOT history

MOT expiry date	2025-04-01
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	10
Total items failed	5

MOT #112024-03-25 12:19

MOT test number838428248650

Result✓ Passed

Next expiry date2025-04-01

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Brake disc worn, pitted or scored, but not seriously weakened all 4 (1.1.14 (a) (ii))
- Advice** Front flexi exhaust corroded
- Advice** Rear Coil spring corroded both rear (5.3.1 (b) (i))

MOT #102023-03-30 16:06

MOT test number542294587305

Result✓ Passed

- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #92022-03-30 16:46

MOT test number703455592105

Result✓ Passed

**MOT #8** 2022-03-30 16:46**MOT test number** 722916035337**Result** ✗ Failed

- Pass with rectification** Nearside Front Headlamp aim too far to the left (4.1.2 (a))
- Pass with rectification** Nearside Rear Exhaust system insecure not fitted in bracket (6.1.2 (a))
- Pass with rectification** Offside Front Headlamp aim too low and too far to the right. (4.1.2 (a))

MOT #7 2021-04-02 08:46**MOT test number** 595100250353**Result** ✓ Passed**MOT #6** 2020-09-30 12:54**MOT test number** 855973671593**Result** ✓ Passed**MOT #5** 2020-09-30 11:12**MOT test number** 107631904104**Result** ✗ Failed

- MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

MOT #4 2019-10-11 12:33**MOT test number** 429266839009**Result** ✓ Passed**MOT #3** 2018-10-09 08:28**MOT test number** 219298315066**Result** ✓ Passed

- Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))



MOT #2	2018-10-09 08:28
MOT test number	472131318884
Result	✗ Failed
Pass with rectification	Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Pass with rectification	Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Advice	Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #1	2017-10-09 08:18
MOT test number	608147599014
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
1 April 2025

Tax status	Valid until 1 April
Days left	336
MOT expiry date	1 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 DA64LVF
Plate since	2024-03-29
Current registration	 DA64LVF
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-10-30
Last registration	2024-03-25
Complete history	See info



Registration #1	2014-10-30	11 mi
Registration #2	2017-10-09	22.727 mi
Registration #3	2018-10-09	34.360 mi
Registration #4	2018-10-09	34.360 mi
Registration #5	2019-10-11	45.376 mi
Registration #6	2020-09-30	56.925 mi
Registration #7	2020-09-30	56.925 mi
Registration #8	2020-09-30	56.925 mi
Registration #9	2020-09-30	56.925 mi
Registration #10	2020-09-30	56.925 mi
Registration #11	2020-09-30	56.925 mi
Registration #12	2020-09-30	56.925 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	77%
Pedestrian	55%
Safety systems	86%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1994 mm
Height	1615 mm
Length	4300 mm
Wheel base	2644 mm
Kerb weight	1376 kg
Max. allowed weight	1905 kg

Additional information

Fuel tank capacity	54 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	B14XER -19EF8057LDD