



General information

Make	FORD
Model	S-MAX
Colour	White
Year of manufacture	2014
Top speed	121 mph
0 - 100 km/h	10.2 seconds
Gearbox	6 speed manual

Engine & fuel consumption

Power	103 kW / 140 HP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	50.0 mpg
Consumption combined	44.4 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 2

Date	2021-11-10
Pictures	4
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-11-09
Pictures	4
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-11-24
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	11
Total items failed	10

## MOT #12 2023-11-15 11:27

MOT test number 566367213164

Result ✓ Passed

Next expiry date 2024-11-24

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))

## MOT #11 2022-11-22 14:52

MOT test number 549002478724

Result ✓ Passed

- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

## MOT #10 2021-11-25 10:26

MOT test number 931351279723

Result ✓ Passed

**MOT #9** 2021-11-23 15:28**MOT test number** 157939169642**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too high and too far to the right. Adjusted (4.1.2 (a))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge wearing on inner edge (5.2.3 (e))**Minor** Nearside Reversing lamp lens defective such that emitted light is adversely affected Lens broken / holed (4.6.1 (b))**Fail** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Fail** Nearside Rear Seat belt not functioning as intended Jammed in retracted position (7.1.2 (c))**Fail** Central Rear Seat belt webbing significantly weakened (7.1.2 (b) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge wearing on inner edge (5.2.3 (e))**MOT #8** 2021-03-26 14:52**MOT test number** 155970908365**Result** ✓ Passed**MOT #7** 2020-03-06 16:52**MOT test number** 237533504479**Result** ✓ Passed**MOT #6** 2020-03-03 17:15**MOT test number** 286330015983**Result** ✗ Failed**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #5** 2019-03-16 10:00**MOT test number** 986427175687**Result** Passed**MOT #4** 2019-03-16 10:00**MOT test number** 264563612524**Result** Failed

**Pass with rectification** Registration plate lamp inoperative in the case of a single lamp or all lamps  
(4.7.1 (b) (ii))

**MOT #3** 2018-03-09 11:36**MOT test number** 387501502614**Result** Passed**MOT #2** 2018-03-09 09:04**MOT test number** 837626414351**Result** Failed

**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

**MOT #1** 2017-03-11 10:17**MOT test number** 640904762732**Result** Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 May 2024

✓  
**MOT**  
**Expires:**  
24 November 2024

<b>Tax status</b>	Valid until 1 May
<b>Days left</b>	2
<b>MOT expiry date</b>	24 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2014-03-02
Last registration	2023-11-15
Complete history	<a href="#">See info</a>



Registration #1	2014-03-02	28 mi
Registration #2	2017-03-11	25.136 mi
Registration #3	2018-03-09	38.993 mi
Registration #4	2018-03-09	38.993 mi
Registration #5	2019-03-16	52.500 mi
Registration #6	2019-03-16	52.500 mi
Registration #7	2020-03-03	65.271 mi
Registration #8	2020-03-06	65.271 mi
Registration #9	2020-03-06	65.271 mi
Registration #10	2020-03-06	65.271 mi
Registration #11	2020-03-06	65.271 mi
Registration #12	2020-03-06	65.271 mi
Registration #13	2020-03-06	65.271 mi
Registration #14	2020-03-06	65.271 mi
Registration #15	2020-03-06	65.271 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1884 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1590 kg

Additional information

Fuel tank capacity	70 l
Number of axles	2
Engine number	EA09685