



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	GOLF MATCH TDI 105
Colour	Black
Year of manufacture	2008
Top speed	116 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	103 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	53.3 mpg
CO2 emission	132 g/km
CO2 label	E





MOT history

MOT expiry date	2021-12-09
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	17
Total items failed	3

MOT #12 2020-12-10 11:22

MOT test number 340438432137

Result ✓ Passed

Next expiry date 2021-12-09

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Minor Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Minor Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Child Seat fitted not allowing full inspection of adult belt

Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Minor Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #11 2019-11-21 15:12

MOT test number 209309814246

Result ✓ Passed

MOT #10 2018-12-10 08:51

MOT test number 364823123943

Result ✓ Passed

**MOT #9** 2017-08-31 14:18**MOT test number** 551644021466**Result** ✓ Passed**MOT #8** 2016-09-20 14:37**MOT test number** 796744750759**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**MOT #7** 2016-09-20 10:50**MOT test number** 875317781195**Result** ✗ Failed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Offside Front Tyre worn close to the legal limit 3mm & worn to edge(s) (4.1.E.1)**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**MOT #6** 2015-09-15 16:02**MOT test number** 222853216139**Result** ✓ Passed**MOT #5** 2014-09-11 15:05**MOT test number** 458324154228**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)



MOT #4	2014-09-11 12:17
---------------	------------------

MOT test number	586934254224
------------------------	--------------

Result	✗ Failed
---------------	----------

Fail	Nearside Registration plate lamp not working (1.1.C.1d)
-------------	---

Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
---------------	--

Advice	Nearside Front Shock absorber has a light misting of oil (2.7.3)
---------------	--

Fail	Exhaust emits an excessive level of metered smoke (7.4.B.3a)
-------------	--

Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
---------------	---

MOT #3	2013-09-09 12:52
---------------	------------------

MOT test number	557252053242
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2012-09-08 13:04
---------------	------------------

MOT test number	348212852236
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2011-09-13 13:24
---------------	------------------

MOT test number	529626751232
------------------------	--------------

Result	✓ Passed
---------------	----------



Tax & MOT check

✕
Untaxed

Tax expired:
26 September 2021

✕
MOT

Expired:
9 December 2021

Tax status	Expired at 26 September
Days left	946 days too late
MOT expiry date	9 December 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	LR58MVL
Plate since	2019-06-29
Current registration	LR58MVL
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2008-09-15
Last registration	2020-12-10
Complete history	See info



Registration #1	2008-09-15	8 mi
Registration #2	2011-09-13	47.446 mi
Registration #3	2012-09-08	68.225 mi
Registration #4	2013-09-09	89.422 mi
Registration #5	2014-09-11	107.275 mi
Registration #6	2014-09-11	107.275 mi
Registration #7	2015-09-15	114.482 mi
Registration #8	2016-09-15	121.689 mi
Registration #9	2017-09-15	128.896 mi
Registration #10	2018-09-15	136.103 mi
Registration #11	2019-09-15	143.310 mi
Registration #12	2020-09-15	150.517 mi
Registration #13	2021-09-15	157.724 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1759 mm
Height	1479 mm
Length	4204 mm
Wheel base	2578 mm
Kerb weight	1251 kg
Max. allowed weight	1890 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	BXE B29276