

Ford



General information

Make	FORD
Model	B-MAX ZETEC
Colour	White
Year of manufacture	2014
Top speed	109 mph
0 - 100 km/h	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 kW / 101 HP / 99 BHP
Max. torque	170 Nm at 1.400 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	42.8 mpg
Consumption extra urban	65.7 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	С





Internet history

Entry 1

Date

Pictures

2021-05-21

Listing price

View report

17



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-29
MOT pass rate	58 %
MOT passed	7
Failed MOT tests	5
Total advice items	2
Total items failed	12

MOT #12	2023-06-21 14:58
MOT test number	290530218965
Result	✓ Passed
Next expiry date	2024-06-29

MOT #11	2023-06-21 09:56
MOT test number	625522636997
Result	🗙 Failed
Fail Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))	

MOT #10	2022-06-15 15:45
MOT test number	912093418425
Result	✓ Passed

MOT #9	2022-06-15 09:44	
MOT test number	981948823071	
Result	🗙 Failed	
Advice Offside Front Inner Tyre worn close to legal limit/worn on edge 0mm (5.2.3 (e	2))	
Fail Offside Front Inner Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))		
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))		
Fail Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))		





MOT #8	2021-06-23 15:06
MOT test number	203120292214
Result	✓ Passed
MOT #7	2021-06-23 08:36
MOT test number	633246223579
Result	🗙 Failed
Fail Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))	

MOT #6	2020-06-30 10:16
MOT test number	287504025274
Result	✓ Passed

MOT #5	2020-06-29 11:52
MOT test number	724909400388
Result	🗙 Failed
Fail Offside Front Windscreen washer jets misaligned and not providing sufficient fl (3.5 (a))	uid to the windscreen
Fail Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.7	2 (c))
Fail Nearside Front Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen (3.5 (a))	
Fail Nearside Front Headlamp aim projected beam image is obviously incorrect (4.3)	1.2 (c))
Fail Front Windscreen washer provides insufficient washer liquid (3.5 (a))	

МОТ #4	2019-06-21 11:40
MOT test number	603081196787
Result	✓ Passed





MOT #3		2019-06-21 11:40
MOT test number		455661909432
Result		🗙 Failed
Pass with rectification	Nearside Rear Stop lamp(s) all not working (4.3.1 (a) (iii))	
Pass with rectification	Windscreen washer not working (3.5 (a))	
Pass with rectification	Offside Rear Stop lamp(s) all not working (4.3.1 (a) (iii))	

MOT #2	2018-06-20 16:14
MOT test number	910727180265
Result	✓ Passed
MOT #1	2017-06-27 16:09

	2017-00-27 10.09
MOT test number	477005141856
Result	✓ Passed



Tax & MOT check

✓ Taxed Tax due: 1 June 2024	✓ MOT Expires: 29 June 2024
Tax status	Valid until 1 June
Days left	32
MOT expiry date	29 June 2024
Full MOT history	See MOT history
Tax calculation	
Vehicle class	48

Venicle class	40
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date	F	
Category		ARME
Туре		
Damage 2		AMPLE
	E E	
Date		\$
Category	AMP	
Туре	No. Contraction of the second se	

Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	7
Carrent registration	
Plate since	
Carrent registration	
Carrent registration Plate since	





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2014-06-26
Last registration	2023-06-21
Complete history	<u>See info</u>



Registration #1	2014-06-26	15 mi
Registration #2	2017-06-27	24.040 mi
Registration #3	2018-06-20	32.821 mi
Registration #4	2019-06-21	41.070 mi
Registration #5	2019-06-21	41.070 mi
Registration #6	2020-06-29	50.595 mi
Registration #7	2020-06-30	50.596 mi
Devictuation #0		
Registration #8		
Registration #9		10.222 mi
-		10.000 est
Registration #9		0.000 est 0.000 est 0.000 est
Registration #9 Registration #10		0.000 est 0.000 est 0.000 est 0.000 est
Registration #9 Registration #10 Registration #11		0.000 est 0.000 est 0.000 est 0.000 est 0.000 est

More info >





Car features

S0225	Air conditioning
\$0295	
50482	
\$0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	92%
Children	84%
Pedestrian	67%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight	
Width	2067 mm
Height	1604 mm
Length	4077 mm
Wheel base	2489 mm
Kerb weight	1760 kg
Max. allowed weight	1760 kg
Additional information	
Fuel tank capacity	48
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles	2
Engine number	ES23713