





report date: 2024-03-28

General information

| Make | BMW |
|---------------------|------------------------|
| Model | M4 |
| Colour | Black |
| Year of manufacture | 2014 |
| Top speed | 155 mph |
| Gearbox | 7 speed Semi-Automatic |

Engine & fuel consumption

| Power | 425 BHP |
|-------------------------|---------------------|
| Max. torque | 550 Nm at 1.850 rpm |
| Engine capacity | 2.979 сс |
| Cylinders | 6 |
| Fuel type | Petrol |
| Consumption city | 25.5 mpg |
| Consumption extra urban | 42.2 mpg |
| Consumption combined | 34.0 mpg |
| CO2 emission | 194 g/km |
| CO2 label | ı |



CarCheck.co.uk page 1/12



Internet history

Entry 1

| Date | 2021-07-22 | |
|---------------|--------------------|--|
| Pictures | 1 | |
| Listing price | <u>View report</u> | |



source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

Advice

| MOT expiry date | 2024-08-07 |
|--------------------|------------|
| MOT pass rate | 73 % |
| MOT passed | 8 |
| Failed MOT tests | 3 |
| Total advice items | 11 |
| Total items failed | 4 |

| MOT #11 | 2023-08-04 14:12 |
|------------------|------------------|
| MOT test number | 954903452502 |
| Result | ✓ Passed |
| Next expiry date | 2024-08-07 |

| MOT #10 | 2023-08-03 13:06 |
|--|------------------|
| MOT test number | 564412772543 |
| Result | × Failed |
| Fail Offside Front Lower Suspension arm ball joint excessively worn front arm (5.3.4 (a) | (i)) |

| MOT #9 | 2022-08-08 15:16 |
|--|---------------------------|
| MOT test number | 279381643836 |
| Result | ✓ Passed |
| | |
| MOT #8 | 2022-08-05 13:56 |
| MOT test number | 545021789843 |
| Result | × Failed |
| Fail Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii)) | |
| Advice Slight play in front wheel(s) detected during decelerometer brake tes where | t, unable to specify from |
| Advice Offside Front Inner Tyre worn close to legal limit/worn on edge edge v | wear (5.2.3 (e)) |

CarCheck.co.uk page 3/12

Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))



MOT #7 2021-08-03 16:11

MOT test number 543958145745

MOT #6 2021-02-15 19:00

MOT test number 557791435592

Result

Passed

MOT #5 2020-02-12 14:06

MOT test number 719834233741

Result
✓ Passed

Advice Offside Rear Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))

Advice Full undertrays fitted

MOT #4 2019-04-01 09:49

MOT test number 658507544439

Result \(\sqrt{Passed} \)

Advice Full under trays fitted to car

(3.5.1i)

Advice Nearside Front Brake disc worn, but not excessively and offside front (1.1.14 (a) (i))

MOT #3 2018-04-06 13:38

MOT test number 711953122906

Result

Passed

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened AND OFFSIDE FRONT

Advice Nearside Front Tyre worn close to the legal limit AND OFFSIDE FRONT (4.1.E.1)

CarCheck.co.uk page 4/12



Result

ND14YTL report date: 2024-03-28

X Failed

MOT #2 2017-04-11 15:16

MOT test number 543161126821

Result ✓ Passed

Advice Engine and under guards fitted

MOT #1 2017-04-11 15:16

MOT test number 575860037898

Pass with rectification Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Pass with rectification Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Engine and under guards fitted

CarCheck.co.uk page 5/12



Tax & MOT check



| Tax status | Valid until 1 June |
|------------------|--------------------|
| Days left | 33 |
| MOT expiry date | 7 August 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|---|------------|
| Band | J |
| Single payment (12 months) | £ 365,00,- |
| Single six month payment | £ 200,75,- |
| Total payable by 12 monthly instalments | £ 383,25,- |

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

| For how long did the current and previous owner(s) have this BMW? How many owners d Check it in the premium report and see all owner registrations. Download the full report J | |
|---|-------------|
| *************************************** | |
| | |
| *************************************** | |
| ******** | |
| | |
| ************ | |
| | More info > |
| Plate changes | |
| See in this check if this BMW had different number plates. | |
| Number of plates | , |
| Current registration | UK UK |
| Plate since | |
| Current registration | NK SIN |
| Plate since | |
| | More info > |

CarCheck.co.uk page 9/12



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact info


More info >

CarCheck.co.uk page 10/12



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 13 |
| First mileage registration | 2014-06-21 |
| Last registration | 2023-08-04 |
| Complete history | See info |



| Registration #1 | 2014-06-21 | 19 mi |
|------------------|------------|-----------|
| Registration #2 | 2017-04-11 | 41.703 mi |
| Registration #3 | 2017-04-11 | 41.703 mi |
| Registration #4 | 2018-04-06 | 47.722 mi |
| Registration #5 | 2019-04-01 | 52.876 mi |
| Registration #6 | 2020-02-12 | 55.762 mi |
| Registration #7 | 2021-02-15 | 63.801 mi |
| Registration #8 | | 11.777 es |
| Registration #9 | | 11.777 mi |
| Registration #10 | | 11.777 es |
| Registration #11 | | 11.177 ms |
| Registration #12 | | 0.00 44 |
| Registration #13 | | D.777 es |

More info >

CarCheck.co.uk page 11/12



Car features

| S0225 | Air conditioning |
|-------|------------------|
| 50295 | |
| 50482 | |
| 50501 | |
| S0566 | |
| S0567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 91% |
| Children | 83% |
| Pedestrian | 63% |
| Safety systems | 86% |
| Overall rating | 83% |
| Video | see crash video |



Dimensions & weight

| Width | 1870 mm |
|---------------------|---------|
| Height | 1383 mm |
| Length | 4671 mm |
| Wheel base | 2812 mm |
| Kerb weight | 1537 kg |
| Max. allowed weight | 2040 kg |

Additional information

| Fuel tank capacity | 60 I | |
|-----------------------------------|------------------|----------|
| Fuel delivery | Direct Injection | |
| Number of doors | 2 | |
| Number of seats CarCheck.co.uk | 4 pa | ge 12/12 |

Number of axles 2

Engine number 08688890