




report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOURAN S TDI
Colour	Silver
Year of manufacture	2011
Top speed	114 mph
0 - 100 km/h	12.8 seconds
0 - 60 mph	12.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	77 kW / 105 HP / 106 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	62.8 mpg
Consumption combined	6.3 mpg
CO2 emission	134 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-06-18
Pictures	23
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-05-19
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	30
Total items failed	3

MOT #13	2023-05-19 12:55
MOT test number	191490998471
Result	✓ Passed
Next expiry date	2024-05-19
Advice	Rear Service brake fluctuating, but not excessively (1.2.1 (e))
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Inner sill covers fitted
Advice	Offside Rear Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))
Advice	Injector seals blowing - no fumes entering cabin

**MOT #12**

2023-05-19 10:36

MOT test number

678284999158

Result**✗ Failed****MAJOR** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Inner sill covers fitted**Advice** Rear Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MAJOR** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Injector seals blowing - no fumes entering cabin**Advice** Offside Rear Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))**MOT #11**

2022-05-20 10:02

MOT test number

163862541501

Result**✓ Passed****Advice** Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))**Advice** Items removed from driver's view prior to test**MOT #10**

2022-05-20 10:02

MOT test number

738251936600

Result**✗ Failed****Pass with rectification** Nearside Headlamp aim too high (4.1.2 (a))**Advice** Items removed from driver's view prior to test**Advice** Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))

**MOT #9** 2021-04-14 08:56**MOT test number** 500307307801**Result** ✓ Passed**Advice** Plastic underside floor covers fitted**MOT #8** 2020-05-05 13:52**MOT test number** 372085140242**Result** ✓ Passed**Advice** Front Service brake fluctuating, but not excessively Both discs (1.2.1 (e))**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Rear bush (5.3.4 (a) (i))**Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Rear bush (5.3.4 (a) (i))**MOT #7** 2020-05-05 13:25**MOT test number** 961437553058**Result** ✗ Failed**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Rear bush (5.3.4 (a) (i))**Advice** Front Service brake fluctuating, but not excessively Both discs (1.2.1 (e))**Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Rear bush (5.3.4 (a) (i))**MAJOR** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords
(5.2.3 (d) (i))**MOT #6** 2018-06-19 11:02**MOT test number** 701793962077**Result** ✓ Passed

**MOT #5** 2017-07-03 12:05**MOT test number** 514989785534**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Brake pad(s) wearing thin @ 2.5 to 3.0mm (3.5.1g)**MOT #4** 2016-04-01 12:39**MOT test number** 242799218688**Result** ✓ Passed**MOT #3** 2016-04-01 12:39**MOT test number** 250007036348**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (1.8)**Pass with rectification** Offside Headlamp aim too low (1.8)**MOT #2** 2015-04-25 09:54**MOT test number** 818025015190**Result** ✓ Passed**MOT #1** 2014-03-25 10:48**MOT test number** 188274584412**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
19 May 2024

Tax status	Valid until 1 September
Days left	126
MOT expiry date	19 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 VK11VHZ
Plate since	2019-06-29
Current registration	 VK11VHZ
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-03-30
Last registration	2023-05-19
Complete history	See info



Registration #1	2011-03-30	28 mi
Registration #2	2014-03-25	36.800 mi
Registration #3	2015-04-25	46.834 mi
Registration #4	2016-04-01	57.501 mi
Registration #5	2016-04-01	57.501 mi
Registration #6	2017-07-03	66.581 mi
Registration #7	2018-06-19	75.740 mi
Registration #8	2020-05-05	84.123 mi
Registration #9	2020-05-05	84.123 mi
Registration #10	2020-05-05	84.123 mi
Registration #11	2020-05-05	84.123 mi
Registration #12	2020-05-05	84.123 mi
Registration #13	2020-05-05	84.123 mi
Registration #14	2020-05-05	84.123 mi
Registration #15	2020-05-05	84.123 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1794 mm
Height	1634 mm
Length	4397 mm
Wheel base	2678 mm
Kerb weight	1539 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
-----------------	---

Engine number	CAY 586764
---------------	------------