





report date: 2024-03-28

General information

Make	CITROEN
Model	DISPATCH 1000 L1H1 SWB P/V HDI 90
Colour	White
Year of manufacture	2010
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	180 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 1

Date 2021-12-03

Pictures 14

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-07-20
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	12
Total items failed	22

MOT #15	2023-07-21 14:03
MOT test number	885990256295
Result	✓ Passed
Next expiry date	2024-07-20

MOT #14	2023-07-17 08:59
MOT test number	123646675134
Result	X Failed
Fail Rear Rear fog lamp not working (4.5.1 (a) (ii))	
Fail Offside Rear Direction indicator incorrect colour (4.4.3 (a))	
Fail Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))	
Fail Offside Front Position lamp not working (4.2.1 (a) (ii))	

MOT #13	2022-07-13 16:02
MOT test number	469615028993
Result	✓ Passed
MOT #12	2021-07-01 07:25
MOT test number	524740318510
Result	✓ Passed

CarCheck.co.uk page 3/13



MOT #11 2019-02-08 12:15

MOT test number 140584607306

Result ✓ Passed

Advice

Power steering component has slight seepage from a component steering rack pinon seal. (2.1.5

(a))

MOT #10 2018-02-06 14:20

MOT test number 774767810658

Result \(\sqrt{Passed} \)

MOT #9 2018-02-05 17:26

MOT test number 319139374684

Result × Failed

Fail Windscreen washer provides insufficient washer liquid (8.2.3)

Fail Nearside Stop lamp not working (1.2.1b)

Fail Offside Registration plate lamp not working (1.1.C.1d)

Fail Windscreen has damage to the swept area in excess of a 40mm circle outside zone 'A' (8.3.1d)

Fail Nearside Front position lamp(s) not working (1.1.A.3b)

Fail Nearside Registration plate lamp not working (1.1.C.1d)

Fail Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)

MOT #8 2017-01-30 07:53

MOT test number 662472853852

Result
✓ Passed

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #7 2017-01-24 09:26

MOT test number 561454729960

Result X Failed

Fail Nearside Stop lamp not working (1.2.1b)

Fail Nearside Front Lower Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)

Fail Nearside Front Outer Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

MOT #6 2016-02-06 09:55

MOT test number 972682963280

Result ✓ Passed

MOT #5 2015-11-05 15:51

MOT test number 519308138347

Result

Passed

Advice Centre brake light not working

Advice Nearside small crack in windscreen outside swept area

MOT #4 2014-10-29 16:17

MOT test number 996452404388

Result

Passed

Notice Upper stop lamp inop.

Notice Windscreen has large crack nearside (not in direct vision)


Advice Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Notice Offside wiper loose

CarCheck.co.uk page 5/13



report date: 2024-03-28



MOT #2	2013-11-07 16:55
MOT test number	908951813390
Result	✓ Passed
MOT #1	2013-11-06 09:12
MOT test number	285760313366
Result	★ Failed
Fail Centre Stop lamp not working (1.2.1b)	
Fail Nearside Anti-roll bar has excessive play in a pin/bush (2.4.G.2)	
Fail Nearside Registration plate lamp not working (1.1.C.1d)	
Notice Fuel cooler damaged but still secure not leaking	
Fail Windscreen washer provides insufficient washer liquid (8.2.3)	
Fail Offside Anti-roll bar has excessive play in a pin/bush (2.4.G.2)	

CarCheck.co.uk page 6/13



_



Days left 125

MOT expiry date 20 July 2024

Full MOT history See MOT history

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner	biotom,
UWNEI	nisioiv

,		
For how long did the current and previous owner(s) have this CITROEN? How many owne have? Check it in the premium report and see all owner registrations. Download the full r		OEN

	More info	>
Plate changes		
See in this check if this CITROEN had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-11-16
Last registration	2023-07-21
Complete history	See info



Registration #1	2010-11-16	25 mi
Registration #2	2013-11-06	55.859 mi
Registration #3	2013-11-07	55.911 mi
Registration #4	2014-10-29	69.107 mi
Registration #5	2015-11-05	78.705 mi
Registration #6	2016-02-06	78.903 mi
Registration #7	2017-01-24	93.652 mi
Registration #8	2017-01-30	93.827 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		10.777 mg

More info >

page 12/13 CarCheck.co.uk



Dimensions & weight

Width	2194 mm
Length	4805 mm

Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	3
Engine number	JBBY0029866

CarCheck.co.uk page 13/13