





report date: 2024-03-28

General information

Make	SUZUKI
Model	VITARA SZ5 DDIS ALLGRIP
Colour	Silver
Year of manufacture	2016
Top speed	112 mph
0 - 60 mph	11.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	70.6 mpg
Consumption combined	67.3 mpg
CO2 emission	111 g/km
CO2 label	С



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 6

Date 2021-08-19

Pictures 10

Listing price <u>View report</u>










source: autoonline.co.uk

Entry 5

Date	2021-08-18

Pictures 1

Listing price <u>View report</u>



source: heycar.co.uk

Entry 4

Date 2021-07-30	
-----------------	--

Pictures 25

Listing price <u>View report</u>










source: autotrader.co.uk

Entry 3

Date	2021-07-07

Pictures CarCheck.co.uk 1 page 2/11

Listing price <u>View report</u>



source: heycar.co.uk

Entry 2

Date	2021-06-18

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

Entry 1

Date 2	2021-06-13
--------	------------


Pictures 24

Listing price <u>View report</u>









source: yesauto.com



MOT history

MOT expiry date	2025-04-01
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	5
Total items failed	3

MOT #8	2024-04-02 08:29
MOT test number	191506335160
Result	✓ Passed
Next expiry date	2025-04-01

MO1 #7		2024-03-27 11.44
MOT test number		738919678873
Result		× Failed
Advice Nearside Fro	ont Play in steering rack inner joint(s)	
Fail Offside Brake pi	ipe excessively corroded front to rear (1.1.11 (c))	
Fail Nearside Brake	pipe excessively corroded front to rear (1.1.11 (c))	
Fail Nearside Rear C	Outer Brake pipe excessively corroded (1.1.11 (c))	

MOT #6	2023-10-13 09:22
MOT test number	321699087043
Result	✓ Passed

CarCheck.co.uk page 3/11



MOT #5 2022-10-07 09:50

MOT test number 450085628497

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #4 2021-10-15 16:23

MOT test number 647670276012

Result

Passed

Advice Nearside Play in steering rack inner joint(s)

MOT #3 2021-03-25 14:49

MOT test number 641007926043

MOT #2 2020-10-10 09:32

MOT test number 815164443437

Result ✓ Passed

MOT #1 2019-07-02 10:57

MOT test number 512177660494

Result ✓ Passed

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	1 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

*		
For how long did the current and previous owner(s) have this SUZUKI? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.		KI

	More info	>
Plate changes See in this check if this SUZUKI had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this SUZUKI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2016-09-21
Last registration	2024-04-02
Complete history	See info



Registration #1	2016-09-21	11 mi
Registration #2	2019-07-02	46.691 mi
Registration #3	2020-10-10	63.818 mi
Registration #4	2021-03-25	69.365 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Safety ratings

NCAP rating	****
Adult	89%
Children	85%
Pedestrian	76%
Safety systems	75%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1775 mm
Height	1610 mm
Length	4175 mm
Wheel base	2500 mm
Kerb weight	1370 kg
Max. allowed weight	1870 kg

Additional information

Fuel tank capacity	47
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	D16AA7525290

CarCheck.co.uk page 11/11