



report date: 2024-03-28

General information

Make	FORD
Model	KA ZETEC
Colour	Black
Year of manufacture	2009
Top speed	99 mph
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	44.8 mpg
Consumption extra urban	64.2 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-01-30
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2023-08-07
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	36
Total items failed	22

MOT #19	2022-08-08 14:50
MOT test number	290315668688
Result	✓ Passed
Next expiry date	2023-08-07

MOT #18	2022-05-06 07:52
MOT test number	500201638896
Result	✓ Passed

- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Breather pipe detached from air box possibly allowing fumes into cabin
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Rear axle has light corrosion

**MOT #17**

2022-05-04 08:41

**MOT test number**

132266165903

**Result****✗ Failed**

- Fail** Nearside Front Direction indicator not working (4.4.1 (a) (ii))
- Fail** Offside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Rear axle has light corrosion
- Fail** Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Breather pipe detached from air box possibly allowing fumes into cabin

**MOT #16**

2021-05-18 07:59

**MOT test number**

936864765536

**Result****✓ Passed**

- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #15**

2021-05-17 11:34

**MOT test number**

236035058615

**Result****✗ Failed**

- Fail** Battery insecure and likely to cause a short circuit (4.13 (a) (ii))
- Fail** Offside Front Lower Suspension arm pin or bush excessively worn Rear bush (5.3.4 (a) (i))
- Fail** Offside Rear Shock absorbers has an excessively worn bush (5.3.2 (c))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Nearside Front Lower Suspension arm pin or bush excessively worn Rear bush (5.3.4 (a) (i))
- Fail** Nearside Rear Shock absorbers has an excessively worn bush (5.3.2 (c))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

**MOT #14**

2019-10-18 20:33

**MOT test number**

770271707381

**Result****✓ Passed****MOT #13**

2018-11-13 09:53

**MOT test number**

429681284938

**Result****✓ Passed**

- Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear accident damage



<b>MOT #12</b>	2017-09-22 13:55
<b>MOT test number</b>	417971748284
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

<b>MOT #11</b>	2017-09-21 11:40
<b>MOT test number</b>	716023095100
<b>Result</b>	✗ Failed
<b>Advice</b>	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
<b>Fail</b>	Rear Exhaust has a major leak of exhaust gases (7.1.2)
<b>Fail</b>	Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)

<b>MOT #10</b>	2016-12-10 11:45
<b>MOT test number</b>	162288202838
<b>Result</b>	✓ Passed
<b>Advice</b>	Front tyres wearing on edges
<b>Advice</b>	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
<b>Advice</b>	Exhaust has a minor leak of exhaust gases rear box and front pipe (7.1.2)

<b>MOT #9</b>	2016-12-09 15:45
<b>MOT test number</b>	348089834971
<b>Result</b>	✗ Failed
<b>Advice</b>	Exhaust has a minor leak of exhaust gases rear box and front pipe (7.1.2)
<b>Advice</b>	Front tyres wearing on edges
<b>Advice</b>	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
<b>Fail</b>	Offside Front Shock absorber has a serious fluid leak (2.7.3)

**MOT #8** 2015-11-25 12:53**MOT test number** 250104248558**Result** ✓ Passed**Advice** N/s/r tyre wearing**Advice** Exhaust condition**MOT #7** 2015-11-24 17:27**MOT test number** 754872883871**Result** ✗ Failed**Fail** Offside Headlamp aim too high (1.8)**Fail** Horn not working (1.6.2a)**Advice** Exhaust condition**Fail** Nearside Headlamp aim too high (1.8)**Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** N/s/r tyre wearing**MOT #6** 2014-11-21 15:32**MOT test number** 975645824376**Result** ✓ Passed**MOT #5** 2014-11-21 14:51**MOT test number** 627055924325**Result** ✗ Failed**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)

**MOT #4** 2014-01-21 16:37**MOT test number** 666651724090**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2014-01-21 13:25**MOT test number** 537491024049**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #2** 2013-01-29 09:01**MOT test number** 695409423082**Result** ✓ Passed**MOT #1** 2012-10-18 14:45**MOT test number** 386172192476**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Wiper blades slightly smearing**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>WR59JXG</b>
Plate since	2019-03-28
Current registration	<b>WR59JXG</b>
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-11-09
Last registration	2022-08-08
Complete history	<a href="#">See info</a>



Registration #1	2009-11-09	21 mi
Registration #2	2012-10-18	35.244 mi
Registration #3	2013-01-29	37.377 mi
Registration #4	2014-01-21	48.086 mi
Registration #5	2014-01-21	48.090 mi
Registration #6	2014-11-21	56.979 mi
Registration #7	2014-11-21	56.979 mi
Registration #8	2015-11-24	67.480 mi
Registration #9	2015-11-25	67.481 mi
Registration #10	2016-12-09	85.055 mi
Registration #11	2016-12-10	85.055 mi
Registration #12	2016-12-10	85.055 mi
Registration #13	2016-12-10	85.055 mi
Registration #14	2016-12-10	85.055 mi
Registration #15	2016-12-10	85.055 mi
Registration #16	2016-12-10	85.055 mi
Registration #17	2016-12-10	85.055 mi
Registration #18	2016-12-10	85.055 mi
Registration #19	2016-12-10	85.055 mi
Registration #20	2016-12-10	85.055 mi
Registration #21	2016-12-10	85.055 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1702 mm
Height	1505 mm
Length	3620 mm
Wheel base	2300 mm
Kerb weight	940 kg
Max. allowed weight	1320 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	5187434