



report date: 2024-03-29

General information

Make	CITROEN
Model	DS4 HDI DSTYLE
Colour	Black
Year of manufacture	2012
Top speed	118 mph
0 - 60 mph	12.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	70.6 mpg
Consumption combined	60.1 mpg
CO2 emission	122 g/km
CO2 label	D





Internet history

Entry 1

Date	2022-01-15
Pictures	20
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-16
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	17
Total items failed	10

MOT #14 2024-01-12 11:50

MOT test number 621917417745

Result ✓ Passed

Next expiry date 2025-01-16

Advice Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

Advice Nearside Front Tyre slightly damaged had cut/damage to tyre wall inside and outside no cords showing (5.2.3 (d) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge around 2.5mm 225/45/18 (5.2.3 (e))

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #13 2024-01-12 11:50

MOT test number 272762982041

Result ✗ Failed

Pass with rectification Nearside Front Headlamp not working on dipped beam replaced bulb h7 (4.1.1 (a) (ii))

Advice Nearside Front Tyre slightly damaged had cut/damage to tyre wall inside and outside no cords showing (5.2.3 (d) (ii))

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge around 2.5mm 225/45/18 (5.2.3 (e))

Advice Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

**MOT #12** 2023-01-16 17:07**MOT test number** 719059142259**Result** ✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge worn low/bald on inside edge and also 2mm 225/45/18 (5.2.3 (e))

MOT #11 2023-01-11 16:52**MOT test number** 952778829618**Result** ✗ Failed

Fail Electronic parking brake control defective so that it cannot be satisfactorily operated switch insecure (1.1.6 (d))

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords 225/45/18 (5.2.3 (d) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge worn low/bald on inside edge and also 2mm 225/45/18 (5.2.3 (e))

Pass with rectification Offside Front Headlamp aim projected beam image is obviously incorrect bulb incorrectly fitted (4.1.2 (c))

MOT #10 2022-01-17 17:03**MOT test number** 580608211234**Result** ✓ Passed**MOT #9** 2021-05-20 09:26**MOT test number** 930230619883**Result** ✓ Passed

Advice Nearside Play in steering rack inner joint(s)

MOT #8 2020-05-22 15:28**MOT test number** 777160091376**Result** ✓ Passed

Advice Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

**MOT #7** 2020-05-22 15:28**MOT test number** 178344628155**Result** ✗ Failed**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Pass with rectification** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt insecure (6.1.7 (g) (ii))**MOT #6** 2020-03-14 15:13**MOT test number** 158162364965**Result** ✗ Failed**Fail** Nearside Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt insecure (6.1.7 (g) (ii))**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Front Brake disc worn, but not excessively both sides (1.1.14 (a) (i))**MOT #5** 2019-03-21 14:57**MOT test number** 773438061467**Result** ✓ Passed**Minor** Nearside Front Windscreen wiper blade defective (3.4 (b) (i))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #4** 2018-03-23 11:42**MOT test number** 799619815191**Result** ✓ Passed



MOT #3	2017-03-22 12:03
MOT test number	537445563938
Result	✓ Passed

MOT #2	2016-01-23 12:36
MOT test number	325996383987
Result	✓ Passed

MOT #1	2015-02-12 12:09
MOT test number	376793145098
Result	✓ Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
16 January 2025

Tax status	Valid until 1 October
Days left	154
MOT expiry date	16 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	MA12ULX
Plate since	2019-03-29
Current registration	MA12ULX
Plate since	2019-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-03-26
Last registration	2024-01-12
Complete history	See info



Registration #1	2012-03-26	23 mi
Registration #2	2015-02-12	12.961 mi
Registration #3	2016-01-23	19.756 mi
Registration #4	2017-03-22	28.046 mi
Registration #5	2018-03-23	34.583 mi
Registration #6	2019-03-21	39.355 mi
Registration #7	2020-03-14	44.134 mi
Registration #8	2020-05-22	44.232 mi
Registration #9	2020-05-22	44.232 mi
Registration #10	2020-05-22	44.232 mi
Registration #11	2020-05-22	44.232 mi
Registration #12	2020-05-22	44.232 mi
Registration #13	2020-05-22	44.232 mi
Registration #14	2020-05-22	44.232 mi
Registration #15	2020-05-22	44.232 mi
Registration #16	2020-05-22	44.232 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	80%
Pedestrian	43%
Safety systems	97%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1523 mm
Length	4275 mm
Wheel base	2612 mm
Kerb weight	1320 kg
Max. allowed weight	1805 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JBET3020007