






report date: 2024-03-29

General information

Make	FORD
Model	B-MAX ZETEC
Colour	Silver
Year of manufacture	2013
Top speed	112 mph
0 - 100 km/h	12.1 seconds
0 - 60 mph	12.1 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	77 kW / 105 HP / 104 BHP
Max. torque	150 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	55.4 mpg
Consumption combined	44.1 mpg
CO2 emission	149 g/km
CO2 label	F



CarCheck.co.uk page 1/11



Internet history

Entry	1
-------	---

Liiti y I	
Date	2021-08-19
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2025-02-05
MOT pass rate	90 %
MOT passed	9
Failed MOT tests	1
Total advice items	11
Total items failed	0

MOT #10	2024-02-06 11:26
MOT test number	553954901540
Result	✓ Passed
Next expiry date	2025-02-05
Advice Rear Coil spring corroded Both sides (5.3.1 (b) (i))	

MOT #9	2024-02-05 16:01
MOT test number	192408981486
Result	X Failed
Advice Rear Coil spring corroded Both sides (5.3.1 (b) (i))	
DANGEROUS Stop lamp(s) all not working (4.3.1 (a) (iii))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
DANGEROUS Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	

MOT #8	2023-01-05 13:04
MOT test number	848685678167
Result	✓ Passed
MOT #7	2022-07-20 09:17
MOT test number	695320045293
Result	✓ Passed

CarCheck.co.uk page 3/11



MOT #6 2021-09-03 15:08

MOT test number 237172689449

Result ✓ Passed

MOT #5 2020-09-15 09:04

MOT test number 788887786072

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #4 2019-09-20 10:07

MOT test number 777253974289

Result \rightarrow Passed

Advice Offside Rear Coil spring top mount deteriorated

MOT #3 2018-09-19 11:38

MOT test number 145567703754

Advice Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

Advice Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

MOT #2 2017-09-27 10:23

MOT test number 174477048400

Result ✓ Passed

Advice Right front seat belt has slight damage (worn) on it

MOT #1 2016-09-28 15:03

MOT test number 218388724687

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 February
Days left	278
MOT expiry date	5 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-


CarCheck.co.uk page 5/11



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report if	
THE STATE OF THE S	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-09-30
Last registration	2024-02-06
Complete history	See info



Registration #1	2013-09-30	11 mi
Registration #2	2016-09-28	38.435 mi
Registration #3	2017-09-27	50.877 mi
Registration #4	2018-09-19	60.968 mi
Registration #5	2019-09-20	70.691 mi
Registration #6	2020-09-15	75.231 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		9.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	92%
Children	84%
Pedestrian	67%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	2067 mm
Height	1604 mm
Length	4077 mm
Wheel base	2489 mm
Kerb weight	1208 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	48 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles CarCheck.co.uk	2 page 11/11

Engine number

CT29076