





report date: 2024-03-29

### General information

Make	PEUGEOT
Model	107 ACTIVE
Colour	Silver
Year of manufacture	2014
Top speed	99 mph
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	68 BHP
Max. torque	93 Nm at 3.600 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	55.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	A



CarCheck.co.uk page 1/11



LM14WVX

report date: 2024-03-29

### Internet history

### Entry 2

Date 2021-09-17

Pictures 5

Listing price <u>View report</u>









source: autotrader.co.uk

#### Entry 1

 Date
 2021-09-03

 Pictures
 5

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-09-16
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	5
Total items failed	2

MOT #10	2023-09-13 14:02
MOT test number	375332181694
Result	✓ Passed
Next expiry date	2024-09-16

MOT #9	2022-09-14 08:47
MOT test number	274703066245
Result	✓ Passed

MOT #8	2022-09-14 07:41
MOT test number	963802272016
Result	<b>X</b> Failed
Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))	

MOT #7		2021-09-17 16:29
MOT test	number	283272137225
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Exhaust system corroded at numerous points	
Advice	Front Coil spring corroded both sides (5.3.1 (b) (i))	

CarCheck.co.uk page 3/11



MOT #6 2021-07-08 15:55

**MOT test number** 505907924900

**Advice** Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement bushes (5.3.4 (a) (i))

MOT #5 2021-07-08 15:55

**MOT test number** 216175413677

Result X Failed

Pass with rectification Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement bushes (5.3.4 (a) (i))

**MOT #4** 2020-07-10 12:49

**MOT test number** 303010085628

Result 

Passed

MOT #3 2019-05-29 09:46

**MOT test number** 523726876196

**Result** ✓ Passed

MOT #2 2018-05-30 09:03

**MOT test number** 117769637733

MOT #1 2017-06-06 14:32

**MOT test number** 947671912008

**Result** ✓ Passed

CarCheck.co.uk page 4/11





Tax & MOT check



Tux Status	7 dill di 311111 2 0 010 10 01
Days left	155
MOT expiry date	16 September 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

LM14WVX

report date: 2024-03-29

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEU have? Check it in the premium report and see all owner registrations. Download the full report <a href="here">here</a> .	GEOT
THE STATE OF THE S	
**************	
**************************************	
***************	

### Plate changes

More info >

More info >

CarCheck.co.uk page 8/11



LM14WVX

report date: 2024-03-29

### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 


More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-07-21
Last registration	2023-09-13
Complete history	See info



Registration #1	2014-07-21	28 mi
Registration #2	2017-06-06	17.304 mi
Registration #3	2018-05-30	21.987 mi
Registration #4	2019-05-29	28.502 mi
Registration #5	2020-07-10	34.515 mi
Registration #6	2021-07-08	39.021 mi
Registration #7	2021-07-08	39.021 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		0.777 66

More info >

CarCheck.co.uk page 10/11



### Car features

S0225	Air conditioning
S0295	
50482	
50501	
S0566	
50567	
50569	

# Safety ratings

NCAP rating	***
Adult	68%
Children	73%
Pedestrian	53%
Safety systems	71%
Overall rating	66%
Video	see crash video



# Dimensions & weight

Width	1630 mm
Height	1465 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	905 kg
Max. allowed weight	1190 kg

# Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	4 page 11/11

Number of axles 2

Engine number 7616689