



report date: 2024-03-28

General information

Make	MINI
Model	MINI (R60) COOPER D
Colour	Red
Year of manufacture	2011
Top speed	112 mph
0 - 60 mph	11.3 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	110 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	50.4 mpg
CO2 emission	149 g/km
CO2 label	F







Internet history

Entry 2

Date	2023-09-23
Pictures	42
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](#)

Entry 1

Date	2021-11-12
Pictures	1
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](#)



## MOT history

MOT expiry date	2025-04-28
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	9
Total items failed	8

MOT #13 2024-04-23 09:36

MOT test number 717458737449

Result ✓ Passed

Next expiry date 2025-04-28

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Offside Front brake heat shield insecure

**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge 205/60 r16 96w (5.2.3 (e))

MOT #12 2023-04-26 11:03

MOT test number 904592430060

Result ✓ Passed

MOT #11 2022-04-29 13:39

MOT test number 581051251385

Result ✓ Passed

MOT #10 2020-11-24 16:12

MOT test number 284425375688

Result ✓ Passed

**MOT #9** 2020-11-24 16:12**MOT test number** 818695453975**Result** ✗ Failed**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MOT #8** 2019-11-23 10:55**MOT test number** 195763124631**Result** ✓ Passed**Advice** Offside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))**MOT #7** 2018-11-22 11:30**MOT test number** 548708828161**Result** ✓ Passed**MOT #6** 2018-11-22 11:30**MOT test number** 668192289296**Result** ✗ Failed**Pass with rectification** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Pass with rectification** Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MOT #5** 2017-11-21 14:24**MOT test number** 291404324274**Result** ✓ Passed**MOT #4** 2016-11-25 17:22**MOT test number** 981472361294**Result** ✓ Passed

**MOT #3** 2016-11-21 14:54**MOT test number** 764040990023**Result** ✗ Failed**Fail** Offside Rear rear parking brake recording little or no effort cable snapped (3.7.B.6a)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Parking brake lever has no reserve travel (3.1.6b)**Fail** Offside Front Front position lamp(s) not working (1.1.A.3b)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**MOT #2** 2015-07-31 16:53**MOT test number** 738772215259**Result** ✓ Passed**MOT #1** 2014-10-02 10:29**MOT test number** 598515374232**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Under-trays fitted obscuring some underside components**Notice** Items removed from driver's view prior to test



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
28 April 2025

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	154
<b>MOT expiry date</b>	28 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	0
Current registration	 
Plate since	2024-03-28
Current registration	 
Plate since	2024-03-28

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-11-21
Last registration	2024-04-23
Complete history	<a href="#">See info</a>



Registration #1	2011-11-21	27 mi
Registration #2	2014-10-02	18.635 mi
Registration #3	2015-07-31	22.962 mi
Registration #4	2016-11-21	35.256 mi
Registration #5	2016-11-25	35.256 mi
Registration #6	2017-11-21	38.355 mi
Registration #7	2018-11-22	43.987 mi
Registration #8	2018-11-22	43.987 mi
Registration #9	2019-05-29	55.377 mi
Registration #10	2019-05-29	55.377 mi
Registration #11	2019-05-29	55.377 mi
Registration #12	2019-05-29	55.377 mi
Registration #13	2019-05-29	55.377 mi
Registration #14	2019-05-29	55.377 mi
Registration #15	2019-05-29	55.377 mi
Registration #16	2019-05-29	55.377 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4097 mm
Wheel base	2595 mm
Kerb weight	1335 kg
Max. allowed weight	1805 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	74337877