



PEUGEOT

**PNIEKG**

report date: 2024-03-29

General information

Make	PEUGEOT
Model	207 S
Colour	Black
Year of manufacture	2011
Top speed	104 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	72 BHP
Max. torque	118 Nm at 3.300 rpm
Engine capacity	1.360 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	56.5 mpg
Consumption combined	44.1 mpg
CO2 emission	145 g/km
CO2 label	F






Internet history

Entry 1

Date	2021-08-08
Pictures	11
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2025-03-06
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	33
Total items failed	10

MOT #17	2024-02-28 11:57
MOT test number	309585379203
Result	✓ Passed
Next expiry date	2025-03-06
Advice	Offside Front Wheel bearing has slight play (5.1.3 (a) (i))

MOT #16	2024-02-26 10:52
MOT test number	430324561608
Result	✗ Failed
Fail	Tailgate cannot be secured in the closed position (6.2.1 (e))
Fail	Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt Clip (6.1.7 (g) (ii))
Fail	Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Offside Front Wheel bearing has slight play (5.1.3 (a) (i))

MOT #15	2023-03-06 11:27
MOT test number	601728879242
Result	✓ Passed
Advice	Oil leak, but not excessive Sump (8.4.1 (a) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #14** 2022-03-07 18:34**MOT test number** 354410370557**Result** ✓ Passed**MOT #13** 2021-11-16 15:14**MOT test number** 416524674579**Result** ✓ Passed**MOT #12** 2021-01-29 14:45**MOT test number** 726530721885**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #11** 2021-01-29 09:20**MOT test number** 812337332512**Result** ✗ Failed**Advice** Nearside Front Valve stem slightly misaligned (5.2.3 (j))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm on both edges (5.2.3 (e))**Advice** Nearside Front Outer tyre edge worn**Fail** Central Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #10** 2020-01-25 13:39**MOT test number** 271958582094**Result** ✓ Passed**Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #9**

2020-01-25 13:39

**MOT test number**

698546194277

**Result****✗ Failed****Pass with rectification**

Registration plate lamp inoperative in the case of a single lamp or all lamps

(4.7.1 (b) (ii))

**Pass with rectification**

Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

**Pass with rectification**

Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

**Advice**

Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))

**Advice**

Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #8**

2019-01-25 12:13

**MOT test number**

990060176352

**Result****✓ Passed****Advice**

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice**

Oil leak from engine

**Minor**

Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources

(4.7.1 (b) (i))

**Advice**

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #7**

2019-01-25 12:13

**MOT test number**

844395861169

**Result****✗ Failed****Advice**

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice**

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Pass with rectification**

Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

**Advice**

Oil leak from engine

**Minor**

Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources

(4.7.1 (b) (i))

**MOT #6** 2018-01-26 10:28**MOT test number** 236283769071**Result** ✓ Passed**Advice** Nearside Rear Tyre side wall cracking**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Oil leak Minor**MOT #5** 2017-01-20 14:20**MOT test number** 589928126299**Result** ✓ Passed**MOT #4** 2016-01-06 15:07**MOT test number** 183506470833**Result** ✓ Passed**Advice** Exhaust bracket insecure but still supported**Advice** Nearside front tyre worn on outer edge**Advice** Nearside rear tyre perished**MOT #3** 2016-01-05 15:27**MOT test number** 201219532124**Result** ✗ Failed**Fail** Front brake excessively fluctuating both front (3.7.B.3)**Advice** Nearside rear tyre perished**Advice** Exhaust bracket insecure but still supported**Advice** Brake disc worn, pitted or scored, but not seriously weakened both front (3.5.1i)**Advice** Nearside front tyre worn on outer edge



MOT #2	2015-04-01 10:03
MOT test number	155271695081
Result	✓ Passed

MOT #1	2014-03-26 12:29
MOT test number	887355384023
Result	✓ Passed

- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Child seat fitted not allowing full inspection of adult belt



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 October 2024

✓  
**MOT**

**Expires:**  
6 March 2025

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	154
<b>MOT expiry date</b>	6 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2011-03-21
Last registration	2024-02-28
Complete history	<a href="#">See info</a>



Registration #1	2011-03-21	8 mi
Registration #2	2014-03-26	27.759 mi
Registration #3	2015-04-01	36.716 mi
Registration #4	2016-01-05	42.067 mi
Registration #5	2016-01-06	42.067 mi
Registration #6	2017-01-20	47.675 mi
Registration #7	2018-01-26	50.992 mi
Registration #8	2019-01-25	57.146 mi
Registration #9	2019-01-25	57.146 mi
Registration #10	2020-01-25	64.493 mi
Registration #11	2020-01-25	64.493 mi
Registration #12	2020-01-25	64.493 mi
Registration #13	2020-01-25	64.493 mi
Registration #14	2020-01-25	64.493 mi
Registration #15	2020-01-25	64.493 mi
Registration #16	2020-01-25	64.493 mi
Registration #17	2020-01-25	64.493 mi
Registration #18	2020-01-25	64.493 mi
Registration #19	2020-01-25	64.493 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1920 mm
Height	1502 mm
Length	4030 mm
Wheel base	2540 mm
Kerb weight	1214 kg
Max. allowed weight	1617 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	FSX46370397