





report date: 2024-03-29

General information

Make	KIA
Model	VENGA CRDI 2 ECODYNAMICS
Colour	Red
Year of manufacture	2010
Top speed	104 mph
0 - 60 mph	14.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	220 Nm at 1.750 rpm
Engine capacity	1.396 сс
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	70.6 mpg
Consumption combined	62.8 mpg
CO2 emission	117 g/km
CO2 label	С



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 1

Date 2021-02-01

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

MOT history

MOT expiry date	2025-02-09
MOT pass rate	92 %
MOT passed	12
Failed MOT tests	1
Total advice items	24
Total items failed	5

MOT #13	2024-01-30 12:49
MOT test number	235654969362
Result	✓ Passed
Next expiry date	2025-02-09
Advice Steering rack has slight free play detected at steering wheel (2.3 (a) (i))	

MOT #12	2023-01-27 12:59
MOT test	number 667586425979
Result	✓ Passed
Advice (a) (i))	Nearside Front Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4
Advice	Rear Coil spring corroded both (5.3.1 (b) (i))

MOT #11	2022-01-25 13:14
MOT test number	380495879898
Result	✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #10 2021-02-10 11:33

MOT test number 800018475047

Result ✓ Passed **Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i)) Advice Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i)) Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice Oil leak, but not excessive (8.4.1 (a) (i)) Offside Rear Coil spring corroded (5.3.1 (b) (i)) Advice Advice Offside Front Inner Road wheel slightly distorted (5.2.2 (c) (i)) Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #9 2021-02-09 16:34 **MOT** test number 619874287897 Result **X** Failed Fail Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i)) Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii)) **Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) **Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i)) Fail Nearside Front Track rod end ball joint worn to the extent there is a serious risk of detachment (2.1.3 (b) (ii)) Fail Offside Front Service brake excessively fluctuating (1.2.1 (e)) **Advice** Offside Front Inner Road wheel slightly distorted (5.2.2 (c) (i)) Fail Electronic stability control warning lamp indicates a fault (7.12 (e)) **Advice** Oil leak, but not excessive (8.4.1 (a) (i)) **Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Offside Rear Coil spring corroded (5.3.1 (b) (i)) Advice **Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))

MOT #8	2020-03-27 10:38
MOT test number	175609451895
Result	✓ Passed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #7	2019-03-26 14:31
MOT test number	206441417252
Result	✓ Passed

CarCheck.co.uk page 5/13



Result

MF60LMX

report date: 2024-03-29

✓ Passed

MOT #6		2018-03-26 11:33
MOT test r	umber	963235436711
Result		✓ Passed
MOT #5		2017-03-29 11:59
MOT test r	number	447097389481
Result		✓ Passed
MOT #4		2016-03-23 08:54
MOT test r	number	225457262618
Result		✓ Passed
MOT #3		2015-06-04 10:42
MOT test r	umber	998895355188
Result		✓ Passed
Notice	Under-trays fitted obscuring some underside components	
Notice	Vehicle's internal headlight adjuster altered to recheck lights	
Advice	Offside Rear coil spring corroded (2.4.C.1b)	
Notice	Brake pedal rubber worn through on edge.	
Notice	Engine covers fitted obscuring some components in the engine bay	
MOT #2		2014-06-05 15:19
MOT test r	number	456666654116

MOT #1	2013-08-07 16:43
MOT test number	645879313235
Result	✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 June
Days left	32
MOT expiry date	9 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did Check it in the premium report and see all owner registrations. Download the full report I	

	More info >
Plate changes	
See in this check if this KIA had different number plates.	
Number of plates	
Current registration	OK SIE
Plate since	
Current registration	OK STE
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-09-01
Last registration	2024-01-30
Complete history	See info



Registration #1	2010-09-01	15 mi
Registration #2	2013-08-07	33.242 mi
Registration #3	2014-06-05	42.438 mi
Registration #4	2015-06-04	54.023 mi
Registration #5	2016-03-23	60.298 mi
Registration #6	2017-03-29	75.109 mi
Registration #7	2018-03-26	88.251 mi
Registration #8	2019-03-26	101.111 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		11.777 es
Registration #13		
Registration # 25		11.777-46
Registration #14		1.77 m

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Adult	79%
Children	66%
Pedestrian	64%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1765 mm
Height	1600 mm
Length	4068 mm
Wheel base	2615 mm
Kerb weight	1370 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	48 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/

Number of axles 2

Engine number D4FCAZ009526