



General information

Make	FORD
Model	FOCUS TITANIUM
Colour	Silver
Year of manufacture	2010
Top speed	112 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	149 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.2 mpg
CO2 emission	159 g/km
CO2 label	G





MOT history

MOT expiry date	2024-08-22
MOT pass rate	58 %
MOT passed	11
Failed MOT tests	8
Total advice items	68
Total items failed	3

MOT #19	2023-08-23 16:00
MOT test number	388500639552
Result	✓ Passed
Next expiry date	2024-08-22
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Offside Rear Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Front Inner tie rod has play
Advice	Nearside Rear Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Rear subframe and suspension components corroded

**MOT #18**

2023-08-22 14:18

MOT test number

405068781748

Result**✗ Failed****MAJOR** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Offside Rear Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Inner tie rod has play**MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Rear subframe and suspension components corroded



MOT #17

2023-08-05 14:10

MOT test number

489322754675

Result

✗ Failed

- MAJOR** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- MAJOR** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Nearside Front Body panel slightly loose front wing (6.2.1 (a) (i))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- MAJOR** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- MAJOR** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Rear subframe and suspension arms corroded
- Advice** Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Minor** Offside Front Lower Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Offside Front Body panel slightly loose wing (6.2.1 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge 2055017 (5.2.3 (e))
- MAJOR** Offside Front Subframe mounting prescribed area excessively damaged significantly reducing structural strength (5.3.6 (a) (i))

MOT #16

2022-07-15 08:58

MOT test number

746846845419

Result

✓ Passed

- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #15**

2022-07-14 11:17

MOT test number

147379772838

Result**✗ Failed****MAJOR** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**DANGEROUS** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**MAJOR** Battery insecure and likely to cause a short circuit (4.13 (a) (ii))**Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MAJOR** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Battery insecure and likely to fall from carrier (4.13 (a) (ii))**MOT #14**

2021-07-22 14:21

MOT test number

607608656103

Result**✓ Passed****Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #13**

2021-07-22 08:43

MOT test number

463497338702

Result**✗ Failed****MAJOR** Nearside Rear Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #12**

2020-04-06 11:56

MOT test number

921279704577

Result**✓ Passed****Advice** Offside Rear Child seat fitted, seatbelt not checked**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #11**

2019-03-23 09:28

MOT test number

852007075275

Result**✓ Passed****Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Inner edge (5.2.3 (e))

**MOT #10** 2019-03-21 11:31**MOT test number** 950736133128**Result** ✗ Failed**MAJOR** Central Front Exhaust system insecure (6.1.2 (a))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Nearside Front Position lamp not working (4.2.1 (a))**MAJOR** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Inner edge (5.2.3 (e))**MOT #9** 2018-04-14 12:23**MOT test number** 909457542827**Result** ✓ Passed**MOT #8** 2018-04-14 08:41**MOT test number** 861194092514**Result** ✗ Failed**Fail** Offside Rear Anti-roll bar linkage insecure (2.4.G.1)

**MOT #7** 2017-04-05 14:49**MOT test number** 219083469073**Result** ✓ Passed**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)**Advice** Nearside Rear Tyre worn close to the legal limit 2.8mm (4.1.E.1)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)**Advice** Both front tyres 3mm aprox and wear on inner edges**MOT #6** 2017-04-05 13:03**MOT test number** 637992744779**Result** ✗ Failed**Fail** Front brake excessively fluctuating both (3.7.B.3)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)**Advice** Both front tyres 3mm aprox and wear on inner edges**Advice** Nearside Rear Tyre worn close to the legal limit 2.8mm (4.1.E.1)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)**MOT #5** 2016-04-21 12:37**MOT test number** 739213041130**Result** ✓ Passed**MOT #4** 2015-06-19 13:40**MOT test number** 286460075475**Result** ✓ Passed



MOT #3	2014-07-03 13:55
MOT test number	389774284152
Result	✓ Passed

MOT #2	2014-07-03 12:04
MOT test number	598424484185
Result	✗ Failed
<div>Fail</div> Front brake application uneven (3.7.B.2)	

MOT #1	2013-06-24 10:54
MOT test number	237335473188
Result	✓ Passed
<div>Advice</div> Offside Front Tyre worn close to the legal limit (4.1.E.1)	



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
22 August 2024

Tax status	Valid until 1 April
Days left	336
MOT expiry date	22 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2010-06-23
Last registration	2023-08-23
Complete history	See info



Registration #1	2010-06-23	22 mi
Registration #2	2013-06-24	25.159 mi
Registration #3	2014-07-03	39.065 mi
Registration #4	2014-07-03	39.067 mi
Registration #5	2015-06-19	46.090 mi
Registration #6	2016-04-21	51.556 mi
Registration #7	2017-04-05	67.330 mi
Registration #8	2017-04-05	67.330 mi
Registration #9	2018-04-14	70.762 mi
Registration #10	2018-04-14	70.762 mi
Registration #11	2019-04-23	70.762 mi
Registration #12	2019-04-23	70.762 mi
Registration #13	2019-04-23	70.762 mi
Registration #14	2019-04-23	70.762 mi
Registration #15	2019-04-23	70.762 mi
Registration #16	2019-04-23	70.762 mi
Registration #17	2019-04-23	70.762 mi
Registration #18	2019-04-23	70.762 mi
Registration #19	2019-04-23	70.762 mi
Registration #20	2019-04-23	70.762 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2019 mm
Height	1500 mm
Length	4337 mm
Wheel base	2640 mm
Kerb weight	1249 kg
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	AS14346