




report date: 2024-03-28

General information

Make	VOLVO
Model	V50 D3 SE LUX
Colour	Blue
Year of manufacture	-
Top speed	127 mph
0 - 60 mph	9.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	148 BHP
Max. torque	350 Nm at 2.750 rpm
Cylinders	5
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	61.4 mpg
Consumption combined	48.7 mpg





Internet history

Entry 1

Date	2021-02-06
Pictures	10
Listing price	View report



source: autoonline.co.uk



MOT history

MOT #14	2023-09-19 08:27
MOT test number	685408349676
Result	✓ Passed
Next expiry date	2024-09-26

MOT #13	2022-09-27 09:02
MOT test number	997998656060
Result	✓ Passed

MOT #12	2022-09-22 18:19
MOT test number	687242801206
Result	✗ Failed
Fail	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
Fail	Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #11	2021-07-06 09:59
MOT test number	400501143369
Result	✓ Passed

MOT #10	2021-02-05 14:37
MOT test number	784951893572
Result	✓ Passed
Advice	Engine cover fitted not allowing full inspection of some components

MOT #9	2021-02-01 14:55
MOT test number	374377935242
Result	✗ Failed
Advice	Engine cover fitted not allowing full inspection of some components
Fail	Rear Brake lever has insufficient reserve travel parking brake (1.1.2 (a))



MOT #8 2020-01-15 15:14

MOT test number 462469091429

Result ✓ Passed

MOT #7 2020-01-15 09:14

MOT test number 166890066691

Result ✗ Failed

Fail Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

Fail Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

MOT #6 2019-01-22 15:32

MOT test number 207096847430

Result ✓ Passed

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #5 2018-01-09 11:59

MOT test number 701315285284

Result ✓ Passed

Advice Offside Rear Tyre Low On Inner Tread

MOT #4 2017-01-18 12:28

MOT test number 644471701057

Result ✓ Passed

MOT #3 2016-01-22 11:40

MOT test number 532823388118

Result ✓ Passed

Advice Offside Front Lower Suspension arm synthetic bush deteriorated but not resulting in excessive movement swade bush (2.4.G.2)



MOT #2 2015-01-23 17:00

MOT test number 176433225067

Result ✓ Passed

MOT #1 2014-01-24 12:34

MOT test number 357054124038

Result ✓ Passed



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	EA60NTU
Plate since	2024-03-28
Current registration	EA60NTU
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled. If not, and you buy this VOLVO then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-01-28
Last registration	2023-09-19
Complete history	See info



Registration #1	2011-01-28	22 mi
Registration #2	2014-01-24	20.605 mi
Registration #3	2015-01-23	28.020 mi
Registration #4	2016-01-22	35.283 mi
Registration #5	2017-01-18	43.280 mi
Registration #6	2018-01-09	50.276 mi
Registration #7	2019-01-22	56.586 mi
Registration #8	2020-01-15	62.644 mi
Registration #9	2021-09-22	65.377 mi
Registration #10	2022-09-22	65.377 mi
Registration #11	2022-09-22	65.377 mi
Registration #12	2022-09-22	65.377 mi
Registration #13	2022-09-22	65.377 mi
Registration #14	2022-09-22	65.377 mi
Registration #15	2022-09-22	65.377 mi
Registration #16	2023-09-19	202.377 mi

[More info >](#)



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1561 kg
Max. allowed weight	2020 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

