





report date: 2024-03-29

## General information

Make	CITROEN
Model	DS3 PURETECH DSIGN
Colour	Red
Year of manufacture	2015
Top speed	108 mph
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	82 BHP
Max. torque	118 Nm at 2.750 rpm
Engine capacity	1.199 сс
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	104 g/km
CO2 label	В



CarCheck.co.uk page 1/12



## Internet history

#### Entry 2

Date 2022-02-22
Pictures 10

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 1

Date	2022-02-21
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-10-25
MOT pass rate	60 %
MOT passed	6
Failed MOT tests	4
Total advice items	10
Total items failed	7

MOT #10	2023-10-24 09:44
MOT test number	698784483210
Result	✓ Passed
Next expiry date	2024-10-25

MOT #9	2023-10-24 09:22
MOT test number	147897128917
Result	<b>X</b> Failed
Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	

MOT #8		2022-10-26 10:58
MOT test number		794195121706
Result		✓ Passed
MOT #7		2022-10-26 10:58
MOT test number		694911986078
Result		<b>X</b> Failed
Pass with rectification	Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Pass with rectification	Nearside Headlamp aim too low (4.1.2 (a))	

CarCheck.co.uk page 3/12



**MOT #6** 2021-10-13 11:59

**MOT test number** 557288426272

**Result** ✓ Passed

**Advice** Tyre pressure warning light on

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5 2020-11-19 12:53

MOT test number 255678077719

Advice Offside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge 2.5mm (5.2.3 (e))

**Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))

MOT #4 2020-11-18 16:35

**MOT test number** 584346699758

**Result** X Failed

Fail Windscreen wiper does not clear the windscreen effectively Both (3.4 (b) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))

Fail Nearside Headlamp aim projected beam image is obviously incorrect bulb incorrectly fitted (4.1.2 (c))

Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Advice Nearside Front Tyre worn close to legal limit/worn on edge 2.5mm (5.2.3 (e))

**Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))

MOT #3 2019-10-26 07:56

**MOT test number** 968024345137

CarCheck.co.uk page 4/12



Result

FY65KPL report date: 2024-03-29

✓ Passed

MOT #2 2019-10-25 16:05

**MOT test number** 812288940459

**Result** X Failed

Fail Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))

MOT #1 2018-09-08 08:18

**MOT test number** 534354130493

Advice Exhaust back box bracket broken off

CarCheck.co.uk page 5/12





## Tax & MOT check



Tax status	Valid until 1 February
Days left	277
MOT expiry date	25 October 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 6/12



#### Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



#### Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

Owner mistory	
For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full in	
manage and a second sec	
***************************************	
***************************************	
*********	
***************************************	
************	
	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	
Current registration	NK SIX
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 9/12



#### Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2015-09-24
Last registration	2023-10-24
Complete history	See info



Registration #1	2015-09-24	17 mi
Registration #2	2018-09-08	30.858 mi
Registration #3	2019-10-25	44.769 mi
Registration #4	2019-10-26	44.769 mi
Registration #5	2020-11-18	57.935 mi
Registration #6	2020-11-19	57.935 mi
Registration #7	2021-10-13	68.512 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		0.074

More info >

CarCheck.co.uk page 11/12



# Safety ratings

NCAP rating	****
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



# Dimensions & weight

Width	1708 mm
Height	1460 mm
Length	3948 mm
Wheel base	2464 mm
Kerb weight	1075 kg
Max. allowed weight	1496 kg

# Additional information

Fuel tank capacity	48 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	B2080357137

CarCheck.co.uk page 12/12