





report date: 2022-08-09

General information

Make	MASERATI
Model	GRAN TURISMO V8 AUTO V8
Colour	Grey
Year of manufacture	2010
Top speed	177 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	400 BHP
Max. torque	460 Nm at 4.750 rpm
Engine capacity	4.244 cc
Cylinders	8
Fuel type	Petrol
Consumption city	13.1 mpg
Consumption extra urban	28.2 mpg
Consumption combined	19.2 mpg
CO2 emission	330 g/km
CO2 label	М



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date	2021-02-01
Pictures	1
Listing price	View report



source: autoonline.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2025-01-14
MOT pass rate	93 %
MOT passed	13
Failed MOT tests	1
Total advice items	25
Total items failed	1

MOT #14		2024-01-15 10:25
MOT test	number	612147537309
Result		✓ Passed
Next expi	ry date	2025-01-14
Advice	Subframe mounting prescribed area is corroded but not considered excess	ive (5.3.6 (a) (i))
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Front Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))	

CarCheck.co.uk page 3/13



report date: 2022-08-09

MOT #13		2023-01-05 12:10
MOT test	number	892886691474
Result		✓ Passed
Advice	Rear Vehicle structure is corroded but structural rigidity is not significantly reduce	ed (6.1.1 (c) (i))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Nearside Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
Advice	Nearside Rear exhaust clamp broken causing small exhaust gas leak	
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	

MOT #12	2022-01-05 15:39
MOT test number	692927753011
Result	✓ Passed
MOT #11	2020-12-24 12:37
MOT test number	795941097270

MOI #I	1	2020-12-24 12:37
MOT tes	t number	795941097270
Result		✓ Passed
Minor	Front Windscreen wiper blade defective (3.4 (b) (i))	
Advice	Nearside Play in steering rack inner joint(s)	
Advice	Front Upper Suspension arm pin or bush worn but not resulting in excessive	movement (5.3.4 (a)
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))	

CarCheck.co.uk page 4/13



report date: 2022-08-09

MOT #10		2020-01-07 11:15
MOT test	number	816570389737
Result		✓ Passed
Advice	Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3	3 (d) (i))
Advice	Offside Front Road wheel slightly distorted (5.2.2 (c) (i))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))	
Advice (6.1.1 (c)	Nearside Rear Vehicle structure is corroded but structural rigidity is not significa	ntly reduced
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2	2.3 (d) (i))
Advice	Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e)))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice (c) (i))	Offside Rear Vehicle structure is corroded but structural rigidity is not significant	tly reduced (6.1.1

MOT #9	2019-01-05 15:32
MOT test number	275055914680
Result	✓ Passed
MOT #8	2018-07-19 12:05
MOT test number	179569749401
Result	✓ Passed
MOT #7	2017-06-26 12:19
MOT test number	595243432795
Result	✓ Passed
MOT #6	2016-07-12 11:50
MOT test number	106625033895
Result	✓ Passed

CarCheck.co.uk page 5/13



report date: 2022-08-09

MOT test number 335933005270

Result
✓ Passed

MOT #4 2014-07-31 15:42

MOT test number 615702814211

Result

Passed

MOT #3 2014-05-24 08:37

MOT test number 925974744120

Result
✓ Passed

MOT #2 2014-05-10 09:52

MOT test number 465820434172

Result X Failed

Fail Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

MOT #1 2013-05-17 09:48

MOT test number 246547433190

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 January
Days left	278
MOT expiry date	14 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	M
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-

CarCheck.co.uk page 7/13




report date: 2022-08-09

Damage history

Check the damage history for this MASERATI. See if, where and when this MASERATI had damage and the car repair costs. We also check if this MASERATI was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra MASERATI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2022-08-09

Vehicle valuation

What is this car worth? See the vehicle value of this MASERATI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2022-08-09

More info >

Owner history

· · · · · · · · · · · · · · · · · · ·	
For how long did the current and previous owner(s) have this MASERATI? How many own MASERATI have? Check it in the premium report and see all owner registrations. Downloa here.	

	More info >
Plate changes	
See in this check if this MASERATI had different number plates.	
Number of plates	,
Current registration	NK NA
Plate since	
Current registration	NK SIN
Plate since	

CarCheck.co.uk page 10/13



Finance check

Check if this MASERATI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MASERATI has been settled.

If not, and you buy this MASERATI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MASERATI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2022-08-09

Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-06-01
Last registration	2024-01-15
Complete history	See info



Registration #1	2010-06-01	20 mi
Registration #2	2013-05-17	9.611 mi
Registration #3	2014-05-10	12.438 mi
Registration #4	2014-05-24	12.438 mi
Registration #5	2014-07-31	13.317 mi
Registration #6	2015-07-22	22.558 mi
Registration #7	2016-07-12	32.139 mi
Registration #8	2017-06-26	40.083 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es

More info >

CarCheck.co.uk page 12/13



Dimensions & weight

Width	1915 mm
Height	1353 mm
Length	4881 mm
Wheel base	2942 mm
Kerb weight	1880 kg

Additional information

Fuel tank capacity	86 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	151771

CarCheck.co.uk page 13/13