



report date: 2024-03-28

General information

Make	VAUXHALL
Model	AGILA DESIGN
Colour	Silver
Year of manufacture	2009
Top speed	109 mph
0 - 60 mph	11.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	85 BHP
Max. torque	114 Nm at 4.400 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	40.9 mpg
Consumption extra urban	60.1 mpg
Consumption combined	51.4 mpg
CO2 emission	131 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-07-07
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-11-09
MOT pass rate	87 %
MOT passed	13
Failed MOT tests	2
Total advice items	24
Total items failed	5

MOT #15	2023-11-08 17:24
MOT test number	550429881846
Result	✓ Passed
Next expiry date	2024-11-09
Advice	Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #14	2022-10-25 13:52
MOT test number	847923730423
Result	✓ Passed
Advice	Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #13	2021-11-10 09:28
MOT test number	326021719461
Result	✓ Passed

**MOT #12** 2021-11-06 17:38**MOT test number** 197060618103**Result** ✗ Failed**Fail** Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Offside Front Upper Macpherson strut pin or bush excessively worn (5.3.4 (a) (i))**MOT #11** 2021-06-22 11:59**MOT test number** 524553428923**Result** ✓ Passed**MOT #10** 2020-07-20 10:48**MOT test number** 662964605956**Result** ✓ Passed**Advice** Offside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #9** 2019-07-05 11:31**MOT test number** 916371219652**Result** ✓ Passed**MOT #8** 2018-07-18 09:50**MOT test number** 719326498069**Result** ✓ Passed**Advice** Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #7** 2018-07-16 08:29**MOT test number** 177975883470**Result** ✗ Failed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))**Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Child Seat fitted not allowing full inspection of adult belt**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #6** 2017-07-13 08:29**MOT test number** 134650002391**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear tyre deteriorated.**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2016-07-11 13:59**MOT test number** 376933445866**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit worn on edges (4.1.E.1)**Advice** Nearside rear tyre outer wall deteriorated**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside front tyre outer wall deteriorated

**MOT #4** 2015-07-15 14:58**MOT test number** 429216795133**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Nearside front tyre wearing on edge**MOT #3** 2014-07-05 09:18**MOT test number** 215726984431**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #2** 2013-07-17 11:31**MOT test number** 269938693485**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #1** 2012-07-04 14:20**MOT test number** 925976582157**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
9 November 2024

Tax status	Valid until 1 November
Days left	185
MOT expiry date	9 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history


Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	LY09HCE
Plate since	2019-09-29
Current registration	LY09HCE
Plate since	2019-09-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-07-31
Last registration	2023-11-08
Complete history	See info



Registration #1	2009-07-31	25 mi
Registration #2	2012-07-04	14.075 mi
Registration #3	2013-07-17	17.300 mi
Registration #4	2014-07-05	21.023 mi
Registration #5	2015-07-15	26.264 mi
Registration #6	2016-07-11	31.170 mi
Registration #7	2017-07-13	35.414 mi
Registration #8	2018-07-16	40.485 mi
Registration #9	2018-07-18	40.527 mi
Registration #10	2019-07-19	45.577 mi
Registration #11	2020-07-20	50.627 mi
Registration #12	2021-07-21	55.677 mi
Registration #13	2022-07-22	60.727 mi
Registration #14	2023-07-23	65.777 mi
Registration #15	2024-07-24	70.827 mi
Registration #16	2025-07-25	75.877 mi
Registration #17	2026-07-26	80.927 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1932 mm
Height	1590 mm
Length	3740 mm
Wheel base	2360 mm
Max. allowed weight	1485 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	1096095