





report date: 2024-03-29

## General information

Make	FIAT
Model	500C S
Colour	White
Year of manufacture	2013
Top speed	99 mph
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 6.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	49.6 mpg
Consumption extra urban	65.7 mpg
Consumption combined	58.9 mpg
CO2 emission	113 g/km
CO2 label	С



CarCheck.co.uk page 1/12



report date: 2024-03-29

## Internet history

## Entry 2

Date 2021-09-11

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 1

Date	2021-09-10

Pictures 14

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

# MOT history

MOT expiry date	2024-11-23
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	18
Total items failed	3

MOT #11		2023-11-20 16:10
MOT test	number	179997484693
Result		✓ Passed
Next expi	ry date	2024-11-23
Advice	Rear Coil spring corroded both (5.3.1 (b) (i))	
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Nearside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))	
Advice	Rear axle corroded	

MOT #10		2023-11-20 10:00
MOT test	number	356585131010
Result		<b>X</b> Failed
Advice	Rear axle corroded	
Advice	Rear Coil spring corroded both (5.3.1 (b) (i))	
Advice Offside Front Shock absorbers has light misting of oil (5.3.2 (b))		
Fail Registration plate lamp inoperative in the case of a single lamp or all lamps both (4.7.1 (b) (ii))		
Advice	Nearside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))	

CarCheck.co.uk page 3/12



report date: 2024-03-29

**MOT** #9 2022-11-10 09:41 559251061853 **MOT** test number Result ✓ Passed **Advice** Coil spring corroded both rear (5.3.1 (b) (i)) **Advice** Offside Front Shock absorbers has slight external damage to the casing corroded & misting through (5.3.2 (b)) Advice Exhaust has a minor leak of exhaust gases rear join & clamp missing (6.1.2 (a)) **Advice** Rear Axle corroded Advice Nearside Front Shock absorbers has slight external damage to the casing corroded (5.3.2 (b)) **Advice** Nearside Front Tyre worn close to legal limit/worn on edge & outer edge bald (5.2.3 (e))

**MOT #8** 2021-11-08 14:35 **MOT** test number 956386647149 Result ✓ Passed **MOT #7** 2021-11-08 14:35 **MOT** test number 785082406109 Result × Failed Pass with rectification Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) **Pass with rectification** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #6	2020-11-19 10:55
MOT test number	437674303436
Result	<b>✓</b> Passed

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #5		2019-11-11 10:09
MOT test	number	448642301945
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #4	2018-11-16 13:43
MOT test number	382670678924
Result	✓ Passed
MOT #3	2017-10-24 13:34
MOT test number	540302648828
Result	✓ Passed
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #2	2016-11-24 12:22
MOT test number	587115703007
Result	<b>✓</b> Passed
MOT #1	2016-05-04 14:26
MOT test number	793588738255
Result	./ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-29

## Tax & MOT check





Expires: 23 November 2024

Tax status	Valid until 1 November
Days left	186
MOT expiry date	23 November 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

## Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



FR13DNE report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

FR13DNE

report date: 2024-03-29

# For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report <a href="https://example.com/here">here</a>.

More info >

# Plate changes

See in this check if this FIAT had different number plates.

More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

## Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

# Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-05-31
Last registration	2023-11-20
Complete history	See info



Registration #1	2013-05-31	12 mi
Registration #2	2016-05-04	17.748 mi
Registration #3	2016-11-24	21.820 mi
Registration #4	2017-10-24	29.839 mi
Registration #5	2018-11-16	40.377 mi
Registration #6	2019-11-11	48.508 mi
Registration #7	2020-11-19	54.290 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 au

CarCheck.co.uk page 11/12



FR13DNE report date: 2024-03-29

Car features

50225	Air conditionin
50295	
50482	
60501	
60566	
60567	
60569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Kerb weight	865 kg
Max. allowed weight	1305 kg

# Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles 2
Engine number 0560529