




report date: 2025-02-13

General information

Make	VOLVO
Model	V50 D DRIVE SE LUX
Colour	Grey
Year of manufacture	2011
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	83.1 mpg
Consumption combined	72.4 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-02-06
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-04-26
MOT pass rate	59 %
MOT passed	10
Failed MOT tests	7
Total advice items	33
Total items failed	18

MOT #17 2024-04-03 16:28

MOT test number 548387629011

Result ✔ Passed

Next expiry date 2025-04-26

Advice Offside Front Tyre worn close to legal limit/worn on edge Worn inner edge (5.2.3 (e))

Advice Front Engine undertray insecure, may become damaged or detached when reversing.

Advice Nearside Front Tyre worn close to legal limit/worn on edge Worn inner edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge Worn inner edge (5.2.3 (e))

MOT #16 2024-04-03 12:21

MOT test number 652775755528

Result ✘ Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge Worn inner edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge Worn inner edge (5.2.3 (e))

Fail Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt Re-band required. (6.1.7 (g) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge Worn inner edge (5.2.3 (e))

Advice Front Engine undertray insecure, may become damaged or detached when reversing.



MOT #15	2023-04-19 16:33
MOT test number	614646255081
Result	✓ Passed
Advice	Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
Advice	Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))

MOT #14	2023-04-19 09:09
MOT test number	323655613619
Result	✗ Failed
Fail	Nearside Rear Anti-roll bar linkage fractured Broken/detached (5.3.3 (b) (ii))
Advice	Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge Very heavy wear on inner edge close to exposing cords. (5.2.3 (e))
Fail	Offside Front Service brake excessively binding (1.2.1 (f))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge Very heavy wear on inner edge close to exposing cords. (5.2.3 (e))
Advice	Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))

MOT #13	2022-04-26 16:48
MOT test number	859189795843
Result	✓ Passed
Advice	Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #12 2022-04-26 13:35

MOT test number 670624621862

Result ✗ Failed

Fail Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Rear Anti-roll bar linkage fractured (5.3.3 (b) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11 2021-04-27 12:04

MOT test number 156967985934

Result ✓ Passed

Advice Rear heatshield loose

Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Under tray fitted

Advice Offside Rear Tyre worn close to legal limit/worn on edge inside edge (5.2.3 (e))



MOT #10	2021-04-22 09:02
MOT test number	214683536664
Result	✗ Failed
Fail	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Rear heatshield loose
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge inside edge (5.2.3 (e))
Fail	Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Advice	Under tray fitted
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))

MOT #9	2020-01-13 10:17
MOT test number	168353604617
Result	✓ Passed

MOT #8	2019-01-15 12:22
MOT test number	585045433982
Result	✓ Passed
Advice	Light damage to offside door mirror cover



MOT #7	2019-01-10 11:01
MOT test number	200571275225
Result	✗ Failed
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
Advice	Light damage to offside door mirror cover
Advice	Offside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))
Fail	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
Fail	Offside Front Side repeater not working (4.4.1 (a) (ii))

MOT #6	2018-01-11 18:21
MOT test number	847397874089
Result	✓ Passed

MOT #5	2018-01-11 18:21
MOT test number	944036421485
Result	✗ Failed
Pass with rectification	Offside Rear Direction indicator incorrect colour (1.4.A.2f)
Pass with rectification	Nearside Rear Direction indicator incorrect colour (1.4.A.2f)

MOT #4	2016-12-29 14:35
MOT test number	670421273123
Result	✓ Passed

MOT #3	2016-01-12 16:56
MOT test number	443066879146
Result	✓ Passed



MOT #2 2016-01-12 11:59

MOT test number 800087815144

Result ✗ Failed

- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Nearside Front coil spring broken (2.4.C.1a)
- Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Nearside Rear Inner Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)
- Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

MOT #1 2014-11-28 11:35

MOT test number 439722334421

Result ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 February 2026

✓
MOT

Expires:
26 April 2025

Tax status Valid until 1 February

Days left 321

MOT expiry date 26 April 2025

Full MOT history [See MOT history](#)

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable




Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Due to strict data protection laws, we cannot and do not provide the personal details of a vehicle's owner. Download the full report [here](#).

Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	YJ13
Plate since	2019-09-29
Current registration	YJ13
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled. If not, and you buy this VOLVO then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2011-12-16
Last registration	2024-04-03
Complete history	See info



Registration #1	2011-12-16	24 mi
Registration #2	2014-11-28	36.107 mi
Registration #3	2016-01-12	48.353 mi
Registration #4	2016-01-12	48.353 mi
Registration #5	2016-12-29	59.404 mi
Registration #6	2018-01-11	69.179 mi
Registration #7	2018-01-11	69.179 mi
Registration #8	2019-01-10	79.296 mi
Registration #9	2019-01-15	79.313 mi
Registration #10	2020-01-13	89.329 mi
Registration #11	2020-01-13	89.329 mi
Registration #12	2020-01-13	89.329 mi
Registration #13	2020-01-13	89.329 mi
Registration #14	2020-01-13	89.329 mi
Registration #15	2020-01-13	89.329 mi
Registration #16	2020-01-13	89.329 mi
Registration #17	2020-01-13	89.329 mi
Registration #18	2020-01-13	89.329 mi
Registration #19	2020-01-13	89.329 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1437 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1760212