



report date: 2024-03-28

General information

| | |
|---------------------|------------------|
| Make | FORD |
| Model | S-MAX ZETEC TDCI |
| Colour | Black |
| Year of manufacture | 2007 |
| Top speed | 116 mph |
| 0 - 60 mph | 10.9 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 125 BHP |
| Max. torque | 285 Nm at 1.750 rpm |
| Engine capacity | 1.753 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 35.8 mpg |
| Consumption extra urban | 54.3 mpg |
| Consumption combined | 45.6 mpg |
| CO2 emission | 164 g/km |
| CO2 label | G |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-01-31 |
| Pictures | 1 |
| Listing price | View report |



source: autoonline.co.uk

**MOT history**

| | |
|---------------------------|------------|
| MOT expiry date | 2025-03-01 |
| MOT pass rate | 83 % |
| MOT passed | 15 |
| Failed MOT tests | 3 |
| Total advice items | 45 |
| Total items failed | 4 |

MOT #18 2024-03-02 09:45**MOT test number** 542505125124**Result** Passed**Next expiry date** 2025-03-01

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #17 2023-02-17 15:07**MOT test number** 890902262381**Result** Passed

- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))

**MOT #16**

2022-02-22 15:14

MOT test number

332934014876

Result

✓ Passed

- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #15

2022-02-22 11:11

MOT test number

424587411330

Result

✗ Failed

- Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
- Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- MAJOR** Offside Front Brake hose excessively damaged Insecure, has been rubbing on wheel (1.1.12 (b) (ii))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- MAJOR** Offside Front Tyre not fitted in accordance with side wall instructions Rotational tyre mounted wrong way round (5.2.3 (i))

MOT #14

2021-01-18 08:35

MOT test number

360235929520

Result

✓ Passed

**MOT #13** 2019-12-12 17:18**MOT test number** 539287712239**Result** ✓ Passed**MOT #12** 2018-12-27 10:16**MOT test number** 403323590311**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #11** 2018-12-27 10:16**MOT test number** 795980095855**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Pass with rectification** Central Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #10** 2017-12-27 09:28**MOT test number** 390653729417**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #9** 2016-12-30 10:49**MOT test number** 905226793036**Result** ✓ Passed**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #8** 2015-12-23 09:20**MOT test number** 942130164307**Result** ✓ Passed**MOT #7** 2014-12-15 09:43**MOT test number** 787139944376**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #6** 2013-12-31 10:42**MOT test number** 175745763326**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2013-03-28 16:03**MOT test number** 598087683097**Result** ✓ Passed**Advice** Inner Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Rear brake discs worn**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Front brake discs serverly worn

**MOT #4** 2013-03-27 16:23**MOT test number** 276866183063**Result** ✗ Failed**Notice** Front brake discs serverly worn**Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Advice** Inner Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Rear brake discs worn**Fail** Front registration plate deteriorated (6.3.1d)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2012-03-27 09:09**MOT test number** 906367782068**Result** ✓ Passed**MOT #2** 2011-10-24 14:49**MOT test number** 685247291200**Result** ✓ Passed**MOT #1** 2010-10-26 16:00**MOT test number** 643679690231**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
1 March 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 September |
| Days left | 126 |
| MOT expiry date | 1 March 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 49 |
| Band | G |
| Single payment (12 months) | £ 240,00,- |
| Single six month payment | £ 132,00,- |
| Total payable by 12 monthly instalments | £ 252,00,- |



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this FORD had different number plates.

| | |
|----------------------|---------------|
| Number of plates | 1 |
| Current registration | XXXXXX |
| Plate since | 2024-03-28 |
| Current registration | XXXXXX |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 20 |
| First mileage registration | 2007-11-12 |
| Last registration | 2024-03-02 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2007-11-12 | 11 mi |
| Registration #2 | 2010-10-26 | 23.870 mi |
| Registration #3 | 2011-10-24 | 32.187 mi |
| Registration #4 | 2012-03-27 | 32.606 mi |
| Registration #5 | 2013-03-27 | 50.504 mi |
| Registration #6 | 2013-03-28 | 50.520 mi |
| Registration #7 | 2013-12-31 | 59.211 mi |
| Registration #8 | 2014-12-15 | 64.952 mi |
| Registration #9 | 2015-12-23 | 70.657 mi |
| Registration #10 | 2016-12-30 | 75.661 mi |
| Registration #11 | 2019-05-29 | 95.377 mi |
| Registration #12 | 2019-05-29 | 95.377 mi |
| Registration #13 | 2019-05-29 | 95.377 mi |
| Registration #14 | 2019-05-29 | 95.377 mi |
| Registration #15 | 2019-05-29 | 95.377 mi |
| Registration #16 | 2019-05-29 | 95.377 mi |
| Registration #17 | 2019-05-29 | 95.377 mi |
| Registration #18 | 2019-05-29 | 95.377 mi |
| Registration #19 | 2019-05-29 | 95.377 mi |
| Registration #20 | 2019-05-29 | 95.377 mi |

More info >



Car features

The FORD factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1884 mm |
| Height | 1658 mm |
| Length | 4768 mm |
| Wheel base | 2850 mm |
| Kerb weight | 1736 kg |
| Max. allowed weight | 2505 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 70 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 7 |

| | |
|------------------------|---------|
| Number of axles | 2 |
| Engine number | 7Y38438 |