





report date: 2024-03-29

General information

Make	HYUNDAI
Model	I10 GO SE
Colour	White
Year of manufacture	2018
Top speed	96 mph
0 - 60 mph	14.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	65 BHP
Max. torque	95 Nm at 3.500 rpm
Engine capacity	998 сс
Cylinders	3
Fuel type	Petrol
Consumption city	47.1 mpg
Consumption extra urban	70.6 mpg
Consumption combined	60.1 mpg
CO2 emission	108 g/km
CO2 label	В



CarCheck.co.uk page 1/11



Internet history

Entry 2

Date 2021-07-18

Pictures 19

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2021-07-17

Pictures 19

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2025-01-24
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	13
Total items failed	0

MOT #5	2024-01-25 08:23
MOT test number	189713057373
Result	✓ Passed
Next expiry date	2025-01-24

MOT #4		2023-06-30 16:19
MOT test	number	581287441806
Result		✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Rear Service brake binding but not excessively (1.2.1 (f))	

CarCheck.co.uk page 3/11



MOT #3 2023-06-27 09:54

MOT test number 653556124515

Result X Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge also cut and perishing (5.2.3 (e))

Advice Rear Service brake binding but not excessively (1.2.1 (f))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge also perishing (5.2.3 (e))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MAJOR Nearside Front Daytime running lamp not working (4.2.1 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge also perishing (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge also perishing (5.2.3 (e))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #2 2022-06-29 08:12

MOT test number 811445767663

Result

Passed

Advice Nearside Front Tyre slightly damaged/cracking or perishing outer side wall damage (5.2.3 (d) (ii))

Advice Front to rear brake and fuel pipes covered by under trays

MOT #1 2021-03-17 12:04

MOT test number 692198398362

Result

Passed

CarCheck.co.uk page 4/11



Tax & MOT check



	<u> </u>
Tax status	Valid until 1 February
Days left	278
MOT expiry date	24 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
First licence fee (12 months)	£ 185,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-


CarCheck.co.uk page 5/11



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

e union mestery	
For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	

	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-03-31
Last registration	2024-01-25
Complete history	See info



Registration #1	2018-03-31	13 mi
Registration #2	2021-03-17	16.068 mi
Registration #3		11.777 es
Registration #4		11.777 es
Registration #5		D.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es

More info >

CarCheck.co.uk page 10/11




Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	79%
Children	80%
Pedestrian	71%
Safety systems	56%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1660 mm
Height	1500 mm
Length	3665 mm
Wheel base	2385 mm
Kerb weight	933 kg
Max. allowed weight	1420 kg

Additional information

Fuel tank capacity	40
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles 2

Engine number G3LAHM466722