





report date: 2024-03-28

General information

Make	ТОУОТА
Model	RAV-4 VVTI XTR
Colour	Silver
Year of manufacture	2007
Top speed	109 mph
0 - 60 mph	12.0 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	150 BHP
Max. torque	194 Nm at 4.000 rpm
Engine capacity	1.998 сс
Cylinders	4
Fuel type	Petrol
Consumption city	24.4 mpg
Consumption extra urban	38.2 mpg
Consumption combined	31.4 mpg
CO2 emission	212 g/km
CO2 label	K



CarCheck.co.uk page 1/13



Internet history

Entry	1

Life y 1	
Date	2021-08-04
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-12-18
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	17
Total items failed	4

MOT #17	2023-12-04 16:01
MOT test number	355602114582
Result	✓ Passed
Next expiry date	2024-12-18

MOT #16	2022-12-13 12:25
MOT test number	496228943768
Result	✓ Passed
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOI #15	2021-12-09 10:14
MOT test number	993219210330
Result	✓ Passed

MOT #14	2020-12-02 10:47
MOT test number	312332485533
Result	√ Passed

MOT #13	2019-05-27 09:58
MOT test number	711841792745
Result	✓ Passed
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	

CarCheck.co.uk page 3/13



MOT #12 2019-05-22 08:51

MOT test number 313069432777

Result X Failed

DANGEROUS Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #11 2018-05-30 12:14

MOT test number 801357019802

Result

Passed

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Coil spring corroded both side (5.3.1 (b) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10 2017-06-19 13:24

MOT test number 503546168147

Result

Passed

Advice Nearside Front tyre wearing low

Advice Nearside Rear Nail in tyre

MOT #9 2016-05-20 16:30

MOT test number 883374120064

Result J Passed

Advice Rear wiper split

CarCheck.co.uk page 4/13



MOT test number

Result

Fail Offside Registration plate lamp not working (1.1.C.1d)

Advice Rear wiper split

Fail Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice Os wiper split

MOT #7

MOT test number

Result

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #6 2014-05-21 14:19 **MOT** test number 287441544463 Result ✓ Passed **MOT** #5 2014-05-21 11:21 **MOT** test number 207901744107 Result × Failed Fail Offside Front position lamp(s) not working (1.1.A.3b) Fail Nearside Front position lamp(s) not working (1.1.A.3b)

MOT #4

MOT test number

676038163130

Result

✓ Passed

CarCheck.co.uk page 5/13



MOT #3		2012-02-27 09:43
MOT test	number	577128652029
Result		✓ Passed
Notice	Nail in nearside front tyre	
Notice	Nail in offside rear tyre	

MOT #2	2011-03-08 10:58
MOT test number	535417161090
Result	√ Passed
MOT #1	2010 02 00 10 20
MOT #1 MOT test number	2010-03-08 10:39 693467160042
Result	✓ Passed

CarCheck.co.uk page 6/13



Tax & MOT check



✓ MOT

Expires: 18 December 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	18 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Damage 2	
Date	
Category	
Туре	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

e mier metery	
For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full	
	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Current registration	NK NK
Flate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-03-12
Last registration	2023-12-04
Complete history	See info



Registration #1	2007-03-12	14 mi
Registration #2	2010-03-08	19.933 mi
Registration #3	2011-03-08	24.749 mi
Registration #4	2012-02-27	28.896 mi
Registration #5	2013-06-17	35.068 mi
Registration #6	2014-05-21	39.899 mi
Registration #7	2014-05-21	39.899 mi
Registration #8	2015-05-26	44.907 mi
Registration #9	2016-05-20	49.954 mi
Registration #10	2016-05-20	49.954 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		D.327 es
Registration #16		11.777 es
Registration #16 Registration #17		11,177 es
-		11,177 es 11,177 es 11,177 es

More info >

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1815 mm
Height	1720 mm
Length	4395 mm
Wheel base	2560 mm
Kerb weight	1560 kg
Max. allowed weight	2110 kg

Additional information

Fuel tank capacity	60 I	
Fuel delivery	Multi-Point Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 13/13

Engine number

1AZ5678590