



Mercedes-Benz

HJI4HHP


report date: 2024-03-29

General information

Make	MERCEDES-BENZ
Model	CLS CLS250 CDI BLUEEFFICIENCY AMG SPORT
Colour	Silver
Year of manufacture	2014
Top speed	146 mph
0 - 100 km/h	7.8 seconds
0 - 60 mph	7.8 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	150 kW / 204 HP / 201 BHP
Max. torque	500 Nm at 1.600 rpm
Engine capacity	2.143 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	60.1 mpg
Consumption combined	53.3 mpg
CO2 emission	143 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-07-31
Pictures	70
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT expiry date	2024-09-20
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	23
Total items failed	0

MOT #10	2023-09-21 11:07
MOT test number	979755253516
Result	✓ Passed
Next expiry date	2024-09-20

MOT #9	2022-08-05 09:03
MOT test number	449938093702
Result	✓ Passed

- Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Parking brake lever defective but can be satisfactorily operated (1.1.6 (d))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #8	2021-08-02 16:02
MOT test number	564461163705
Result	✓ Passed

**MOT #7** 2021-08-02 14:35**MOT test number** 103321087744**Result** ✗ Failed

- DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- DANGEROUS** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #6 2020-08-27 15:22**MOT test number** 803870745093**Result** ✓ Passed

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))

MOT #5 2020-08-27 14:16**MOT test number** 980825169060**Result** ✗ Failed

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))
- DANGEROUS** Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- DANGEROUS** Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MOT #4 2019-08-23 09:54**MOT test number** 651418828962**Result** ✓ Passed



MOT #3	2018-08-21 14:24
MOT test number	152078486487
Result	✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #2	2017-08-14 13:54
MOT test number	187959993413
Result	✓ Passed
Advice	Brake pad(s) wearing thin Front and rear (3.5.1g)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2016-08-15 12:20
MOT test number	876179835525
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
20 September 2024

Tax status	Valid until 1 July
Days left	62
MOT expiry date	20 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history


Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-29
Current registration	 XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-04-29
Last registration	2023-09-21
Complete history	See info



Registration #1	2014-04-29	18 mi
Registration #2	2016-08-15	19.885 mi
Registration #3	2017-08-14	44.480 mi
Registration #4	2018-08-21	65.076 mi
Registration #5	2019-08-23	84.267 mi
Registration #6	2020-08-27	101.018 mi
Registration #7	2021-09-29	121.277 mi
Registration #8	2022-09-29	141.537 mi
Registration #9	2023-09-29	161.797 mi
Registration #10	2024-09-29	182.057 mi
Registration #11	2025-09-29	202.317 mi
Registration #12	2026-09-29	222.577 mi

More info >



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	93%
Children	81%
Pedestrian	67%
Safety systems	86%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	2075 mm
Height	1416 mm
Length	4956 mm
Wheel base	2874 mm
Kerb weight	1865 kg
Max. allowed weight	2390 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	65192431955453