




report date: 2024-03-28

General information

Make	AUDI
Model	A4 TDI SE TECHNIK
Colour	White
Year of manufacture	2014
Top speed	130 mph
0 - 100 km/h	9.1 seconds
0 - 60 mph	9.1 seconds
Gearbox	8 speed CVT

Engine & fuel consumption

Power	110 kW / 150 HP / 141 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	64.2 mpg
Consumption combined	58.9 mpg
CO2 emission	127 g/km
CO2 label	D






Internet history

Entry 2

Date	2021-09-29
Pictures	30
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-09-28
Pictures	1
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-11-20
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	35
Total items failed	9

MOT #10	2023-11-21 09:14
MOT test number	265006022513
Result	✓ Passed
Next expiry date	2024-11-20
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #9**

2023-09-08 08:38

MOT test number

663445168526

Result**✗ Failed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Nearside Front Tyre has a tear, caused by separation or partial failure of its structure Inside wall (5.2.3 (d) (ii))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #8

2022-09-01 09:43

MOT test number

426130760434

Result**✓ Passed**

- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #7

2021-08-28 09:26

MOT test number

530059240752

Result**✓ Passed**

- Advice** Centre exhaust clamp corroded
- Advice** Nearside Rear Nail in tyre
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #6** 2020-09-05 08:37**MOT test number** 584768516572**Result** ✓ Passed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Centre exhaust clamp corroded**MOT #5** 2019-09-17 14:15**MOT test number** 723422019903**Result** ✓ Passed**MOT #4** 2018-05-24 12:22**MOT test number** 528068646627**Result** ✓ Passed**MOT #3** 2018-05-23 15:21**MOT test number** 881713187480**Result** ✗ Failed**Fail** Offside Side repeater not working (4.4.1 (a) (ii))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))



MOT #2

2017-05-17 13:21

MOT test number

375928263359

Result

✓ Passed

- Advice

Nearside Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)
- Advice

Rear Brake pad(s) wearing thin (3.5.1g)
- Advice

Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice

Offside Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)
- Advice

Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice

FRONT SIDE WINDOWS TINTED
- Advice

Windscreen has damage to an area less than a 40mm circle outside zone 'A' chip (8.3.1d)

**MOT #1**

2017-05-16 15:23

MOT test number

768714559376

Result**✗ Failed**

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)
- Fail** Rear registration plate insecure (6.3.1b)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** FRONT SIDE WINDOWS TINTED
- Fail** Registration plate fitted to the rear does not have black characters on a yellow background (6.3.2b)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Rear reflector not red in colour (1.5.1d)
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' chip (8.3.1d)
- Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)
- Fail** Nearside Rear Shock absorber has a serious fluid leak (2.7.3)
- Fail** Registration plate fitted to the front does not have black characters on a white background (6.3.2a)
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Nearside Rear reflector not red in colour (1.5.1d)




Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-28
Current registration	
Plate since	2019-09-28

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-07-01
Last registration	2023-11-21
Complete history	See info



Registration #1	2014-07-01	14 mi
Registration #2	2017-05-16	33.930 mi
Registration #3	2017-05-17	33.952 mi
Registration #4	2018-05-23	42.142 mi
Registration #5	2018-05-24	42.143 mi
Registration #6	2019-09-17	52.719 mi
Registration #7	2020-09-05	65.851 mi
Registration #8	2020-09-05	65.851 mi
Registration #9	2020-09-05	65.851 mi
Registration #10	2020-09-05	65.851 mi
Registration #11	2020-09-05	65.851 mi
Registration #12	2020-09-05	65.851 mi
Registration #13	2020-09-05	65.851 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	93%
Children	84%
Pedestrian	39%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	2040 mm
Height	1427 mm
Length	4701 mm
Wheel base	2808 mm
Kerb weight	1515 kg
Max. allowed weight	2065 kg

Additional information

Fuel tank capacity	63 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	CJCD270639