





report date: 2024-03-29

General information

| Make | VOLVO | |
|---------------------|-------------------------|--|
| Model | XC60 D4 INSCRIPTION AWD | |
| Colour | Black | |
| Year of manufacture | 2019 | |
| Top speed | 127 mph | |
| 0 - 60 mph | 8.3 seconds | |
| Gearbox | 8 speed automatic | |

Engine & fuel consumption

| Power | 190 BHP |
|----------------------|---------------------|
| Max. torque | 400 Nm at 2.500 rpm |
| Engine capacity | 1.969 сс |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption combined | 52.3 mpg |
| CO2 emission | 148 g/km |
| CO2 label | F |



CarCheck.co.uk page 1/11



Internet history

Entry 1

Date 2022-06-25

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/11



MOT history

| MOT expiry date | 2025-03-28 |
|--------------------|------------|
| MOT pass rate | 75 % |
| MOT passed | 3 |
| Failed MOT tests | 1 |
| Total advice items | 7 |
| Total items failed | 2 |

| MOT #4 | | 2024-03-08 09:06 |
|-----------|---|------------------|
| MOT test | number | 965036516261 |
| Result | | ✓ Passed |
| Next expi | ry date | 2025-03-28 |
| Advice | Front Brake disc worn, but not excessively both fronts (1.1.14 (a) (i)) | |
| Advice | Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |

| MOT #3 | 2024-03-06 15:16 |
|--|------------------|
| MOT test number | 642428064651 |
| Result | X Failed |
| Fail Nearside Rear Outer Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) | |
| Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Advice Front Brake disc worn, but not excessively both fronts (1.1.14 (a) (i)) | |
| Fail Offside Rear Outer Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) | |

| MOT #2 | 2023-03-06 14:46 |
|-----------------|------------------|
| MOT test number | 801957320126 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/11



MOT test number

Result

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/11



Tax & MOT check



| Tax status | Valid until 1 June |
|------------------|--------------------|
| Days left | 32 |
| MOT expiry date | 28 March 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|--|------------|
| Band | Н |
| First licence fee (12 months) | £ 255,00,- |
| First licence fee diesel non RDE2 tested (12 months) | £ 645,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

| Owner History | |
|--|-------------|
| For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively. | |
| | |
| ************************************** | |
| | |
| *************************************** | |
| | |
| manage of the same | |
| *************************************** | |
| *************************************** | |
| | |
| | More info > |
| | |
| Plate changes | |
| See in this check if this VOLVO had different number plates. | |
| | |
| Number of plates | |
| Current registration | NK SIX |
| Plate since | |
| Current registration | OR SILE |
| Plate since | |
| | More info > |
| | |

CarCheck.co.uk page 8/11



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 6 |
| First mileage registration | 2019-03-29 |
| Last registration | 2024-03-08 |
| Complete history | See info |



| Registration #1 | 2019-03-29 | 7 mi |
|-----------------|------------|-----------|
| Registration #2 | 2022-03-05 | 34.649 mi |
| Registration #3 | | 11,777 mi |
| Registration #4 | | 11,777 es |
| Registration #5 | | 71,777 66 |
| Registration #6 | | D.777 es |

More info >

CarCheck.co.uk page 10/11



Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| 50482 | |
| S0501 | |
| S0566 | |
| 50567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 98% |
| Children | 87% |
| Pedestrian | 76% |
| Safety systems | 95% |
| Overall rating | 90% |
| Video | see crash video |



Dimensions & weight

| Width | 2117 mm |
|---------------------|---------|
| Height | 1658 mm |
| Length | 4688 mm |
| Wheel base | 2865 mm |
| Max. allowed weight | 2450 kg |

Additional information

| Fuel tank capacity | 60 I |
|-----------------------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles CarCheck.co.uk | 2 page 11/11 |

Engine number

2993423