



report date: 2024-03-29

General information

Make	FIAT
Model	DOBLO 16V MULTIJET
Colour	White
Year of manufacture	2014
Top speed	102 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	290 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	52.3 mpg
CO2 emission	144 g/km
CO2 label	F





Internet history

Entry 1

Date	2022-01-13
Pictures	18
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2023-01-17
MOT pass rate	60 %
MOT passed	6
Failed MOT tests	4
Total advice items	14
Total items failed	2

MOT #10	2022-01-18 12:02
MOT test number	168208139334
Result	✓ Passed
Next expiry date	2023-01-17

MOT #9	2022-01-13 08:59
MOT test number	391588909617
Result	✗ Failed
MAJOR Brake lever has insufficient reserve travel (1.1.2 (a))	
DANGEROUS Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
MAJOR Parking brake efficiency below requirements (1.4.2 (a) (i))	
MAJOR Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))	
DANGEROUS Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice	Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

MOT #8	2021-01-04 15:51
MOT test number	897656556663
Result	✓ Passed

**MOT #7** 2020-01-07 16:55**MOT test number** 269565680216**Result** ✓ Passed**MOT #6** 2020-01-07 09:12**MOT test number** 773659089404**Result** ✗ Failed

MAJOR Offside Rear reflector defective or damaged by more than 50% of the reflecting surface (4.8.1 (a) (ii))

MOT #5 2018-12-19 10:47**MOT test number** 623497953011**Result** ✓ Passed

Advice Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #4 2018-12-18 11:52**MOT test number** 447553429780**Result** ✗ Failed

MAJOR Offside Front Headlamp aim too high (4.1.2 (a))

Advice Front day time running lights inop new bulbs fitted

MAJOR Nearside Front Headlamp aim not tested (4.1.2 (b))

MAJOR Offside Front Lower Coil spring fractured or broken (5.3.1 (b) (i))

Advice Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MAJOR Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #3 2017-12-29 13:29**MOT test number** 834621211000**Result** ✓ Passed



MOT #2	2017-12-29 13:29
MOT test number	896439989843
Result	✗ Failed
Pass with rectification	Offside Headlamp aim too low (1.8)
Pass with rectification	Nearside Headlamp aim too low (1.8)

MOT #1	2017-02-06 12:49
MOT test number	862950979441
Result	✓ Passed



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-03-01
Last registration	2022-01-18
Complete history	See info



Registration #1	2014-03-01	21 mi
Registration #2	2017-02-06	35.237 mi
Registration #3	2017-12-29	36.742 mi
Registration #4	2017-12-29	36.742 mi
Registration #5	2018-12-18	47.613 mi
Registration #6	2018-12-19	47.619 mi
Registration #7	2019-01-29	55.277 mi
Registration #8	2019-01-29	55.277 mi
Registration #9	2019-01-29	55.277 mi
Registration #10	2019-01-29	55.277 mi
Registration #11	2019-01-29	55.277 mi
Registration #12	2019-01-29	55.277 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

★★★★☆

Video

[see crash video](#)



Dimensions & weight

Width	1832 mm
Height	1880 mm
Length	4740 mm
Kerb weight	1445 kg
Max. allowed weight	2430 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2
Engine number	7091804