



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	COUPE SE
Colour	Blue
Year of manufacture	2005
Top speed	129 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	141 BHP
Max. torque	186 Nm at 4.500 rpm
Engine capacity	1.975 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.9 mpg
Consumption extra urban	44.1 mpg
Consumption combined	35.3 mpg
CO2 emission	193 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-06-25
Pictures	9
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-10-23
MOT pass rate	67 %
MOT passed	16
Failed MOT tests	8
Total advice items	55
Total items failed	16

MOT #24	2023-10-24 06:53
MOT test number	508102431693
Result	✓ Passed
Next expiry date	2024-10-23
Advice	Offside Front tyre tread cracking.

MOT #23	2023-10-10 10:25
MOT test number	279874911255
Result	✗ Failed
Fail	Windscreen washer not working (3.5 (a))
Fail	Offside Front Windscreen washer provides insufficient washer liquid (3.5 (a))
Fail	Offside Rear Brake pipe excessively corroded (1.1.11 (c))
Fail	Nearside Front Windscreen washer provides insufficient washer liquid (3.5 (a))
Advice	Offside Front tyre tread cracking.
Fail	Nearside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Fail	Exhaust has a major leak of exhaust gases middle/back. (6.1.2 (a))
Fail	Nearside Rear Parking brake inoperative on one side (1.4.1 (a))

**MOT #22** 2022-10-12 08:25**MOT test number** 697523436450**Result** ✓ Passed**MOT #21** 2021-10-04 11:32**MOT test number** 791885061005**Result** ✓ Passed

- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))
- Advice** Rear Brakes only just met efficiency
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing 215/45/17 (5.2.3 (d) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #20 2021-10-04 11:32**MOT test number** 332945230711**Result** ✗ Failed

- Advice** Nearside Front Tyre slightly damaged/cracking or perishing 215/45/17 (5.2.3 (d) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Rear Brakes only just met efficiency

**MOT #19** 2020-09-19 13:02**MOT test number** 391053011296**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #18** 2019-10-18 13:12**MOT test number** 706299599071**Result** ✓ Passed**Advice** Nearside Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))**MOT #17** 2019-10-10 16:15**MOT test number** 501930793519**Result** ✗ Failed**Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Advice** Nearside Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))**Fail** Exhaust has a major leak of exhaust gases (6.1.2 (a))**MOT #16** 2018-10-04 12:03**MOT test number** 481919029133**Result** ✓ Passed**MOT #15** 2018-10-04 12:03**MOT test number** 113034903970**Result** ✗ Failed**Pass with rectification** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

**MOT #14** 2017-09-28 16:31**MOT test number** 793642014637**Result** ✓ Passed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #13 2017-09-28 16:31**MOT test number** 569783344119**Result** ✗ Failed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)
- Pass with rectification** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #12 2016-10-10 16:04**MOT test number** 626445898211**Result** ✓ Passed

- Advice** Not able to see rear inner brake pad wear
- Advice** Rear Tyre worn close to the legal limit O/S,N/S (4.1.E.1)

**MOT #11** 2015-10-16 13:34**MOT test number** 361669875500**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Rear Tyre worn close to the legal limit O/S,N/S cracked (4.1.E.1)**Advice** Nearside Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #10** 2015-10-16 13:34**MOT test number** 423628521944**Result** ✗ Failed**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Rear Tyre worn close to the legal limit O/S,N/S cracked (4.1.E.1)**Advice** Nearside Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**MOT #9** 2014-10-17 14:01**MOT test number** 815410694215**Result** ✓ Passed**MOT #8** 2013-10-17 17:54**MOT test number** 339990993426**Result** ✓ Passed**Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**Notice** Not able to see rear inner brake pad wear.

**MOT #7** 2013-10-17 14:19**MOT test number** 926070193265**Result** ✗ Failed**Notice** Not able to see rear inner brake pad wear.**Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)**Fail** Exhaust has a major leak of exhaust gases (7.1.2)**Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**MOT #6** 2012-09-25 12:45**MOT test number** 159119662264**Result** ✓ Passed**MOT #5** 2011-10-08 09:13**MOT test number** 109581681236**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2010-10-09 13:16**MOT test number** 651682880297**Result** ✓ Passed**Advice** Offside Ball joint has slight play (2.2.B.1f)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Nail in offside rear tyre

**MOT #3** 2009-10-10 14:31**MOT test number** 313563789209**Result** ✓ Passed

- Notice** Nearside front wiperblade is splitting
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #2 2008-10-06 16:10**MOT test number** 662260388214**Result** ✓ Passed

- Advice** Nearside Rear brake disc slightly pitted (3.5.1h)
- Advice** Offside Rear brake disc slightly pitted (3.5.1h)
- Advice** Offside Front brake disc slightly pitted (3.5.1h)

MOT #1 2008-10-06 11:07**MOT test number** 104890388243**Result** ✗ Failed

- Advice** Offside Front brake disc slightly pitted (3.5.1h)
- Advice** Nearside Rear brake disc slightly pitted (3.5.1h)
- Fail** Nearside Front Steering rack gaiter insecure (2.2.D.2d)
- Advice** Offside Rear brake disc slightly pitted (3.5.1h)



Tax & MOT check

✓
Taxed
Tax due:
1 May 2024

✓
MOT
Expires:
23 October 2024

Tax status	Valid until 1 May
Days left	3
MOT expiry date	23 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	RV55VOT
Plate since	2019-03-28
Current registration	RV55VOT
Plate since	2019-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2005-10-13
Last registration	2023-10-24
Complete history	See info



Registration #1	2005-10-13	16 mi
Registration #2	2008-10-06	17.637 mi
Registration #3	2008-10-06	17.637 mi
Registration #4	2009-10-10	22.530 mi
Registration #5	2010-10-09	27.086 mi
Registration #6	2011-10-08	34.677 mi
Registration #7	2012-09-25	42.610 mi
Registration #8	2013-10-17	48.438 mi
Registration #9	2013-10-17	48.438 mi
Registration #10	2014-10-17	54.269 mi
Registration #11	2015-10-16	58.010 mi
Registration #12	2015-10-16	58.010 mi
Registration #13	2016-10-10	61.663 mi
Registration #14	2016-10-10	61.663 mi
Registration #15	2016-10-10	61.663 mi
Registration #16	2016-10-10	61.663 mi
Registration #17	2016-10-10	61.663 mi
Registration #18	2016-10-10	61.663 mi
Registration #19	2016-10-10	61.663 mi
Registration #20	2016-10-10	61.663 mi
Registration #21	2016-10-10	61.663 mi
Registration #22	2016-10-10	61.663 mi
Registration #23	2016-10-10	61.663 mi
Registration #24	2016-10-10	61.663 mi
Registration #25	2016-10-10	61.663 mi
Registration #26	2016-10-10	61.663 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1760 mm
Height	1330 mm
Length	4395 mm
Wheel base	2530 mm
Kerb weight	1382 kg
Max. allowed weight	1740 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	G4GC5381465