



Mercedes-Benz



report date: 2024-03-29

General information

Make	MERCEDES
Model	SLK SLK 200 KOMPRESSOR
Colour	Red
Year of manufacture	2008
Top speed	155 mph
Gearbox	7 speed automatic

Engine & fuel consumption

Power	184 BHP
Max. torque	250 Nm at 2.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	23.9 mpg
Consumption extra urban	45.6 mpg
Consumption combined	34.5 mpg
CO2 emission	192 g/km
CO2 label	J





Internet history

Entry 1	
Date	2021-10-11
Pictures	50
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-25
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	19
Total items failed	7

MOT #18 2023-10-26 10:15**MOT test number** 127413492490**Result** ✓ Passed**Next expiry date** 2024-10-25**Advice** Offside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))**MOT #17** 2023-10-19 13:36**MOT test number** 240240435697**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))**Fail** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**MOT #16** 2022-10-19 08:21**MOT test number** 883069214018**Result** ✓ Passed

**MOT #15** 2022-10-19 04:57**MOT test number** 911021775621**Result** ✗ Failed**Fail** Nearside Front Suspension arm ball joint likely to become detached (5.3.4 (a) (ii))**Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MOT #14** 2021-10-15 11:15**MOT test number** 780356797905**Result** ✓ Passed**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))**MOT #13** 2020-10-13 08:20**MOT test number** 853841250886**Result** ✓ Passed**Advice** Offside Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))**MOT #12** 2019-04-12 11:57**MOT test number** 459829561658**Result** ✓ Passed**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #11** 2019-04-12 11:57**MOT test number** 683037532610**Result** ✗ Failed**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Pass with rectification** Offside Driver's view of the road through the swept area of the windscreen materially affected by an obstruction (3.1 (a) (ii))

**MOT #10** 2018-04-20 12:59**MOT test number** 276708116383**Result** ✓ Passed**Advice** Front brake discs slightly worn**Advice** Front tyres slightly perished**MOT #9** 2018-04-19 08:36**MOT test number** 973383495355**Result** ✗ Failed**Fail** Nearside Side repeater not working (1.4.A.2c)**Advice** Front brake discs slightly worn**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Front tyres slightly perished**MOT #8** 2017-04-11 11:24**MOT test number** 382620185128**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2016-04-12 14:57**MOT test number** 916818851380**Result** ✓ Passed

**MOT #6** 2016-04-12 10:54**MOT test number** 561104343199**Result** ✗ Failed**Fail** Nearside Front coil spring broken (2.4.C.1a)**Fail** Offside Front coil spring broken (2.4.C.1a)**MOT #5** 2015-04-04 10:53**MOT test number** 478664795044**Result** ✓ Passed**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #4** 2014-03-06 08:38**MOT test number** 138065864445**Result** ✓ Passed**MOT #3** 2013-03-15 10:20**MOT test number** 136204173069**Result** ✓ Passed**MOT #2** 2012-03-30 13:57**MOT test number** 759710592070**Result** ✓ Passed**MOT #1** 2011-03-29 14:26**MOT test number** 428698181030**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
25 October 2024

Tax status	Valid until 1 February
Days left	278
MOT expiry date	25 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-




Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history


For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-29
Current registration	 XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-04-04
Last registration	2023-10-26
Complete history	See info



Registration #1	2008-04-04	10 mi
Registration #2	2011-03-29	9.769 mi
Registration #3	2012-03-30	11.072 mi
Registration #4	2013-03-15	12.688 mi
Registration #5	2014-03-06	14.203 mi
Registration #6	2015-04-04	15.177 mi
Registration #7	2016-04-12	16.434 mi
Registration #8	2016-04-12	16.434 mi
Registration #9	2017-04-11	17.793 mi
Registration #10	2018-04-19	18.617 mi
Registration #11	2019-05-20	19.377 mi
Registration #12	2019-05-20	19.377 mi
Registration #13	2019-05-20	19.377 mi
Registration #14	2019-05-20	19.377 mi
Registration #15	2019-05-20	19.377 mi
Registration #16	2019-05-20	19.377 mi
Registration #17	2019-05-20	19.377 mi
Registration #18	2019-05-20	19.377 mi
Registration #19	2019-05-20	19.377 mi
Registration #20	2019-05-20	19.377 mi

More info >



Dimensions & weight

Width	2012 mm
Height	1296 mm
Length	4103 mm
Wheel base	2430 mm
Kerb weight	1415 kg
Max. allowed weight	1705 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	27195431063736