



report date: 2024-03-28

General information

Make	CITROEN
Model	C3 PICASSO HDI VTR PLUS PICASSO
Colour	White
Year of manufacture	2014
Top speed	108 mph
0 - 60 mph	13.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	91 BHP
Max. torque	312 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	76.4 mpg
Consumption combined	68.9 mpg
CO2 emission	107 g/km
CO2 label	B






Internet history

Entry 1

Date	2021-10-27
Pictures	9
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-10-02
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	25
Total items failed	7

MOT #11	2023-09-21 08:26
MOT test number	427888912056
Result	✓ Passed
Next expiry date	2024-10-02

MOT #10	2022-10-03 13:25
MOT test number	415440198109
Result	✓ Passed
<b>Advice</b>	Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
<b>Minor</b>	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #9	2022-10-03 11:41
MOT test number	757929215157
Result	✗ Failed
<b>Fail</b>	Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
<b>Pass with rectification</b>	Offside Headlamp aim too low (4.1.2 (a))
<b>Advice</b>	Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
<b>Minor</b>	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #8** 2021-09-16 08:25**MOT test number** 562241108001**Result** ✓ Passed**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Exhaust mounting defective in front of rear box (6.1.2 (a))**Advice** Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))**MOT #7** 2020-09-22 15:26**MOT test number** 603681116015**Result** ✓ Passed**Advice** Exhaust mounting defective in front of rear box (6.1.2 (a))**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))**MOT #6** 2020-09-22 07:57**MOT test number** 226001644753**Result** ✗ Failed**Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Exhaust mounting defective in front of rear box (6.1.2 (a))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))**Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

**MOT #5**

2019-09-09 07:39

**MOT test number**

454653929724

**Result**

✓ Passed

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge O/S/R tyre wearing on inner edge (5.2.3 (e))

**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**Advice** Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Tyre worn close to legal limit/worn on edge Both front tyres wearing on inner edge (5.2.3 (e))

**MOT #4**

2019-09-09 07:39

**MOT test number**

950696815661

**Result**

✗ Failed

**Advice** Tyre worn close to legal limit/worn on edge Both front tyres wearing on inner edge (5.2.3 (e))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge O/S/R tyre wearing on inner edge (5.2.3 (e))

**Pass with rectification** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**Advice** Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #3**

2018-09-28 13:53

**MOT test number**

112443586965

**Result**

✓ Passed

**Advice** Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt



MOT #2	2018-09-27 13:22
MOT test number	124688982664
Result	✗ Failed
Fail	Horn not working (7.7 (a) (ii))
Advice	Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Fail	Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MOT #1	2017-09-28 07:43
MOT test number	790865192788
Result	✓ Passed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
2 October 2024

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	186
<b>MOT expiry date</b>	2 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	 
Plate since	2024-03-28
Current registration	 
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-09-30
Last registration	2023-09-21
Complete history	<a href="#">See info</a>



Registration #1	2014-09-30	7 mi
Registration #2	2017-09-28	33.479 mi
Registration #3	2018-09-27	44.805 mi
Registration #4	2018-09-28	44.888 mi
Registration #5	2019-09-09	55.412 mi
Registration #6	2019-09-09	55.412 mi
Registration #7	2020-09-22	61.691 mi
Registration #8	2020-09-22	61.691 mi
Registration #9	2020-09-22	61.691 mi
Registration #10	2020-09-22	61.691 mi
Registration #11	2020-09-22	61.691 mi
Registration #12	2020-09-22	61.691 mi
Registration #13	2020-09-22	61.691 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	83%
Children	74%
Pedestrian	33%
Safety systems	40%
Overall rating	67%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1766 mm
Height	1631 mm
Length	4078 mm
Wheel base	2540 mm
Kerb weight	1404 kg
Max. allowed weight	1779 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JBFM0120939