





report date: 2024-03-29

General information

Make	MAZDA
Model	RX-8 RX-8 231PS
Colour	Black
Year of manufacture	2006
Top speed	146 mph
0 - 60 mph	6.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	237 BHP
Max. torque	216 Nm at 6.000 rpm
Engine capacity	2.616 cc
Cylinders	2
Fuel type	Petrol
Consumption city	17.9 mpg
Consumption extra urban	31.7 mpg
Consumption combined	24.8 mpg
CO2 emission	284 g/km
CO2 label	М



CarCheck.co.uk page 1/15



report date: 2024-03-29

Internet history

Entry 1

Date 2021-08-25


Pictures 43

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/15



report date: 2024-03-29

MOT history	ΜO	Γh	nist	orv	
-------------	----	----	------	-----	--

MOT expiry date	2024-10-13
MOT pass rate	80 %
MOT passed	16
Failed MOT tests	4
Total advice items	32
Total items failed	9

MOT #20	2023-10-14 12:36
MOT test number	204734028503
Result	✓ Passed
Next expiry date	2024-10-13

MOT #19	2022-08-26 08:20
MOT test number	707578163662
Result	✓ Passed

MOT #18		2021-08-24 17:00
MOT test	number	966815851382
Result		✓ Passed
Advice	Suspension arm corroded but not seriously weakened front and rear (5.3.3 (b) (i))
Advice	Exhaust has a minor leak of exhaust gases plus corroded (6.1.2 (a))	
Advice	All brake discs worn and corroded	

CarCheck.co.uk page 3/15



report date: 2024-03-29

MOT #17 2021-08-21 15:02

MOT test number 447660051162

Result X Failed

Fail Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))

Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice All brake discs worn and corroded

Advice Suspension arm corroded but not seriously weakened front and rear (5.3.3 (b) (i))

Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Exhaust has a minor leak of exhaust gases plus corroded (6.1.2 (a))

MOT #16 2020-09-25 12:19

MOT test number 504071766956

Result

Passed

Advice Corrosion inner sills

Advice Offside Front Nail in tyre

Advice Rear brake pads worn low

Advice All suspension componants corroded

Advice Front and rear brake discs corroded

MOT #15 2019-09-20 12:42

MOT test number 636506193313

Result

Passed

Advice Corrosion various suspension components

CarCheck.co.uk page 4/15



report date: 2024-03-29

MOT #14	2018-09-15 08:26
MOT test number	328886749416
Result	✓ Passed
Advice Various suspension components corroded	

MOT #13	2017-09-25 12:01
MOT test number	206003759725
Result	✓ Passed
MOT #12	2016-09-20 11:43
MOT test number	904352195969
Result	✓ Passed
Advice Front tyres perished in tread	


MOT #11	2015-09-23 08:14
MOT test number	290460382228
Result	✓ Passed
Advice Front tyres perished in tread	

MOT #10		2014-05-20 12:49
MOT test	number	647580144168
Result		✓ Passed
Advice	Nearside front brake fluctuating, but not excessively (3.7.B.3)	
Notice	Condensation offside rear lamp unit	
Advice	Offside front brake fluctuating, but not excessively (3.7.B.3)	
Notice	Front tyres perished in tread	

CarCheck.co.uk page 5/15



report date: 2024-03-29



MOT #8		2013-04-12 15:34
MOT test	number	809892903174
Result		✓ Passed
Notice	Both front tyres have cracks within tread and deteriorated	
Notice	Under-trays fitted obscuring some underside components	
Notice	Front brake discs deteriorated and have surface corrosion	
Notice	Engine covers fitted obscuring some components in the engine bay	

CarCheck.co.uk page 6/15



report date: 2024-03-29

MOT #7		2013-04-12 12:13
MOT test	number	568552103113
Result		× Failed
Notice	Engine covers fitted obscuring some components in the engine bay	
Notice	Both front tyres have cracks within tread and deteriorated	
Notice	Under-trays fitted obscuring some underside components	
Fail Offside Front Anti-roll bar linkage severely distorted (2.4.G.1)		
Notice	Front brake discs deteriorated and have surface corrosion	

MOT #6		2012-04-03 10:20
MOT test number		368524892023
Result		✓ Passed
MOT #5		2011-08-18 11:56
MOT test number		716240331241
Result		× Failed
Pass with rectification	Centre Stop lamp not working (1.2.1b)	
Pass with rectification	Front registration plate missing (6.3.1a)	

rass with rectification	Tront registration plate missing (0.5.1a)
MOT #4	2011-08-18 11:56
MOT test number	318980831212
Result	✓ Passed
MOT #3	2010-09-04 14:59
MOT test number	464907440204
Result	✓ Passed

CarCheck.co.uk page 7/15



report date: 2024-03-29

MOT #2	2009-08-27 09:52
MOT test number	734299139214
Result	✓ Passed
MOT #1	2009-03-20 12:44
MOT test number	361749979003
Result	✓ Passed
Notice Child seat fitted not allowing full inspection of adult belt	

CarCheck.co.uk page 8/15



report date: 2024-03-29

Tax & MOT check





Expires: 13 October 2024

Tax status	Expired at 1 October 2023
Days left	211 days too late
MOT expiry date	13 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 9/15



report date: 2024-03-29

Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 11/15



report date: 2024-03-29

Owner	history
-------	---------

For how long did the current and previous owner(s) have this MAZDA? How many owne have? Check it in the premium report and see all owner registrations. Download the ful	

	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	
Current registration	OK SIE
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 12/15



report date: 2024-03-29

Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 13/15



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-03-03
Last registration	2023-10-14
Complete history	See info



Registration #1	2006-03-03	29 mi
Registration #2	2009-03-20	27.186 mi
Registration #3	2009-08-27	29.332 mi
Registration #4	2010-09-04	33.868 mi
Registration #5	2011-08-18	38.322 mi
Registration #6	2012-04-03	40.093 mi
Registration #7	2013-04-12	43.588 mi
Registration #8	2013-04-12	43.588 mi
Registration #9	2014-05-20	45.196 mi
Registration #10	2014-05-20	45.196 mi
Registration #11	2015-09-23	46.487 mi
Registration #12		11.777 es
Registration #13		11.707 es
Registration #13 Registration #14		1.77 4
		11.77 mi 11.77 mi 11.77 mi
Registration #14		11.77 mi 11.77 mi 11.77 mi
Registration #14 Registration #15		11.777 ea 11.777 ea 11.777 ea 11.777 ea
Registration #14 Registration #15 Registration #16		11.777 ea 11.777 ea 11.777 ea 11.777 ea 11.777 ea
Registration #14 Registration #15 Registration #16 Registration #17		11,777 ea 11,777 ea 11,777 ea 11,777 ea 11,777 ea 11,777 ea
Registration #14 Registration #15 Registration #16 Registration #17 Registration #18		11,777 ea 11,777 ea 11,777 ea 11,777 ea 11,777 ea 11,777 ea

More info >

CarCheck.co.uk page 14/15



report date: 2024-03-29

Dimensions & weight

Width	1770 mm
Height	1340 mm
Length	4425 mm
Wheel base	2700 mm
Kerb weight	1350 kg
Max. allowed weight	1815 kg

Additional information

Fuel tank capacity	61
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	4
Number of axles	2
Engine number	13B 487479

CarCheck.co.uk page 15/15