





report date: 2024-03-28

General information

Make	CITROEN
Model	C4 BLUEHDI FLAIR
Colour	Silver
Year of manufacture	2016
Top speed	114 mph
0 - 60 mph	10.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	98 BHP
Max. torque	254 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	67.3 mpg
Consumption extra urban	85.6 mpg
Consumption combined	78.5 mpg
CO2 emission	95 g/km
CO2 label	A



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 6

Date 2021-12-09

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

Entry 5

Date	2021-12-03
Pictures	0
Listing price	View report

source: heycar.co.uk

Entry 4

Date	2021-10-14
Pictures	33

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 3

Date	2021-10-02
Pictures	1
Listing price	<u>View report</u>

CarCheck.co.uk page 2/12



source: autoonline.co.uk

Entry 2

Date	2021-10-02
Pictures	0
Listing price	View report

source: heycar.co.uk

Entry 1

Date	2021-10-01
Pictures	0
Listing price	View report

source: heycar.co.uk



report date: 2024-03-28

MOT history

MOT expiry date	2024-11-16
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	13
Total items failed	2

MOT #8		2023-11-11 12:03
MOT test no	umber	619514015532
Result		✓ Passed
Next expiry	y date	2024-11-16
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Rear Exhaust mounting defective (6.1.2 (a))	

MOT #7		2023-11-11 09:43
MOT test	number	532063844472
Result		≍ Failed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Rear Exhaust mounting defective (6.1.2 (a))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Fail Or of dirt (6.1	ffside Front Drive shaft joint constant velocity boot split or insecure, no longer (7 (g) (ii))	prevents the ingress

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #6 2022-10-26 08:55

MOT test number 384932013401

Result ✓ Passed

Advice Nearside Front Tyre slightly damaged/cracking or perishing outer wall damage (5.2.3 (d) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing perish outer tread to wall (5.2.3 (d) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing perish outer tread to wall (5.2.3 (d) (ii))

MOT #5 2021-11-17 14:54

MOT test number 917083624705

Result ✓ Passed

MOT #4 2021-05-21 12:38

MOT test number 755079607112

Advice Nearside Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #3 2021-05-21 12:38

MOT test number 412726052021

Result ★ Failed

Advice Nearside Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Pass with rectification

Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #2 2020-06-05 13:51

MOT test number 768486689442

Result ✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #1 2019-04-25 11:35

MOT test number 882438922837

Result ✓ Passed

CarCheck.co.uk page 5/12



SC16EWX report date: 2024-03-28

Tax & MOT check





Expires: 16 November 2024

Tax status	Valid until 1 January
Days left	247
MOT expiry date	16 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



SC16EWX report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



factor scincol

SC16EWX

report date: 2024-03-28

More info >

Owner history For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this CITROEN had different number plates.

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >


CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2016-04-29
Last registration	2023-11-11
Complete history	See info



Registration #1	2016-04-29	9 mi
Registration #2	2019-04-25	19.332 mi
Registration #3	2020-06-05	22.228 mi
Registration #4	2021-05-21	24.279 mi
Registration #5	2021-05-21	24.279 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		9.777 es
Registration #12		11.777 es
Registration #13		9.777 es
Registration #14		11.777 es
Registration #15		D.777 es

More info >

CarCheck.co.uk page 11/12



SC16EWX report date: 2024-03-28

Safety ratings

NCAP rating	****
Adult	90%
Children	85%
Pedestrian	43%
Safety systems	97%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1729 mm
Height	1480 mm
Length	4157 mm
Wheel base	2595 mm
Kerb weight	1068 kg
Max. allowed weight	1610 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JBHA0116115

CarCheck.co.uk page 12/12