





## General information

Make	VOLVO	
Model	V50 D DRIVE SE LUX	
Colour	Grey	
Year of manufacture	2010	
Top speed	118 mph	
0 - 60 mph	10.9 seconds	
Gearbox	5 speed Manual	

## Engine & fuel consumption

Power	109 BHP	
Max. torque	240 Nm at 1.750 rpm	
Engine capacity	1.560 cc	
Cylinders	4	
Fuel type	Diesel	
Consumption city	57.7 mpg	
Consumption extra urban	83.1 mpg	
Consumption combined	72.4 mpg	
CO2 emission	104 g/km	
CO2 label	В	







## Internet history

Entry 3	
Date	2023-01-11
Pictures	2
Listing price	View report

=AutoTrader

**Highly** Rated



source: cargurus.co.uk

### Entry 2

Date	2023-01-10
Pictures	2
Listing price	<u>View report</u>





#### source: autotrader.co.uk

## Entry 1

Date	2022-02-27
Pictures	47
Listing price	View report



source: cargurus.co.uk



# MOT history

MOT expiry date	2025-01-16
MOT pass rate	100 %
MOT passed	12
Failed MOT tests	0
Total advice items	8
Total items failed	0

MOT #12	2024-01-10 14:55
MOT test number	377188645098
Result	✓ Passed
Next expiry date	2025-01-16
Advice Offside Rear Tyre worn close to legal limit/worn on edge 205/50r17 (5.2.3 (e))	

MOT #11	2023-01-17 11:59
MOT test number	510303961176
Result	✓ Passed

MOT #10	2022-03-03 17:18
MOT test number	748358762996
Result	✓ Passed

МОТ #9	2021-07-29 10:38
MOT test number	926528344005
Result	✓ Passed

MOT #8	2020-07-10 14:00
MOT test number	548790047318
Result	🗸 Passed





MOT #7	2019-07-12 08:29
MOT test number	595160146881
Result	✓ Passed
MOT #6	2018-07-27 11:27
MOT test number	990197974566
Result	✓ Passed
MOT #5	2017-07-04 15:22
MOT test number	935220389429
Result	✓ Passed
MOT #4	2016-07-15 09:44
MOT test number	796396594734
Result	✓ Passed
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

2015-07-31 11:16
247262115251
✓ Passed

MOT #2	2014-07-29 13:06
MOT test number	459010014264
Result	✓ Passed
<b>Notice</b> Offside front tyre scrubbed on inner edge	





MOT #1		2013-08-02 15:12
MOT test	number	758964913242
Result		Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice	Nail in offside rear tyre	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	



KY60DYV report date: 2024-03-29

Tax & MOT check

✓ Taxed Tax due: 1 April 2025	✓ MOT Expires: 16 January 2025
Tax status	Valid until 1 April
Days left	337
MOT expiry date	16 January 2025
Full MOT history	See MOT history
Tax calculation	

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-





## Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	4 ARAPE
Туре	
Damage 2	AMPL
	F Stores
Date	1.E
Category	ante
Туре	

#### Extra VOLVO salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





## Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711





## Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and the second se	
**********	
********	
*******	
**********	
********	
	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	
	More info >





### Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-09-03
Last registration	2024-01-10
Complete history	See info



Registration #1	2010-09-03	25 mi
Registration #2	2013-08-02	12.030 mi
Registration #3	2014-07-29	26.146 mi
Registration #4	2015-07-31	41.128 mi
Registration #5	2016-07-15	57.634 mi
Registration #6	2017-07-04	75.928 mi
Registration #7	2018-07-27	85.007 mi
Registration #8	2019-07-12	90.893 mi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 esi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.277 est





## Car features

S0225	Air conditioning
\$0295	
50482	
S0501	
\$0566	
\$0567	
S0569	

# Safety ratings

**NCAP** rating

Video

see crash video



Dimensions & weight	
Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1437 kg
Max. allowed weight	1900 kg
Additional information	
Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles	2
Engine number	1260602