



WN59FVU

report date: 2024-03-29

General information

Make	FORD
Model	FUSION STYLE PLUS
Colour	Silver
Year of manufacture	2009
Top speed	103 mph
Gearbox	4 speed automatic

Engine & fuel consumption

Power	95 BHP
Max. torque	128 Nm at 4.200 rpm
Engine capacity	1.388 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	55.4 mpg
Consumption combined	43.5 mpg
CO2 emission	154 g/km
CO2 label	G





Internet history

Entry 1

Date	2022-02-18
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-13
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	28
Total items failed	6

MOT #16	2023-07-14 10:08
MOT test number	375509379336
Result	✓ Passed
Next expiry date	2024-07-13
Advice	Front Tyre worn close to legal limit/worn on edge both front tyres outer edge wearing (5.2.3 (e))
Advice	Underside surface corrosion rear end
Advice	Front Tyre worn close to legal limit/worn on edge both outer tread wearing (5.2.3 (e))

MOT #15	2023-07-14 09:48
MOT test number	325821094589
Result	✗ Failed
MAJOR	Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))
Advice	Front Tyre worn close to legal limit/worn on edge both outer tread wearing (5.2.3 (e))
MAJOR	Offside Stop lamp(s) not working (4.3.1 (a) (ii))
Advice	Underside surface corrosion rear end
Advice	Front Tyre worn close to legal limit/worn on edge both front tyres outer edge wearing (5.2.3 (e))
MAJOR	Offside Rear Position lamp not working (4.2.1 (a) (ii))

**MOT #14** 2022-07-08 14:48**MOT test number** 265077505672**Result** ✓ Passed**MOT #13** 2021-10-04 15:14**MOT test number** 323325037604**Result** ✓ Passed**Minor** Offside Headlamp reflector slightly defective (4.1.1 (b) (i))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Minor** Nearside Headlamp reflector slightly defective (4.1.1 (b) (i))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #12** 2020-10-01 13:03**MOT test number** 551939063256**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #11** 2019-10-01 17:00**MOT test number** 642215297013**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10** 2019-10-01 17:00**MOT test number** 141714631840**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**MOT #9** 2018-10-01 10:33**MOT test number** 788101229688**Result** ✓ Passed**MOT #8** 2018-10-01 10:33**MOT test number** 404963226653**Result** ✗ Failed**Pass with rectification** Central Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #7** 2017-09-25 08:20**MOT test number** 800783879280**Result** ✓ Passed**MOT #6** 2016-09-28 08:18**MOT test number** 592517611737**Result** ✓ Passed

**MOT #5** 2015-09-24 15:58**MOT test number** 972531200821**Result** ✓ Passed**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Offside Front Tyre worn close to the legal limit 3mm (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit 3mm (4.1.E.1)**MOT #4** 2015-09-24 15:58**MOT test number** 130774922788**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Front Tyre worn close to the legal limit 3mm (4.1.E.1)**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Offside Front Tyre worn close to the legal limit 3mm (4.1.E.1)**MOT #3** 2014-09-23 15:07**MOT test number** 179746264262**Result** ✓ Passed**Notice** Nail in nearside front tyre**MOT #2** 2013-09-23 09:59**MOT test number** 965666563202**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2012-09-24 09:54
MOT test number	966338462281
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
13 July 2024

Tax status	Valid until 1 July
Days left	62
MOT expiry date	13 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-09-29
Last registration	2023-07-14
Complete history	See info



Registration #1	2009-09-29	26 mi
Registration #2	2012-09-24	15.132 mi
Registration #3	2013-09-23	19.795 mi
Registration #4	2014-09-23	25.928 mi
Registration #5	2015-09-24	31.512 mi
Registration #6	2015-09-24	31.512 mi
Registration #7	2016-09-28	36.339 mi
Registration #8	2017-09-25	40.036 mi
Registration #9	2018-10-01	47.298 mi
Registration #10	2019-09-29	55.277 mi
Registration #11	2019-09-29	55.277 mi
Registration #12	2019-09-29	55.277 mi
Registration #13	2019-09-29	55.277 mi
Registration #14	2019-09-29	55.277 mi
Registration #15	2019-09-29	55.277 mi
Registration #16	2019-09-29	55.277 mi
Registration #17	2019-09-29	55.277 mi
Registration #18	2019-09-29	55.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1922 mm
Height	1481 mm
Length	3958 mm
Wheel base	2489 mm
Kerb weight	966 kg
Max. allowed weight	1530 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	9J10615