



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	CELICA VVTI RED
Colour	Silver
Year of manufacture	-
Top speed	127 mph
0 - 60 mph	8.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	172 Nm at 4.200 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	45.6 mpg
Consumption combined	36.7 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-06
Pictures	1
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

**MOT #19** 2022-03-19 14:07**MOT test number** 117065089065**Result** ✗ Failed

**Fail** Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))

**MOT #18** 2021-02-22 12:14**MOT test number** 760080269488**Result** ✓ Passed

**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Advice** Rear Vehicle structure is corroded but structural rigidity is not significantly reduced inner sills (6.1.1 (c) (i))

**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #17** 2020-03-03 10:16**MOT test number** 203495733235**Result** ✓ Passed

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #16** 2020-03-03 10:16**MOT test number** 680156590974**Result** ✗ Failed

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Pass with rectification** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #15** 2019-03-05 14:37**MOT test number** 932940570229**Result** ✓ Passed

**Advice** Suspension component mounting prescribed area is corroded but not considered excessive n/s and o/s rear chassis legs and inner sills (5.3.6 (a) (i))

**MOT #14** 2019-03-05 10:57**MOT test number** 877873942924**Result** ✗ Failed

**Advice** Brake pipe corroded, covered in grease or other material to n/s and o/s rear hoses (1.1.11 (c))

**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**Fail** Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))

**Advice** Suspension component mounting prescribed area is corroded but not considered excessive n/s and o/s rear chassis legs and inner sills (5.3.6 (a) (i))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13** 2018-03-05 13:47**MOT test number** 315063019983**Result** ✓ Passed**MOT #12** 2018-03-05 13:47**MOT test number** 956364298149**Result** ✗ Failed

**Pass with rectification** Nearside Stop lamp not working (1.2.1b)

**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)

**Pass with rectification** Registration plate lamp not working (1.1.C.1d)

**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)

**MOT #11** 2017-02-27 11:06**MOT test number** 559317551238**Result** ✓ Passed

- Advice** Engine management light on
- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)

**MOT #10** 2016-02-23 11:41**MOT test number** 528572253207**Result** ✓ Passed

- Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)

**MOT #9** 2015-03-11 12:40**MOT test number** 146420175468**Result** ✓ Passed**MOT #8** 2014-03-05 12:48**MOT test number** 949634164079**Result** ✓ Passed**MOT #7** 2013-02-18 10:07**MOT test number** 586279743029**Result** ✓ Passed**MOT #6** 2012-03-12 10:53**MOT test number** 945472072017**Result** ✓ Passed



MOT #5	2011-02-28 12:22
MOT test number	136469151424
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
MOT #4	2010-02-16 13:13
MOT test number	424127040000
Result	✓ Passed
MOT #3	2009-02-19 11:36
MOT test number	790340659063
Result	✓ Passed
MOT #2	2008-02-18 16:08
MOT test number	444519048056
Result	✓ Passed
MOT #1	2007-02-19 11:47
MOT test number	190240257446
Result	✓ Passed




Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2004-03-01
Last registration	2022-03-19
Complete history	<a href="#">See info</a>



Registration #1	2004-03-01	20 mi
Registration #2	2007-02-19	26.105 mi
Registration #3	2008-02-18	26.329 mi
Registration #4	2009-02-19	33.256 mi
Registration #5	2010-02-16	39.772 mi
Registration #6	2011-02-28	46.116 mi
Registration #7	2012-03-12	52.338 mi
Registration #8	2013-02-18	59.481 mi
Registration #9	2014-03-05	67.063 mi
Registration #10	2015-03-11	74.191 mi
Registration #11	2016-02-23	80.773 mi
Registration #12	2016-03-20	81.377 mi
Registration #13	2016-04-19	81.977 mi
Registration #14	2016-05-18	82.577 mi
Registration #15	2016-06-17	83.177 mi
Registration #16	2016-07-16	83.777 mi
Registration #17	2016-08-15	84.377 mi
Registration #18	2016-09-14	84.977 mi
Registration #19	2016-10-13	85.577 mi
Registration #20	2016-11-12	86.177 mi
Registration #21	2016-12-11	86.777 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1735 mm
Height	1315 mm
Length	4350 mm
Wheel base	2600 mm
Kerb weight	1145 kg
Max. allowed weight	1565 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Engine number	1ZZ1939118