



report date: 2024-03-29

General information

Make	VOLVO
Model	V70 D5 SE
Colour	Grey
Year of manufacture	2010
Top speed	140 mph
0 - 60 mph	7.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	205 BHP
Max. torque	420 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	32.5 mpg
Consumption extra urban	55.4 mpg
Consumption combined	44.1 mpg
CO2 emission	144 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-09-15
Pictures	65
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-09-17
MOT pass rate	92 %
MOT passed	11
Failed MOT tests	1
Total advice items	18
Total items failed	1

MOT #12	2023-09-18 07:56
MOT test number	463396036222
Result	✓ Passed
Next expiry date	2024-09-17
Minor	Offside Side repeater insecure (4.4.1 (c) (i))
Advice	Tyre worn close to legal limit/worn on edge offside and nearside rear (5.2.3 (e))
Minor	Offside Obligatory mirror slightly loose (3.3 (b) (i))
Advice	Tyre worn close to legal limit/worn on edge offside and nearside front (5.2.3 (e))

MOT #11	2022-09-13 07:59
MOT test number	442183842534
Result	✓ Passed
Minor	Offside Side repeater insecure (4.4.1 (c) (i))
Minor	Offside Obligatory mirror slightly loose (3.3 (b) (i))

MOT #10	2021-09-18 10:51
MOT test number	632614965701
Result	✓ Passed

**MOT #9** 2020-10-10 10:39**MOT test number** 379891756999**Result** ✓ Passed**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2019-10-14 15:00**MOT test number** 682030251108**Result** ✓ Passed**MOT #7** 2018-10-12 13:53**MOT test number** 760374347586**Result** ✓ Passed**Advice** Suspension component pin or bush slightly worn Both rear trailing arm bushes starting to debond (5.3.4 (a) (i))**MOT #6** 2017-10-17 11:27**MOT test number** 587641252239**Result** ✓ Passed**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #5** 2017-10-17 11:27**MOT test number** 343519421073**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #4** 2016-10-24 14:03**MOT test number** 616233587256**Result** ✓ Passed**MOT #3** 2015-10-30 09:52**MOT test number** 337567324109**Result** ✓ Passed**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2014-10-13 12:37**MOT test number** 896956084205**Result** ✓ Passed**MOT #1** 2013-10-21 12:32**MOT test number** 597404193228**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
17 September 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	155
<b>MOT expiry date</b>	17 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2010-10-30
Last registration	2023-09-18
Complete history	<a href="#">See info</a>



Registration #1	2010-10-30	20 mi
Registration #2	2013-10-21	23.517 mi
Registration #3	2014-10-13	32.195 mi
Registration #4	2015-10-30	41.043 mi
Registration #5	2016-10-24	47.974 mi
Registration #6	2017-10-17	57.772 mi
Registration #7	2017-10-17	57.772 mi
Registration #8	2018-10-17	57.772 mi
Registration #9	2018-10-17	57.772 mi
Registration #10	2018-10-17	57.772 mi
Registration #11	2018-10-17	57.772 mi
Registration #12	2018-10-17	57.772 mi
Registration #13	2018-10-17	57.772 mi
Registration #14	2018-10-17	57.772 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	84%
Pedestrian	43%
Safety systems	71%
Overall rating	77%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1861 mm
Height	1547 mm
Length	4823 mm
Wheel base	2816 mm
Kerb weight	1755 kg
Max. allowed weight	2300 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	834573