






### General information

Make	VAUXHALL
Model	VIVA SL
Colour	Red
Year of manufacture	2017
Top speed	106 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed Semi-Automatic

## Engine & fuel consumption

Power	74 BHP
Max. torque	95 Nm at 4.500 rpm
Engine capacity	999 сс
Cylinders	3
Fuel type	Petrol
Consumption city	50.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	103 g/km
CO2 label	В







Factory 1			
E <b>ntry 1</b> Date	2021-02-05		
Pictures	6		
	-		
Listing price	View report		
torregularisates socials	MORESONATION ARE L2.005,400 DIAMONG OF ADDRESSON MATEM, INFORMATE 1225,30 MATEM, INFORMATE 1233,30	Video viewing with one of our tears.         States wideo viewing	Contract of the experimentation         Contract of the experimentation available         Contract of the experimentation available         Contract of the experiment of the experimentation         Contract of the experimentation

source: autoonline.co.uk



# MOT history

MOT expiry date	2025-03-14
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	12
Total items failed	3

MOT #6		2024-03-11 15:01
MOT test	number	224888418746
Result		✓ Passed
Next exp	iry date	2025-03-14
Minor (i))	Offside Registration plate lamp inoperative in the case of multiple lamps or lig	ght sources (4.7.1 (b)
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Engine oil level low	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #5	2024-03-11 11:18
MOT test number	317889284844
Result	× Failed
Advice Engine oil level low	
<b>Fail</b> Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor Offside Registration plate lamp inoperative in the case of multiple lamps or l (i))	light sources (4.7.1 (b)
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	





MOT #4	2023-03-13 10:17
MOT test number	972123999319
Result	✓ Passed
МОТ #3	2022-03-15 13:52
MOT test number	490563376870
Result	✓ Passed
MOT #2	2020 12 21 12.26

MOT #2	2020-12-21 13:36
MOT test number	579057170850
Result	✓ Passed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #1		2020-12-21 13:36
MOT test number		433711712425
Result		🗙 Failed
Pass with rectification	Nearside Headlamp aim too low (4.1.2 (a))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Pass with rectification	Offside Headlamp aim too low (4.1.2 (a))	



Tax & MOT check

✓	✓
Taxed	MOT
Tax due:	Expires:
1 April 2025	14 March 2025
Tax status	Valid until 1 April
Days left	337
MOT expiry date	14 March 2025
Full MOT history	See MOT history

# Tax calculation

Vehicle class	48
Band	F
First licence fee (12 months)	£ 185,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-





#### Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FET A
Category	L AMP
Туре	
Damage 2	AMPLE
Date	4
Category	AMPL
Туре	

#### Extra VAUXHALL salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200





### Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

***********	
********	
	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





#### Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-09-20
Last registration	2024-03-11
Complete history	See info



Registration #1	2017-09-20	28 mi
Registration #2	2020-12-21	19.528 mi
Registration #3	2020-12-21	19.528 mi
Registration #4		11.777 esi
Registration #5		11.777 mi
Registration #6		11.777 esi
Registration #7		11.777 mi
Registration #8		11.777 esi





# Safety ratings

NCAP rating	****	
Adult	52%	EURO
Children	91%	
Pedestrian	53%	
Safety systems	57%	La Contraction and Annual
Overall rating	61%	
Video	see crash video	

Dimensions & weight	
Width	1876 mm
Height	1485 mm
Length	3675 mm
Wheel base	2385 mm
Kerb weight	864 kg
Max. allowed weight	1353 kg
Additional information	
Additional information Fuel tank capacity	32
	32 l Multi-Point Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Multi-Point Injection
Fuel tank capacity Fuel delivery Number of doors	Multi-Point Injection 5