



report date: 2024-03-28

General information

Make	MAZDA
Model	5 D TS
Colour	Black
Year of manufacture	2008
Top speed	110 mph
0 - 60 mph	13.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	310 Nm at 3.500 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	52.3 mpg
Consumption combined	46.3 mpg
CO2 emission	159 g/km
CO2 label	G






Internet history

Entry 1

Date	2022-02-08
Pictures	9
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2023-03-09
-----------------	------------

MOT pass rate	71 %
---------------	------

MOT passed	12
------------	----

Failed MOT tests	5
------------------	---

Total advice items	43
--------------------	----

Total items failed	2
--------------------	---

MOT #17	2022-03-10 15:47
---------	------------------

MOT test number	319598980237
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2023-03-09
------------------	------------

Advice N/s/f shocker damp-oil leak-under vehicle corroded-coil springs corroded-o/s/r tyre outer wall deteriorated-rear sub frame corroded-inner sills corroded- brake pipes corroded-

Advice Welding covered by substance, unable to check properly

MOT #16	2022-03-09 12:56
---------	------------------

MOT test number	207738245798
-----------------	--------------

Result	✗ Failed
--------	----------

MAJOR Anti-roll bar linkage damaged and seriously weakened o/s/r link (5.3.3 (b) (i))

MAJOR Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt n/s/f (6.1.7 (g) (ii))

MAJOR Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced n/s/r inner sill holed x1 (6.1.1 (c) (i))

Advice N/s/f shocker damp-oil leak-under vehicle corroded-coil springs corroded-o/s/r tyre outer wall deteriorated-rear sub frame corroded-inner sills corroded- brake pipes corroded-

MAJOR Anti-roll bar linkage damaged and seriously weakened n/s/r link (5.3.3 (b) (i))

MAJOR Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced o/s/r inner sill x2 holed- (6.1.1 (c) (i))

**MOT #15** 2021-06-22 16:26**MOT test number** 937313858384**Result** ✓ Passed**Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #14** 2020-09-15 15:13**MOT test number** 869659182284**Result** ✓ Passed**Advice** Nearside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Offside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**MOT #13** 2020-09-09 11:53**MOT test number** 784623970718**Result** ✗ Failed**DANGEROUS** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Nearside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Offside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**MAJOR** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #12** 2019-09-13 13:58**MOT test number** 373980478207**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**MOT #11** 2019-09-10 13:53**MOT test number** 956679806536**Result** ✗ Failed**Advice** Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**MAJOR** Nearside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))**MAJOR** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**MAJOR** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**MAJOR** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MOT #10** 2018-09-08 09:31**MOT test number** 956394918004**Result** ✓ Passed**MOT #9** 2017-09-04 13:42**MOT test number** 469629740612**Result** ✓ Passed**Advice** Front Suspension arm rubber bush deteriorated but not resulting in excessive movement 2 (2.4.G.2)**MOT #8** 2016-11-11 11:18**MOT test number** 915223502173**Result** ✓ Passed



MOT #7	2016-11-11 11:18
---------------	------------------

MOT test number	123716377065
------------------------	--------------

Result	✗ Failed
---------------	----------

Pass with rectification	Nearside Registration plate lamp not working (1.1.C.1d)
--------------------------------	---

MOT #6	2015-11-25 12:26
---------------	------------------

MOT test number	591705127713
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #5	2014-11-24 12:26
---------------	------------------

MOT test number	369928424304
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2014-11-24 12:26
---------------	------------------

MOT test number	539928024301
------------------------	--------------

Result	✗ Failed
---------------	----------

Pass with rectification	Nearside Rear position lamp(s) not working (1.1.A.3b)
--------------------------------	---

**MOT #3**

2013-12-02 13:55

MOT test number

898786233381

Result

✓ Passed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Notice** Child seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Vehicle presented as 5 seater
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Under-trays fitted obscuring some underside components
- Notice** O/s/f tyre worn on outer edges
- Notice** Exhaust heat shield insecure/rear

MOT #2

2012-11-27 14:41

MOT test number

286402432320

Result

✓ Passed

- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)
- Notice** Under-trays fitted obscuring some underside components
- Notice** Chip on front windscreen outside zone(a)
- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)

MOT #1

2011-11-17 13:03

MOT test number

499161621397

Result

✓ Passed

- Notice** Nearside rear brake disc corroded



Tax & MOT check

X

Untaxed

Tax expired:
1 August 2022

X

MOT

Expired:
9 March 2023

Tax status	Expired at 1 August 2022
Days left	636 days too late
MOT expiry date	9 March 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-




Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled. If not, and you buy this MAZDA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-12-03
Last registration	2022-03-10
Complete history	See info



Registration #1	2008-12-03	20 mi
Registration #2	2011-11-17	57.494 mi
Registration #3	2012-11-27	64.605 mi
Registration #4	2013-12-02	71.259 mi
Registration #5	2014-11-24	75.409 mi
Registration #6	2015-11-25	79.036 mi
Registration #7	2016-11-11	83.555 mi
Registration #8	2016-11-11	83.555 mi
Registration #9	2017-09-04	92.093 mi
Registration #10	2018-09-04	92.093 mi
Registration #11	2019-09-04	92.093 mi
Registration #12	2020-09-04	92.093 mi
Registration #13	2021-09-04	92.093 mi
Registration #14	2022-03-10	92.093 mi
Registration #15	2022-03-10	92.093 mi
Registration #16	2022-03-10	92.093 mi
Registration #17	2022-03-10	92.093 mi
Registration #18	2022-03-10	92.093 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1755 mm
Height	1615 mm
Length	4505 mm
Wheel base	2750 mm
Kerb weight	1535 kg
Max. allowed weight	2245 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	RF 10228611