



report date: 2024-03-29

General information

Make	FIAT
Model	PANDA ACTIVE
Colour	Red
Year of manufacture	2007
Top speed	93 mph
0 - 60 mph	15.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	54 BHP
Max. torque	87 Nm at 2.750 rpm
Engine capacity	1.108 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	58.9 mpg
Consumption combined	49.6 mpg
CO2 emission	135 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-06-05
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-06-06
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	32
Total items failed	3

MOT #20	2023-06-07 14:29
MOT test number	498046844942
Result	✓ Passed
Next expiry date	2024-06-06

MOT #19	2023-06-06 09:12
MOT test number	194021512038
Result	✗ Failed
MAJOR Nearside Rear Suspension arm attachment bracket/mounting corroded and seriously weakened (5.3.3 (b) (i))	
MAJOR Parking brake efficiency below requirements (1.4.2 (a) (i))	
MAJOR Offside Rear Suspension arm attachment bracket/mounting corroded and seriously weakened (5.3.3 (b) (i))	

MOT #18	2022-05-31 09:30
MOT test number	465632211378
Result	✓ Passed
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Front Upper suspension mounts have slight play	
Advice Rear exhaust silencer corroded	
Advice Offside Front Upper suspension mounts have slight play	

**MOT #17** 2021-06-05 10:19**MOT test number** 669380950569**Result** ✓ Passed**MOT #16** 2020-08-20 10:52**MOT test number** 429645853754**Result** ✓ Passed**MOT #15** 2020-08-20 10:52**MOT test number** 730946590885**Result** ✗ Failed**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #14** 2019-08-26 12:37**MOT test number** 762433936580**Result** ✓ Passed

- Advice** Nearside Front tyre on 3mm
- Advice** Front Brake pad(s) wearing thin both (1.1.13 (a) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Exhaust system corroded
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Front registration plate cracked

**MOT #13**

2019-08-26 12:37

MOT test number

622685106794

Result**✗ Failed****Pass with rectification**

Nearside Rear Bumper damaged and likely to cause injury when grazed or contacted (6.1.4 (a) (i))

Advice

Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice

Front registration plate cracked

Advice

Nearside Front tyre on 3mm

Advice

Front Brake pad(s) wearing thin both (1.1.13 (a) (ii))

Advice

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice

Exhaust system corroded

MOT #12

2018-08-20 13:37

MOT test number

267087533399

Result**✓ Passed****MOT #11**

2018-08-20 12:49

MOT test number

519319401294

Result**✗ Failed****MAJOR**

Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

MOT #10

2017-08-18 08:32

MOT test number

440759082294

Result**✓ Passed****Advice**

Rear Exhaust box outer skin peeling + corroded

Advice

Nearside Front Outer Wall slightly worn

**MOT #9** 2016-08-22 08:35**MOT test number** 687843153692**Result** ✓ Passed**MOT #8** 2015-08-24 12:37**MOT test number** 907636935237**Result** ✓ Passed**Notice** Items removed from driver's view prior to test**MOT #7** 2014-08-18 16:38**MOT test number** 696240234286**Result** ✓ Passed**Notice** Exhaust back box heavily corroded**Notice** Oil overfull**Notice** Items removed from driver's view prior to test**MOT #6** 2013-08-14 14:21**MOT test number** 828026223267**Result** ✓ Passed**Notice** Back box corroded**MOT #5** 2013-08-14 11:53**MOT test number** 439616623202**Result** ✗ Failed**Notice** Back box corroded**Fail** Offside Front Shock absorber has a serious fluid leak (2.7.3)



MOT #4	2012-08-15 17:01
MOT test number	126438222255
Result	✓ Passed

MOT #3	2012-03-27 12:54
MOT test number	186917182485
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2	2011-03-31 13:38
MOT test number	528180791052
Result	✓ Passed

MOT #1	2010-03-25 18:20
MOT test number	553874180092
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
6 June 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	6 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-03-30
Last registration	2023-06-07
Complete history	See info



Registration #1	2007-03-30	13 mi
Registration #2	2010-03-25	17.574 mi
Registration #3	2011-03-31	24.484 mi
Registration #4	2012-03-27	32.575 mi
Registration #5	2012-08-15	34.621 mi
Registration #6	2013-08-14	41.115 mi
Registration #7	2013-08-14	4.111 mi
Registration #8	2014-08-18	43.680 mi
Registration #9	2015-08-24	44.427 mi
Registration #10	2016-08-22	45.955 mi
Registration #11	2017-08-18	47.089 mi
Registration #12	2018-06-20	51.377 mi
Registration #13	2019-06-20	55.377 mi
Registration #14	2020-06-20	59.377 mi
Registration #15	2021-06-20	63.377 mi
Registration #16	2022-06-20	67.377 mi
Registration #17	2023-06-20	71.377 mi
Registration #18	2024-06-20	75.377 mi
Registration #19	2025-06-20	79.377 mi
Registration #20	2026-06-20	83.377 mi
Registration #21	2027-06-20	87.377 mi
Registration #22	2028-06-20	91.377 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1578 mm
Height	1540 mm
Length	3538 mm
Wheel base	2299 mm
Kerb weight	840 kg
Max. allowed weight	1255 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4

Number of axles	2
Engine number	3946090